Southern Cross Hospitals Ltd Endoscopy Consultants' PRESSS Building

Gary Haverland

BE (Civil)(Hons) Director / Senior Engineer Structex, Christchurch









ENT Building

- ENT Building designed in 2007
- 3-storey building, carpark on ground
- Building footprint 19m x 28m
- Lateral loads resisted by limited ductile frame in transverse direction, nominally ductile shear walls in longitudinal direction

ENT Building







Precast frames ENT Construction

structex Endoscopy Consultants' Building

- Endoscopy Consultants' building similar in form & plan area to ENT building
- \$7.2M budget
- 4-storey building including half depth basement
- Building footprint 19.3m x 30.2m
- Gross floor area 2940m²
- Budget cost \$2,450/m²
- Designed as Importance Level 3 structure
- Soft site to 9m requiring piles

Typical cross section of central frame





Level 1 Plan - Carpark

- Frames in transverse direction providing gravity support for floors & resisting lateral loads
- Column layout to suit carparks & span of flooring
- Shear walls resist loads in longitudinal direction & located each side of building
- Used wall adjacent to stair well as shear wall on south side
- Installed wall on north side to balance longitudinal lateral resistance





Proposed PRESSS structure with the following advantages:

- Full length precast beams could be used eliminating insitu beam joints
- No plastic hinges resulting in very little structural damage
- Building structure is self centering resulting in very little residual lean following an earthquake
- Building accelerations are lower than a RC frame or shear wall building resulting in less risk of damage to contents





- More rapid construction time as less insitu concrete on site
- Construction uses conventional building components such as precast beams, walls, drossbach ducts & starters
- Post-tensioning could be carried out by a number of contractors
- Lower foundation actions resulting in pile savings
- Screw piles required to minimise noise & avoid vibration
- Reduced wall reinforcing, tendon replacement





- Positive response from client, conditional upon demonstrating price savings
- Review with Fletcher Construction and complete construction and costing analysis resulting in \$40,000 of structural savings including 45% reduction in some columns and two week time saving







- Pricing analysis confirmed savings were achieved
- Beam depth reduced from 700mm to 600mm allowing services to be accommodated without raising the building height
- Displacement based design procedures used to determine base shear
- Building drift 1.6% for walls, 1.8% for frames
- Code allows up to 2.5% drift


- To keep construction components as conventional as possible
- To avoid structural components that may be perceived as adding cost
- To make all precast components a manageable size to allow transport and cranage
- To keep components simple and easy to construct

General construction order:


- Sheet piling and excavation
- Screw piles
- Foundation beams
- Ground floor columns, install & grout
- Install beams & hollowcore floor with propping
- Install shear walls
- Cast topping slab
- Thread cable & tension beams & walls
- Complete insitu end beams, gutter etc









Install columns




Install beams




Place floor and cast topping




Install tendon




Install columns




Install beams




Place floor & cast topping




Install tendon




Install columns




Install beams




Place floor & cast topping




Install tendon




Install columns





note ; when column Is on either grId A or D the 3-D32s run over the top of the column and have varying end details (either PC19) or PC20) or welded flat), refer to beam elevations

column joint (insitu beams not shown)





(section)

ENG.HAV.0001.31


Components & Detailing

Precast beams, anchors & seating





Components & Detailing



Precast columns & anchors

column C29 similar column = C35

Precast columns & anchors




Precast columns & anchors




Precast columns & anchors












Shear Walls





HR10 links, galv at 200, each side of Pl4 ducts for height of duct $_$

Components & Detailing










Shear Wall Detailing precast panel with Pi15 insert (including bolts) P[15 Insert (including bolts) cast in 20 panel dimension on elevation 40 19 目 旧 -日 ıН 20 \$ -日 ١H 800 20 rad 40 Ъ 25 panel reinforcing -Pi15 insert 3 (stirrups not shown) (including bolts) cast in (plan) (elevation) 200 x 20 flat (G300) galv, bent as shown with 40mm panel edges beyond inside radius, with 4-22 dia holes for 4-M20 bolts at (40 thick) centres to match Pi15 and central across 200 dimension, bend after galvanising Pi15 insert PC21 (section)




Structex Components & Detailing





structex Components & Detailing



structex



structex



structex



structex





structex



structex Example of Damage to Plastic Hinge Beam





structex <u>Post Earthquake Photos</u>







structex Post Earthquake Photos









structex Post Earthquake Photos



Structex How did the building perform...

- Building has experienced over 7500 earthquakes and aftershocks.
- 22 February 2011 earthquake exceeded the loadings that buildings are typically designed to.
- Seismic resisting system of the structure (PRESSS frames & walls) performed extremely well.
- Some cosmetic damage to non-structural components of the building.
- Some damage to services requiring repair.
- Armouring of joints at ends of beams & walls necessary and performed well with some spalling occurring.