

# CTV Building Collapse Technical Investigation



# Outline of Presentation


- Our Task
- Building features
- Investigation approach
- How did the building collapse?
- Why did the building collapse?



**CTV Building in 2004 (viewed from southeast)**

# Building Features

Rectangular columns on Line A only



Infill Masonry Wall on three levels

North Core

Drag Bars Level 4, 5 and 6

Column C18

Foundations

South Wall

Cashel St on South face



Edge beams and circular columns


Madras St on East face

**Birds-eye view from east without slabs**

for

Canterbury Earthquakes Royal Commission


# Foundation Plan



5

# Floor Plan Level 2 to Level 6


BUI.MAD249.0509.6



6


# North Core Wall with Column attached

BUI.MAD249.0509.7



# South Wall Elevation


BUI.MAD249.0509.8






# Beam and Floor Sections

① (F similar)




②




# Column Elevation & Section

BUI.MAD249.0509.10




Vertical bars lap here



for

Canterbury Earthquakes Royal Commission


# Beam-Column Joints Internal - Line 2



# Beam-Column Joints East Side – Line F

1

2



# Masonry Infill West Side

1


2

BUI.MAD249.0509.13

Three masonry panels in each bay between columns




Elevation (1 of 3 bays)



Section

# Precast Spandrels



Spandrel end walls adjacent to columns

4  
TYPICAL SPANDREL FIXING




# Investigation Approach

- Collapsed Condition
- Witness Interviews
- Site Examination
- Materials Testing
- Structural Analysis
- Compliance Checks
- Collapse Scenario Evaluation

# Scientific Method

BUI.MAD249.0509.16





# CTV Building after the Collapse

- View from west
  - Fire just started near north end
  - Level 4 to 6 cladding pushed north
    - Little debris otherwise on this side
  - Diagonal cracking to masonry infill
  - No liquefaction

North Core

Level 4, 5 and 6 Cladding

Level 2 masonry with diagonal cracking

No liquefaction



View from Les Mills from west Immediately after the collapse

# CTV Building after the Collapse

- View from South
  - Prior to fire starting
  - Level 5 slab hanging from North Core
  - Level 6 slab supported by drag bars
  - No debris south of the building
    - Cars parked in front of South Wall undamaged

Cars undamaged  
on South face



View from Cashel Street from south Immediately after the collapse

# CTV Building after the Collapse

- View from southeast
  - Smoke from fire in background
  - No liquefaction
  - Slight eastward throw
    - Cars in Madras Street crushed by edges beams and Spandrel panels
  - Columns fractured



View from southeast Immediately after the collapse

# CTV Building after the Collapse

- View from East Lines 2 to 4
  - Smoke from fire in background
  - No liquefaction
  - Cars in Madras street crushed
  - Columns fractured



View from Blackwells from east Line 2 to 4 shortly after the collapse at 1:21 pm



View from east at Line 4 North Core immediately after the collapse at 1:00 pm

# Witness Interviews

- 18 Eye-witnesses Interviewed
  - 6 were in the building during the collapse
    - Levels 1, 4 and 6
  - Views of the collapse from East, South and West
    - 3D perspectives
    - Fly-through video



# Witness Observations

- Witness 14: Gutteridge
  - Twisting, bursting, columns breaking
- Witness 8 and 15: Hawker and Spencer
  - Upper portion came down as a unit
- Witness 6: May
  - Top leaned to east then collapsed straight down
- Witness at Level 4 Lifts: Godkin and Horsley
  - Floor started collapsing and undulating near South Wall before sharp west-east lurch



# Site Examination

- Salvaged Structural components
- North Core examination
- Levels Survey
- Foundations excavation and examination
- Column extraction and testing at Burwood

# Salvaged Structural Components



- South Wall Level 5 to 6
  - Soft concrete at door head
  - Smooth construction joints






# Salvaged Structural Components

- Column Hinging
  - Base
  - Mid-height
    - Vertical reinforcing steel termination zone
    - Spandrel Panel contact?
  - Head



# Salvaged Structural Components




- Possible East and South face column damage sequence

# South Wall Condition

- South Wall
  - Heavy compression spalling at east end
  - Fan like flexural cracking
    - Cantilever behaviour
    - Masonry infill of door




# North Core Condition




- Hairline cracking to North Core
- Fire effects on inner faces

# North Core Examination



- Drag Bars at Levels 4 to 6
- Slab broken away at end of saddle bars
  - 1200 mm south of beam
- No or little slab reinforcing connection to some walls

# North Core Examination



- Drag Bars connection to some walls

# North Core Examination



L6 Drag Bar still attached to and holding up slab

L5 Drag Bars

L5 Line 4 precast concrete beam after L5 slab has rotated off

L4 slab failure along ends of H12 saddle bars 1200mm off Line 4 similar to L5 and L6

Failure surface runs diagonally from inside face of edge beam to the ends of the slab saddle bars

Column Line 4 D/E L4-5 and L5-6 with beam-column joint pullout at L5

# North Core Examination



L5 Drag Bar

L5 slab from in front of lifts between  
Walls D/E and D

L5 slab failure surface 1200 mm out  
from Line 4 at end of H12 saddle  
bars




# North Core Examination

- Slabs leaning against North Core
- Indicates loss of support along Line 3 prior to breaking off North Core



# North Core Examination

- Drag Bars slab anchors at Levels 4, 5 and 6 upright behind wall tips
  - Slab appeared to have rotated off after collapse further south in building
- Some Drag Bars had been cut off during recovery operations



Level 4 Drag Bars


# North Core Examination



- Beam bottom bars not cast into North Core L3 to L6

# Levels Survey

- No sign of settlement of the ground floor
- North Core had a northwards displacement
  - More at the eastern end



# Foundations Examination

- No liquefaction was found adjacent to the foundations.
- No signs of uplift
- No signs of damage to the foundation beams



# Materials Testing

- Concrete cores from walls, slabs and columns
- Reinforcing steel and decking
- Drag Bar threaded anchors
  - Results used to assess Drag Bar capacity



# Concrete Quality

- Wall Concrete
  - Localised door head issue
- Slab Concrete
- Beam Concrete
- Column Concrete
  - Highly variable



# Column Extraction at Burwood

The CTV Building debris field at the Burwood Eco Landfill from which columns were extracted



CTV Building columns extracted for examination and testing






# Column Concrete

- Cores extracted and tested
  - NZS3112:1986
- Rebound Hammer testing
  - Calibrated to core tests ASTM C805
- Comparison to concrete production statistical limits
  - NZS 3104:1983
- Density
  - Low in some cases

# Column Concrete



- Concrete in a significant proportion of the columns may have had strengths less than the minimum specified
- It was decided use minimum specified + 2.5 MPa for analyses and check sensitivity

# Reinforcing Steel




- South Wall
  - Some yielding at base only




# Structural Analysis

- ERSA
  - Elastic Response Spectrum Analysis
- NTHA
  - Nonlinear Time History Analysis
- NPA
  - Nonlinear Push-over Analysis
- Column drift capacity
- Drift Compatibility
  - ERSA drifts compared to drift capacities
  - Could the columns cope with the drifts of the South Wall and North Core?

# Non-Linear Analysis model




# Recorded Peak Ground Accelerations – 4 September 2010



(Source: EQC-GNS Geonet)

# Recorded Peak Ground Accelerations – 22 February 2011




(Source: EQC-GNS Geonet)

# 3-D Animation: 22 February 2011

- Ground shakes, causing building to move
- Notice:
  - Lateral (sideways) movement of floors
  - Twisting of floors
  - Strain on columns






# Columns under strain


Lateral movement of floors causes columns to distort

Distortion causes bending and shear in columns

Heavily loaded columns can sustain less drift




# Column F2 Level 3 – 22 Feb 2011 – CBGS Record



Comparison of drift demand and capacity

# Column Actions Grid D2 Level 1 - 22 Feb 2011




# Comments on NTHA

- Earthquake records used without scaling
- Calibration to observed damage difficult
- Appears to over predict damage
  - Drag Bar failure predicted in September Earthquake
  - Drag Bar failure predicted very early in February Aftershock
    - Site evidence and L4 witness testimony indicates Drag Bars did not fail before collapse started elsewhere

# ERSA

- 3D elastic structural behaviour
  - Standard design spectra for compliance checks
  - CBD earthquake records spectra
    - September Earthquake response 2.0 x December Aftershock
    - February Aftershock 2.2 x September Earthquake
      - Tables 15 to 17

# Earthquake Records vs Design Spectra




- Earthquake Loadings Standard (NZS 4203:1984)
  - Ductile response
- Design spectra vs Earthquake spectra
  - Calibration issues

# Compliance Checks to Standards

- Compliance checks to Standards using ERSA
  - Walls “complied” with inter-storey drift limits
  - Columns non-compliant for seismic spiral reinforcing limits
  - Columns non-compliant for spiral reinforcing for shear under imposed drifts




# Column Drift Capacity



- At average tested concrete strength of 27.5 MPa (Fig 159)
  - Cracking at 0.10 to 0.35% drifts
- Level 2 to 4 columns North and East faces 1.15 to 1.45% drift capacity (Table 13 and 14)
  - Less than 1.51% safe drift performance expected by Standard

# Column Drift Capacity



Column failure limit  
 $ecu = 0.004$  at 1.20% drift


Steel yield at 0.80% drift

Concrete yield limit  
 $ec = 0.002$  at 0.60% drift

Column F/2 Level 2  
with 995 kN axial load

- At average tested concrete strength of 27.5 MPa
- Drift capacity reduces with increased axial load from vertical acceleration
  - Table 13 for C/1 and Table 14 for F/2 axial loads and drift limits

# Column Drift Capacity



Column failure limit  
 $ec=0.004$  at 1.05% drift  
before steel yields

Concrete yield limit  
 $ec=0.002$  at 0.48% drift



Column F/2 Level 2  
with 995 kN axial load

- At lower 5%ile tested concrete strength of 14.2 MPa
- Drift capacity reduces with reduced concrete strength

# NTHA Drag Bar Failure Estimates



Column F2 Level 3 Drifts - CBGS, 22 February Lyttelton Aftershock, no masonry

Column F2 Level 3 Drifts - CBGS, 4 September Darfield Earthquake, no masonry




Drag Bar failure estimated to occur when 1% drift along Line F

# Concrete Columns



- Same reinforcing in all main building columns
- Light spiral binding R6 @ 250 centres
  - Non-compliant
- Rectangular columns on Line A only

# Spandrel Panels



**Non-compliant : no seismic gaps specified between columns and Spandrel Panels**




# Spandrel Panels and Columns

Line F columns on east face

Column C18

North Core on north face




Concrete edge beams


Pre-cast concrete Spandrel panels between columns on edge beams

**CTV Building in May and October 1987 during construction (viewed from northeast)**


# Masonry Infill Wall on West Face



- Drawings showed
  - Grouted top row of masonry at each floor
  - 25 mm gaps on sides at columns
- Workers outside just before collapse found
  - Top rows partially grout filled
  - No gaps on sides at columns on outer face
  - No obvious damage from September eq.
- Staff inside found
  - Sealant and gaps on sides at columns




Workers preparing wall for cladding just prior to Eq (CTV News)



Section through wall from Drawings




# Adjacent Building




**CTV Building in January 1987 during construction  
(viewed from southeast)**

# Effect of Masonry Infill on West Wall

- Increased torsional eccentricity
- Drifts on East face similar to drifts on South face
- May have reduced demand on South Wall




# Drag Bars Added after Completion




Drag Bars Level  
4, 5 and 6


- Construction of building 1986-1987
- Design defect found in 1990
  - Building could separate from North Core in an Eq.
- Remedial work using Drag Bars designed in 1991
  - Steel angles epoxy bolted into walls and underside of slabs
  - No Drag Bars designed or installed at Level 2 or 3
  - Unable to sustain full design response of the structure
- No Building Consent application on Council files



# Summary of Vulnerabilities



# Collapse Scenarios




# Collapse Initiation Scenarios

- Collapse Initiation Scenarios Examined
  1. East or South face column Failure on (Line F or 1)
  2. Internal column failure on Line 2 or 3
  3. Internal column failure following floor slab diaphragm disconnection at North Core
    - No Drag Bars at these levels
  4. Column failure following floor slab disconnection at North Core at Levels 4, 5 or 6
- Scenario 1 preferred
  - (Refer p.103 to107)




# Likely Collapse Sequence



## • East face column failure initiation



# Likely Collapse Sequence




- Line 2 (east to west) column failure development





# Likely Collapse Sequence



- Line C to D (south to north) column failure development

# Why Did the CTV Building Collapse?

- Specific factors that contributed (or may have contributed) to the collapse include:
  - Severe earthquake aftershock
  - Column drift capacity substandard
  - Seismic gaps between columns and Spandrel Panels substandard
  - Some column concrete test strengths substandard
  - Unsymmetrical layout and large strength differential between South Wall and North Core
  - Seismic separation of masonry infill on west wall compromised
  - Substandard construction joints in South Wall

# Likely or Possible Contributors to the Collapse of the CTV Building

(From p.31 of the report)

- The stronger than design-level ground shaking.
- The low displacement-drift capacity of the columns due to:
  - The low amounts of spiral reinforcing in the columns which resulted in sudden failure once concrete strain limits were reached.
  - The large proportion of cover concrete, which would have substantially reduced the capacity of columns after crushing and spalling.
  - Significantly lower than expected concrete strength in some of the critical columns.
  - The effects of vertical earthquake accelerations, probably increasing the axial load demand on the columns and reducing their capacity to sustain drift.
- The lack of sufficient separation between the perimeter columns and the Spandrel Panels which may have reduced the capacity of the columns to sustain the lateral building displacements.
- The plan irregularity of the earthquake-resisting elements which further increased the inter-storey drifts on the east and south faces.
- Increased displacement demands due to diaphragm (slab) separation from the North Core.
- The plan and vertical irregularity produced by the influence of the masonry walls on the west face up to Level 4 which further amplified the torsional response and displacement demand.
- The limited robustness (tying together of the building) and redundancy (alternative load path) which meant that the collapse was rapid and extensive.

# Summary of Findings

BUI.MAD249.0509.76

- The earthquake aftershock was severe but the building appears to have collapsed at inter-storey drifts less than those expected by the Standards
- A number of collapse scenarios were considered. Collapse most likely initiated in substandard concrete columns along the east face of the building at Levels 3, 4 or 5.
- Columns designed in accordance with the standards would have been expected to be safe at drifts of 1.51%.
- The columns along the North and East faces of the CTV Building at Levels 2 to 4 were estimated to have drift capacities between 1.15 and 1.45%
- It appears that these East face columns may have failed at drifts of less than 1.0% prior to Drag Bar failure at the North Core

# Summary of Findings

BUI.MAD249.0509.77

- Specific factors that contributed (or may have contributed) to the columns failures include:
  - Columns did not have the amount of spiral confining and shear reinforcing steel required by the design standard.
  - There was no specific seismic gaps between the Spandrel Panels and the Columns
  - The South Wall may have begun to yield and lose stiffness at drifts as low as of 0.40% due to structural asymmetry
  - Vertical accelerations may have reduced column drift capacity
  - Smooth construction joints in the South Wall may have slipped and increased inter-storey drifts..
  - The concrete in some of the columns had test strengths less than the minimum strength specified.
  - Seismic separation gaps between the Infill masonry on the west face and the structure appear to have been compromised and may have changed the response of the structure.

# Summary of Findings

BUI.MAD249.0509.78

- Critical connections of the floors to some of the North Core walls were omitted in the original design and were only identified during a pre-purchase structural review 3 years after construction.
  - The Council did not have any record of the remedial works that were subsequently undertaken.
  - The Drag Bars installed could not sustain the ultimate design response of the structure.
- The building did not appear to have suffered significant structural damage in the 4 September 2011 Earthquake or 26 December 2010 Aftershock.
- The presentation is based on the findings of the CTV Building Collapse Investigation Report by Hyland Fatigue + Earthquake Engineering and StructureSmith Ltd and the Site Examination and Materials Testing Report by Hyland for the Department of Building and Housing
- The scope of the investigation was limited to identifying technical reasons for the collapse.