


Review of Expert Panel and Beca Report on PGC Building

William T. Holmes
Structural Engineer
San Francisco

Structural plan of Ground and Level 1



Pyne Gould Corporation Building

- All agree that building collapsed due to failure of the central tower at floor 1-2
 - Failure caused large movement of Level 2 downward and to the east (about 3 m)

Original position →

Known distance

3 m

2.60 m

60° ±

(2.16)⁴
slab
wt.

85
= 83.3




Pyne Gould Corporation Building

- All agree that building collapsed due to failure of the central tower at floor 1-2
 - Failure caused large movement of Level 2 downward and to the east (about 3 m)
 - Some girders supported by tower pulled away and collapsed (in unknown sequence)
 - Props placed behind perimeter columns as a retrofit were to provide supplemental support for the columns under excessive drifts (range of 5 cm), not meters. Exterior columns therefore collapsed. (in unknown sequence)
 - It is interesting to speculate if the “props” provided any assistance to the columns in Sept.

Level 1-2 had many seismic deficiencies

- Light central reinforcement.
 - Weak in global flexure (overturning)
 - Weak in EW shear (many openings, low R/F ratio, small trim bars. Piers in North Wall appear to be “shear critical”)



Can these walls provide sufficient coupling of east and west wall for the tower to act as a unit?


If so, would the south wall fail in shear prior to a flexural tower failure?

Our calculations indicate these various failure modes have reasonably close yield strengths.— Too close to call.

Additional Seismic deficiencies

- Discontinuity at north end of east wall


Structural plan of Ground and Level 1



Seismic deficiencies

- Discontinuity at north end of east wall
- No confined “column” elements under floor girders
- Poor connection of girders to tower at all levels
- Displacement critical gravity columns at perimeter (retrofit props not intended to support gravity loads under very large displacements.)

Structural plan of Ground and Level 1



Drift sensitive exterior columns—sensitive to torsion

Very poor connection to tower

Girder support on wall
No column element

Comment on use of Capacity Spectrum Method

- In Appendix A5, a pushover curve representing the structure and a spectral displacement vs spectral acceleration plot are superimposed to estimate maximum displacements. Normally in this method the a-d plot is reduced for increased damping due to damage.
- This would change the ratios used to estimate %NBS

Lessons for other “older” concrete buildings

- What conditions should be considered “Critical Structural Weaknesses”? Did it take a combination of the deficiencies to cause failure?
- Use of %N BS
 - Assessments of 33%-50% NBS but building was only slightly damaged in September, which, arguably, had shaking of the same order of magnitude as 100% NBS.
 - Brittle buildings of 100% NBS may be dangerous with only a small increase in shaking intensity.
 - However, it is unrealistic to evaluate buildings for very rare shaking (e.g. 2500 year return)
 - Brittle buildings examined for potential catastrophic failure modes at greater than 100% NBS?