




PLAN SECTION 2-2 - INTERIOR BEAM-COLUMN JOINT
(ALLOWING 10mm CONSTRUCTION TOLERANCE)




PLAN SECTION 3-3 - INTERIOR BEAM-COLUMN JOINT
(ALLOWING 10mm CONSTRUCTION TOLERANCE + CORNER SPALLING)




PLAN SECTION 1-1 - INTERIOR BEAM-COLUMN JOINT
(AS DESIGNED)




Typical Section thru PC Log Beam



LONGITUDINAL SECTION - TYPICAL INTERIOR BEAM-COLUMN JOINT



SECTION NEAR COLUMN CENTRELIN



Original Dwgs call for the gaps between beam ends to be sealed to prevent grout loss during insitu concrete (infill) pour. It's not clear to me what made up the fill in these nominal 25x20 'rebates' - PEF rod/ sealer/concrete.

Approximate location of last stirrup before column
Likely crack location

Compressive stresses at bottom of beam
under gravity load conditions.
(to balance top steel tension loads)

With smooth interface between precast (log) beam and 350ø column infill concrete longitudinal beam forces can't be transferred 'in line' across interface. So large RADIAL forces generated. Since there were no beam stirrups detailed to be located past start of curved end, there was nothing

to confine the concrete in the 'wings' or resist these radial/splitting forces. Vertical EQ acceleration loads would have increased the magnitude of all these forces and likely exceeded the tensile capacity of the unreinforced concrete 'wings' at the ends of the beams.

230 (as drawn)
(examples up to 300mm found in debris)

Outline of 400ø Supporting Column Below

400

175

200

175

Precast Log Beam

Precast Log Beam

Refer also to: File: CTV Bldg - Interior Beam-Column Joint - GF 20120217.dcd

File: CTV PC Beam Stress Concepts - GF 20120501.dcd

generate large RADIAL forces in at the interface.

Plan Section at Typical Interior Column
(thru Bottom of Precast Log Beams)

SK GF 20120501