

**CHRONOLOGY  
194 HEREFORD ST**

<b>DATE</b>	<b>EVENT</b>	<b>No.</b>	<b>DOCUMENT</b>	<b>DOCUMENT ID</b>
	<b>Application of the Council's earthquake prone policy to the building prior to the September earthquake</b>			
2005/2006	Structural strengthening carried out on building	1.	Copies of Council, building consents, reports and plans	BUI.HER194.0006.1
	<b>Events following the September 2010 earthquake</b>			
5/9/10	Level 1 Rapid Assessment. Noted damage as minor/none. Building green placarded.	2.	Rapid assessment form	BUI.HER194.0006.12
Post 22 February 2011	Photos taken showing collapse of unreinforced masonry parapets on north west and south elevations and north façade of first floor.	3.	Photos	BUI.HER194.0006.13
27/4/11	Earthquake damage assessment by O'Loughlin Taylor Spence, structural engineers.	4.	Report dated 27/4/11	BUI.HER194.0001.1