

Canterbury Earthquake Royal Commission

List One: Buildings Alan Reay Consultants involved with prior to September 4th 2010.

Job No.	Address	Company that engaged us	Contact Name	Contact Details
7490	iStay Hotel 187 Cashel Street Structural Review to Front Entry	Liverpool Developments / Paxton Pacific (in liquidation)	Craig Mudgway Leonard Ross	22a Upland Rd, Remuera, AKL 1050 10 Rata Rd, Cheltenham, AKL 0624
7962	IRD 224 Cashel St Structural Concept Report	Rapaki Property Group	Simon Henry	2 Buffon Street Waltham Christchurch
10527	Rebel Sports 521 Colombo Street Earthquake Review	Whitewater Holdings Ltd	Terrence Stirling (Built in 1997/98)	Lovells Flat RD 2 Milton
6932	Warren House 84 Gloucester Street Draft Structural Report	Gloucester Cambridge Holdings	John Hutton	PO Box 2121 Christchurch

Canterbury Earthquake Royal Commission

List Two: Buildings Alan Reay Consultants involved with post to September 4th 2010.

Job No.	Address	Company that engaged us	Contact Name	Contact Details
10279	IRD 224 Cashel Street Post EQ Damage Repair Report	Rapaki Property Group	Simon Henry	2 Buffon Street Waltham Christchurch
10527	Rebel Sports 521 Colombo Street Earthquake Review	Whitewater Holdings Ltd	Terrence Stirling (Built in 1997/98)	Lovells Flat RD 2 Milton
9485	646 Colombo Street Initial Post Seismic Occupancy Report – was referred to in a letter but haven't found it	McLarens Young International	Aaron Clegg	PO Box 623 Palmerston North 4440
10134	Warren House 84 Gloucester Street Post EQ Structural Assessment	Gloucester Cambridge Holdings	John Hutton	PO Box 2121 Christchurch
9859	The Link Centre 152 Hereford Street EQ Remedial Report	Rapaki Property Group	Brendon Stewart	2 Buffon Street Waltham Christchurch
9994	Medlab 137 Kilmore Street Post EQ Initial Occupancy Report	Nobby Holdings	David Shackleton	PO Box 29529 Christchurch

iStay Hotel, 187 Cashel St

Year Designed: 2004/2005
 Extent of Earthquake Damage: unknown
 Construction Type: Construction type: shear wall reinforced concrete
 Floor System: hollowcore
 Foundation System: bored piles and foundation beams
 Basement: Plant room only

IRD Building, 224 Cashel St

Year Designed: 2005
 Extent of Earthquake Damage: light
 Construction Type: Construction type: Precast Concrete Shear Walls
 Floor System: hollowcore
 Foundation System: bored piles and foundation beams
 Basement: no

Rebel Sports, 521 Colombo St

Year Designed: 1997
 Extent of Earthquake Damage: light
 Construction Type: Construction type: Tilt Slab, Steel portal frames
 Floor System: ground floor slab on grade
 Foundation System: shallow foundations
 Basement: no

646 Colombo St

Year Designed: 1900-1920 (estimated)
 Extent of Earthquake Damage: moderate to extensive
 Construction Type: Construction type: URM
 Floor System: timber joist
 Foundation System: unknown
 Basement: no

Warren House, 84 Gloucester St

Year Designed: 1962
 Extent of Earthquake Damage: moderate
 Construction Type: Construction type: RC Frame, Masonry shear walls
 Floor System: precast rib units
 Foundation System: shallow pads
 Basement: no

The Link Centre, 185 Hereford St

Year Designed: 1978
 Extent of Earthquake Damage: moderate to extensive
 Construction Type: Construction type: RC frame, insitu concrete and masonry block shear walls
 Floor System: insitu concrete floor
 Foundation System: bored concrete piles
 Basement: yes (partial)

Medlab, 137 Kilmore St

Year Designed: 1970's (estimated)
 Extent of Earthquake Damage: moderate to extensive
 Construction Type: Construction type: MRF reinforced concrete
 Floor System: insitu concrete floor
 Foundation System: part piled, part shallow founds
 Basement: yes