



Administration Division

11 August 2011

Tim Fahy  
Arrow International  
PO Box 14109  
Christchurch 8544

**Via Email**    [tim.fahy@arrowinternational.co.nz](mailto:tim.fahy@arrowinternational.co.nz)

Dear Tim

**Re Royal Commission Canterbury Earthquakes**


We refer to the request for information from the Commission.

Several years prior to the earthquakes, the Church sought reports from Richard Sullivan, Registered Engineer, on the structural strength and upgrading options for the Durham Street Church.

A decision on any strengthening work was held pending the Christchurch City Council's policy on upgrading earthquake prone buildings.

The Christchurch Mission, which holds the reports on behalf of the Church, is unable to produce the reports as they were held in the Durham Street Church which has been destroyed or in the Aldersgate building which has been damaged.

Yours faithfully



Greg Wright  
**Executive Officer**