



Alan Reay Consultants

21 April 2011

Dr Clark Hyland  
Director  
Hyland Fatigue and Earthquake Engineering  
PO Box 97282  
**Manukau**

Dear Clark

Further to our meeting of 5<sup>th</sup> April 2011 we confirm that you have requested information regarding the following:

1. Geotechnical records
2. Structural drawings
3. Any modifications during construction
4. Shop drawings
5. Specifications
6. Calculations

We now enclose copies of:

- a) Site Investigation Report
- b) Structural drawings
- c) Structural Specifications
- d) Calculations

I intend forwarding a copy of this material to Mr David Hardy.

We have not been able to locate any shop drawings, such as shell beams or any drawings of modifications during construction.

You noted at our meeting that you had a copy of the Council documents. We would appreciate it if you could provide a copy of the sections of these documents which have structural relevance.

Innovation  
by design

Alan Reay Consultants Ltd  
395 Madras Street  
PO Box 3911  
Christchurch  
New Zealand  
Tel 03 366 0434  
Fax 03 379 3981  
Email [eng@arcl.co.nz](mailto:eng@arcl.co.nz)  
Internet [www.arcl.co.nz](http://www.arcl.co.nz)



Alan Reay Consultants

With regards to the alterations that were subsequently made to the building we are continuing to search for such records and will write again when the search is complete.

Yours sincerely  
Alan Reay Consultants Ltd

Dr Alan Reay

enc.