

SMS Incident Report

6/08/2012 9:28:28 a.m.

Summary

CAD Number F0913883 Status Closed

Station Addington Station

Incident Started 22/02/2011 1:32:30 p.m. Incident Ended 2/03/2011 5:40:16 p.m.

Incident Type 1101: Structure fire with damage

Common Name CTV

Address 249 MADRAS STREET CHRISTCHURCH CENTRAL

Alarm Method 111 Telephone Alarm Level 1

PFA Number

Zone 342101 Risk Classification N

Map Grid E 1571112 Map Grid N 5179963

First Caller CHRISTCHURCH CENTRAL First Caller Contact 0273310481
POLICE STN

Incident Closed 2/03/2011 5:40:16 p.m.

Report Completed 20:47, Wed 09 Mar 2011 by Bruce Irvine

Responses

Callsign	Type	Station Alert	Enroute Time	Arrival Time	Departed
ADDI221	P1	13:32:31 22 Feb 2011	13:33:00 22 Feb 2011	13:33:22 22 Feb 2011	23:10:48 24 Feb 2011
WOOL2435	PTR	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	13:46:50 22 Feb 2011	04:13:57 23 Feb 2011
AMBE487	PR	14:10:00 22 Feb 2011	14:15:53 22 Feb 2011	14:32:50 22 Feb 2011	20:30:38 22 Feb 2011
WOOD7711	WT	14:04:00 22 Feb 2011	14:09:13 22 Feb 2011	14:33:25 22 Feb 2011	07:43:53 02 Mar 2011
DUNS4411	WT	14:55:00 22 Feb 2011	15:00:16 22 Feb 2011	15:23:16 22 Feb 2011	10:51:00 02 Mar 2011
21C	OF	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	15:43:46 22 Feb 2011	18:00:00 22 Feb 2011
MIDCANVSO1	VSO	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	15:56:59 22 Feb 2011	23:33:57 22 Feb 2011
20A	OF	17:04:37 22 Feb 2011	17:04:45 22 Feb 2011	17:36:07 22 Feb 2011	07:03:03 23 Feb 2011
GOVE331	P1	13:46:48 22 Feb 2011	17:52:47 22 Feb 2011	18:12:35 22 Feb 2011	04:47:14 23 Feb 2011
RANG761	CU	20:14:47 22 Feb 2011	20:15:24 22 Feb 2011	20:41:15 22 Feb 2011	00:24:03 23 Feb 2011
RANG7611	WT	20:15:04 22 Feb 2011	20:15:24 22 Feb 2011	20:41:16 22 Feb 2011	14:29:18 27 Feb 2011
SUMN2810	RU	20:15:18 22 Feb 2011	20:15:24 22 Feb 2011	20:41:16 22 Feb 2011	06:38:54 23 Feb 2011
SOUT451	P1	20:17:59 22 Feb 2011	20:18:58 22 Feb 2011	20:41:17 22 Feb 2011	22:55:57 22 Feb 2011

The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.


Some message timestamps may differ to actual times in multi-agency incidents. Communication centres can supply correct times if essential.

CHRI216	TL	13:45:00 22 Feb 2011	13:46:49 22 Feb 2011	21:16:13 22 Feb 2011	23:00:00 22 Feb 2011
LINC4111	WT	13:46:48 22 Feb 2011	22:40:00 22 Feb 2011	22:45:44 22 Feb 2011	02:54:50 24 Feb 2011
DUNE2118	CUHU	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	02:11:43 23 Feb 2011	16:52:18 02 Mar 2011
BROO3111	WT	04:54:21 23 Feb 2011	05:02:51 23 Feb 2011	05:28:36 23 Feb 2011	16:39:13 02 Mar 2011
WEST9511	WT	08:16:58 23 Feb 2011	08:17:32 23 Feb 2011	08:28:59 23 Feb 2011	12:15:17 23 Feb 2011
BROO311	P1	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	11:30:50 23 Feb 2011	14:56:55 23 Feb 2011
CHRI211	P1	18:24:34 23 Feb 2011	18:25:38 23 Feb 2011	18:30:35 23 Feb 2011	14:03:58 26 Feb 2011
CHRI214	PM	21:34:05 23 Feb 2011	21:35:41 23 Feb 2011	21:39:12 23 Feb 2011	13:43:50 02 Mar 2011
CUST7811	WT	13:46:48 22 Feb 2011	00:32:15 24 Feb 2011	00:34:06 24 Feb 2011	17:59:11 25 Feb 2011
TIMA804	PM	16:59:29 24 Feb 2011	17:04:11 24 Feb 2011	17:10:20 24 Feb 2011	19:43:34 24 Feb 2011
HARE261	P1	22:18:57 24 Feb 2011	22:22:59 24 Feb 2011	22:39:00 24 Feb 2011	03:03:46 25 Feb 2011
STAL231	P1	13:46:48 22 Feb 2011	02:21:41 25 Feb 2011	02:44:44 25 Feb 2011	13:02:01 28 Feb 2011
CHRI217	PR	13:46:48 22 Feb 2011	05:42:55 25 Feb 2011	05:52:31 25 Feb 2011	05:57:02 25 Feb 2011
KIRW7211	WT	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	16:28:30 25 Feb 2011	09:04:05 28 Feb 2011
SOCK257	PR	18:02:48 22 Feb 2011	18:02:52 22 Feb 2011	12:23:59 27 Feb 2011	16:21:18 27 Feb 2011
TRANS042	P2	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	21:34:42 27 Feb 2011	02:16:54 28 Feb 2011
BURN911	P1	13:46:48 22 Feb 2011	13:46:49 22 Feb 2011	02:17:06 28 Feb 2011	07:14:02 28 Feb 2011
SOUT4511	WT	09:00:00 28 Feb 2011	09:05:00 28 Feb 2011	09:10:54 28 Feb 2011	18:56:20 01 Mar 2011
RAKA6411	WT	14:35:45 28 Feb 2011	14:36:08 28 Feb 2011	15:12:17 28 Feb 2011	21:41:33 28 Feb 2011
OXFO7911	WT	13:29:26 02 Mar 2011	13:30:24 02 Mar 2011	13:44:25 02 Mar 2011	16:46:14 02 Mar 2011
EAST462	P2	15:15:36 22 Feb 2011			15:16:18 22 Feb 2011
WOOD7726	VN	13:46:48 22 Feb 2011	08:31:45 23 Feb 2011		11:21:53 23 Feb 2011
WOOD777	PR	14:28:59 22 Feb 2011			14:29:09 22 Feb 2011
CHRI212	P2	11:25:21 23 Feb 2011			11:26:00 23 Feb 2011
CHRI2110	RU	13:46:48 22 Feb 2011	14:59:43 22 Feb 2011		15:12:23 22 Feb 2011
HORO7311	WT	13:55:15 01 Mar 2011			13:55:49 01 Mar 2011

Start->Alert

7 min

10 min



The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.

Some message timestamps may differ to actual times in multi-agency incidents. Communication centres can supply correct times if essential.

0 min

15 min

30 min

Alert->1st Arrival

Elapsed Times

Callsign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Depart
ADDI221	00:00:01	00:00:51	00:00:52	57:38:18
WOOL2435	00:14:18	00:00:02	00:14:20	14:41:27
AMBE487	00:37:30	00:22:50	01:00:20	06:58:08
WOOD7711	00:31:30	00:29:25	01:00:55	86:11:23
DUNS4411	01:22:30	00:28:16	01:50:46	89:18:30
21C	00:14:18	01:56:58	02:11:16	04:27:30
MIDCANVSO1	00:14:18	02:10:11	02:24:29	10:01:27
20A	03:32:07	00:31:30	04:03:37	17:30:33
GOVE331	00:14:18	04:25:47	04:40:05	15:14:44
RANG761	06:42:17	00:26:28	07:08:45	10:51:33
RANG7611	06:42:34	00:26:12	07:08:46	20:56:48
SUMN2810	06:42:48	00:25:58	07:08:46	17:06:24
SOUT451	06:45:29	00:23:18	07:08:47	09:23:27
CHRI216	00:12:30	07:31:13	07:43:43	09:27:30
LINC4111	00:14:18	08:58:56	09:13:14	37:22:20
DUNE2118	00:14:18	12:24:55	12:39:13	95:19:48
BROO3111	15:21:51	00:34:15	15:56:06	95:06:43
WEST9511	18:44:28	00:12:01	18:56:29	22:42:47
BROO311	00:14:18	21:44:02	21:58:20	25:24:25
CHRI211	28:52:04	00:06:01	28:58:05	96:31:28
CHRI214	32:01:35	00:05:07	32:06:42	92:11:20
CUST7811	00:14:18	34:47:18	35:01:36	76:26:41
TIMA804	51:26:59	00:10:51	51:37:50	54:11:04
HARE261	56:46:27	00:20:03	57:06:30	61:31:16
STAL231	00:14:18	60:57:56	61:12:14	43:29:31
CHRI217	00:14:18	64:05:43	64:20:01	64:24:32
KIRW7211	00:14:18	74:41:42	74:56:00	39:31:35
SOCK257	04:30:18	14:21:11	18:51:29	22:48:48
TRANS042	00:14:18	27:47:54	28:02:12	32:44:24
BURN911	00:14:18	32:30:18	32:44:36	37:41:32
SOUT4511	39:27:30	00:10:54	39:38:24	73:23:50
RAKA6411	45:03:15	00:36:32	45:39:47	52:09:03
OXFO7911	91:56:56	00:14:59	92:11:55	95:13:44
EAST462	01:43:06			01:43:48
WOOD7726	00:14:18			21:49:23
WOOD777	00:56:29			00:56:39
CHRI212	21:52:51			21:53:30
CHRI2110	00:14:18			01:39:53
HORO7311	68:22:45			68:23:19

Notifications

Date	Time	Party Notified
------	------	----------------

The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.

Some message timestamps may differ to actual times in multi-agency incidents. Communication centres can supply correct times if essential.

Date	Time	Party Notified
23 Feb 2011	13:35:04	AMBO
24 Feb 2011	10:27:51	CITY ICP WILL ORGANISE DAZZLE PAINT
24 Feb 2011	13:03:55	RANG USAR COMMAND - THEY WILL ORGANISE THIS FOR CTV COMMAND
25 Feb 2011	16:58:31	CTV COMMAND
25 Feb 2011	16:58:31	SOUTHCOMS ACK JOB
25 Feb 2011	16:58:31	POLICE - THEY WILL VERIFY THE DETAILS AND ADVISE
27 Feb 2011	13:14:17	USAR COMMAND ADVISED WOOD7711 NOT BEING RELEASED BY QUEENSLAND USAR.

Equipment Involved	Unable to classify
Year	
Make	
Model	

Fire

Arrival Condition	Small fire		
Heat Source	Heat from electrical equipment: Properly operating		
Termination Stage	Flame		
First Object Ignited	Packing, Wrapping material		
First Object Material	Cardboard		
Second Object Ignited			
Second Object Material			
Indicated Cause	Earthquake		
Certainty of Cause	High		
Age of Person	No person involved		
Ethnicity	No person involved		
Gender			
FAIP Service Offered	No	FAIP Service Accepted	No

Alarms

Type of Alarm Initiating Call	Smoke Detector System (Monitored)
Performance of System	Unable to classify
Failure/Ineffectiveness of system	Unable to classify
Number of sprinkler heads operated	

Structure

Area of One Floor	600
Age of Building	1970 - 1991
Structural Frame Type	Reinforced concrete tilt slab
Number of Floors	5
Number of Basements	0
Internal Wall Lining	Gypsum board (e.g. Gib board, Elephant board)
Ceiling Lining	Gypsum board (e.g. Gib board, Elephant board)
Material Generating Most Flame	Wood: Sawn, Finished timber
Material Generating Most Smoke	Fabric, Fibre
Avenue of Flame Travel	Unknown
Avenue of Smoke Travel	Unknown
Extent of Flame Damage	Confined to structure of origin
Area of Flame Damage	400

Extent of Smoke Damage	No damage of this type
Area of Smoke Damage	0
Extent of Water Damage	No damage of this type
Area of Water Damage	0
Extent of Fire Control Damage	Confined to structure of origin
Area of Fire Control Damage	400

Comments

08:46, Wed 9 March 2011

Reporter Comments

Multiple Rescues and Multiple Fatalities as a result of the earthquake.
DVI Police and USAR involved in operations

Bruce Irvine

09:50, Tue 29 March 2011

Reporter Comments

This building was collapsed during the QE and no investigation was carried out.

Graham Davies