

Site history

Conf in original discussion:

10. cracks caused prior to completion of section
agreed to epoxy grout from inside etc.

noted that this work has not been carried out
as agreed and should now be done

A.

- Piling guarantee.

- Conf settle or not account received for retails.

CALCULATIONS

best
solution
Judge

SECT -
FILE 2672
DATE 29/10/86

remove internal walls -

slit mid bay to front bay

full width - keep lights

consider rear mezz

cranes go - runway beams

- lighting - repair - mezz in apex -

natural light

4930