


STREET ADDRESS 249 MADRAS ST		BU/40 135/249
CODE	DATE	COMMENTS
Found	10-10-86	Set out by Surveyor - OK Steel to finish Engineer's Plan.
Found	11-12-86	Last of Found Beams
1st Floor	18-2-87	OK
Shear Wall	8-3-87	OK. Cast by U.S.
	31-3-87	Preparing 2nd floor.
	20-4-87	Fixing Cup wrong Card Left New Form.

Permit No.

*(Handwritten signature)*



TYPE:


OFFICE

104 X 1 2500, 18, U.S. Pat. Nos. 3,147,561; 3,220,133 U.S. Pat. No. 3,251,879 Others Pending 6 Shown

STREET ADDRESS 249 MADRAS ST		BU/40 135/249
CODE	DATE	COMMENTS
	9-10-87	Foreman to prove Frank Cole on site & fill Block with 1st West End.
	16-10-87	No Contact from site so digital found per Cole to be removed Foreman Advised.

Permit No.

*(Handwritten signature)*



TYPE:


OFFICE

104 X 1 2500, 18, U.S. Pat. Nos. 3,147,561; 3,220,133 U.S. Pat. No. 3,251,879 Others Pending

STREET ADDRESS 249 MADRAS ST		BU/40 135/249
CODE	DATE	COMMENTS
		Call 200 on Street. Survey peg set at 3m from Kerb.
	11-1-88	Cole removed Boxing ready to pour.
	22-3-88	Finishing Handrails & Hardware
	15-6-88	

Permit No.

*(Handwritten signature)*



TYPE:

OFFICE

104 X 1 2500, 18, U.S. Pat. Nos. 3,147,561; 3,220,133 U.S. Pat. No. 3,251,879 Others Pending