COMPUSOFT

# ENGINEERING

# CTV Building

# Non-Linear Time History Analysis (NLTHA) Report

Ref: 12026-00 FIRST DRAFT ISSUE July 2012

Prepared for:

Canterbury Earthquakes Royal Commission Te Komihana Rūwhenua o Waitaha PO Box 14053, Christchurch Airport, Christchurch 8544

BUI.MAD249.0535.1

MM Y

Compusoft Engineering Limited, PO Box 9493, Newmarket, Auckland, New Zealand. Telephone: +64 9 522 1456 www.compusoftengineering.com

<u>Docu</u>	iment Contro	<u>l Record</u>			
	Report Title	Report on Additional Non-Linear Seismic Analyses			
	Document ID	12026-00	Project Number		12036
	File Path	Z:\01 Projects current\12026 - CTVNL(extended) - RoyalCommission\Report\12026.00 Report on Additional Non-Linear Analyses.docx			
Client		Canterbury Earthquakes Royal Commission	Client Contact		Professor Athol Carr
Rep	port prepared by	Compusoft Engineering Limited PO Box 9493, Newmarket Auckland 1149 09 522 1456			
Rev	Date	<b>Revision Details/Status</b>	Author	Verifier	Approver
0	13 July 2012	Draft	DSB/T	TJS/NJB	BJD
(	Current Revision	0			
Appr	<u>oval</u>				
Author Signature		D.b.ally	Approver Signature		B Davidon
Name		Derek Bradley Tony Stuart Dr. Nicholas Brooke	Name		Dr. Barry Davidson
Title		Structural Engineer		Title	Director
Limitations					

This report has been prepared for Canterbury Earthquakes Royal Commission, and the findings presented within the report are for their sole use. The findings are not intended for use by other parties, and may not contain sufficient information for the purposes of other parties or other uses. The client will place no reliance on any draft reports, incomplete documents, and/or verbal advice.

Compusoft Engineering Limited undertakes professional services using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at the current time. No other warranty, expressed or implied, is made as to the professional advice presented in this report.

# <u>Contents</u>

Document Control Record	i
Approval	i
Limitations	i
List of figures	.iv
List of Tables	xiii
Executive Summary	1
1. Introduction	3
2. Building description	4
3. Analysis Procedure Overview	7
3.1. Alterations Made from Previous Analysis Model	7
3.2. Analysis Procedure	
4. Material Properties	10
4.1. Concrete	10
4.2. Reinforcement	11
5. Structural Elements	13
5.1. Soil Structure Interaction	13
5.2. Foundation Elements	
5.3. Reinforced Concrete Frames	15
5.3.1. Beams and beam hinges	15
5.3.2. Columns and column hinges	18
5.3.3. Beam-Column Joints	20
5.4. Reinforced Concrete Shear Walls	26
5.5. Floors	27
6. Loadings	30
6.1. Gravity Loadings	30
6.2. Dynamic Mass	31
7. Seismic Analyses	33
7.1. Modal Analysis	33
7.2. Non-Linear Static (Pushover) Analysis	34
7.3. Non-linear Dynamic (Time History) Analysis	34

Rep	ort on Addi	tional Non-Linear Seismic Analyses	July 2012
	7.3.1.	Analysis Ground Motions	
	7.3.2.	Damping	
8.	Non-Li	near Pushover Results	
8	8.1. For	ce-Displacement Relationships	
8	8.2. Bui	lding Displacement Ductility Capacity.	
9.	Non Lir	near Time History Darfield Results	47
	9.1.1.	Drifts and Displacements	
	9.1.2.	Diaphragm Connection Forces.	
	9.1.3.	Inelastic Wall Demands.	
	9.1.4.	Inelastic Column Actions	55
	9.1.5.	Inelastic Beam-Column Joint Actions	59
10.	Non I	Linear Time History: Lyttelton Results	
	10.1.1.	Drifts and Displacements	65
	10.1.2.	Diaphragm Connection Forces.	67
	10.1.3.	Inelastic Column Actions	72
	10.1.4.	Beam-Column Joints	
11.	Vertic	cal Earthquake Effects	
1	1.1. A	Axial Load Effects	
12.	Concl	usions	
13.	Refer	ences	91
List	t of appen	dices	
	Append	ix A Nonlinear analysis of diagonally reinforced coupling beams	96
	Append interacti		moment (P-M)
	Append	ix C Development of a model for beam-column joints of the CTV bu	ilding 103
	Append	ix D Foundation Modelling Properties	119
	Append	ix E Acceleration Time History Records	
	Append	ix F Analysis Results - Darfield Event: CBGS Record	
	Append	ix G Analysis Results - Darfield Event: CCCC Record	
	Append	ix H Analysis Results - Lyttelton Aftershock: CBGS record	
	Append	ix I Analysis Results - Lyttelton Aftershock: CCCC record	

#### BUI.MAD249.0535.5

Report on Additional Non-Linear Seismic AnalysesJuly 2012
Appendix J Analysis Results - Lyttelton Aftershock: CHHC record
Appendix K Analysis Results - Lyttelton Aftershock: REHS record
List of figures
Figure 1: Overall view of the CTV structural model (viewed from SW & SE respectively)
Figure 2: CTV structural model viewed from the east (slabs omitted for clarity)
Figure 3: CTV foundation arrangement viewed from the south-west
Figure 4: Building grid system
Figure 3: Time history analysis sequence
Figure 5: Concrete stress-strain curve
Figure 6: Reinforcing steel stress-strain curve
Figure 7: CTV foundation element location plan (Design Engineer 1986)
Figure 8: Typical moment-curvature relationship for beam hinges
Figure 9: Reinforcement anchorage in Grid A beam column joint zone (Design Engineer 1986) 17
Figure 10: Typical bottom reinforcement anchorage in interior beam column joint zone (Design Engineer 1986)
Figure 11: Effective column stiffness relationship
Figure 12: Typical column reinforcement. (Design Engineer 1986)
Figure 13: Column at GL 4 D/E (C18) to wall connection detailing at roof level (Design Engineer 1986)
Figure 14: Joint response backbone curve for joint at grid A2, level 3 (exterior E/W, interior N/S)
Figure 15: Effective wall stiffness relationship
Figure 16: South shear wall typical coupling beam reinforcement arrangement (Design Engineer 1986)
Figure 17: Seismic mass distribution
Figure 18: Site spectral displacements
Figure 19: Darfield N00E 5% damped response spectra (north/south)
Figure 20: Darfield N90E 5% damped response spectra (east/west)
Figure 21: Darfield Vertical 5% damped response spectra
Figure 22: Lyttelton N00E 5% damped response spectra (north/south)
Figure 23: Lyttelton N90E 5% damped response spectra (east/west)

Figure 24: Lyttelton Vertical 5% damped response spectra	38
Figure 25: Equivalent viscous damping vs structure period - Lyttelton	41
Figure 26: Force-displacement relationship	42
Figure 27: Base shear components - east/west direction	43
Figure 28: Base shear components - north/south direction.	43
Figure 29: Level 6 western pushover displacement profile.	44
Figure 30: Level 6 eastern pushover displacement profile	45
Figure 31: Level 6 northern pushover displacement profile.	45
Figure 32: Level 6 southern pushover displacement profile	
Figure 33: Bi-linear pushover plots	46
Figure 34: Frame A north/south storey drifts - Darfield.	47
Figure 35: Frame F north/south storey drifts - Darfield.	47
Figure 36: Frame 1 east/west storey drifts - Darfield.	48
Figure 37: Frame 4 east/west storey drifts - Darfield.	48
Figure 38: Slab 4 C-C/D section cut line.	52
Figure 39: Column F3, Level 4 hinge rotation and elongation vs time, CBGS, Darfield	56
Figure 40: Column F3 Level 4 hinge strain vs time, CBGS, Darfield.	56
Figure 41: Column F3 Level 4 hinge axial and moments vs time, CBGS, Darfield	57
Figure 42: Column F3 Level 4 hinge moment axial relationship, CBGS, Darfield.	57
Figure 43: Column F3 Level 4 hinge hysteretic form, CBGS, Darfield.	58
Figure 44: Column F3 Level 4 moment rotation plot, CBGS, Darfield	58
Figure 45: Column F3 Level 4 hinge bi-axial moment plot, CBGS, Darfield	59
Figure 46: Colour coding used to represent different joint deformation states in Figure 47 to Fi	0
Figure 47: One-way beam-column joint R1 rotations - CBGS, Darfield	60
Figure 48: Two-way beam-column joint R1 rotations - CBGS, Darfield	61
Figure 49: Two-way beam-column joint R2 rotations - CBGS, Darfield	61
Figure 50: One-way beam-column joint R1 rotations - CCCC, Darfield.	62
Figure 51: Two-way beam-column joint R1 rotations - CCCC, Darfield	63
Figure 52: Two-way beam-column joint R2 rotations - CCCC, Darfield	63
Figure 53: Frame A north/south storey drifts - Lyttelton.	65

Figure 54: Frame F north/south storey drifts - Lyttelton	66
Figure 55: Frame 1 east/west storey drifts - Lyttelton	
Figure 56: Frame 4 east/west storey drifts - Lyttelton	
Figure 57: Building level 6 displacements, CBGS, Lyttelton	
Figure 58: Column C2, Level 1 hinge rotation and elongation vs time, CBGS, Lyttelton	
Figure 59: Column C2 Level 1 hinge strain vs time, CBGS, Lyttelton.	
Figure 60: Column C2 Level 1 hinge axial and moments vs time, CBGS, Lyttelton.	
Figure 61: Column C2 Level 1 hinge moment axial relationship, CBGS, Lyttelton	
Figure 62: Column C2 Level 1 hinge hysteretic form, CBGS, Lyttelton	
Figure 63: Column C2 Level 1 moment rotation, CBGS, Lyttelton.	
Figure 64: Column C2 Level 1 hinge bi-axial moment, CBGS, Lyttelton Figure 65: One-way beam-column joint R1 rotations - CBGS, Lyttelton	
Figure 66: Two-way beam-column joint R1 rotations - CBGS, Lyttelton	
Figure 67: Two-way beam-column joint R1 rotations - CBGS, Lyttelton (cumulative)	
Figure 68: Two-way beam-column joint R2 rotations - CBGS, Lyttelton	80
Figure 69: Two-way beam-column joint R2 rotations - CBGS, Lyttelton (cumulative)	81
Figure 70: One-way beam-column joint R1 rotations - CCCC, Lyttelton	82
Figure 71: Two-way beam-column joint R1 rotations - CCCC, Lyttelton.	82
Figure 72: Two-way beam-column joint R1 rotations - CCCC, Lyttelton (cumulative)	83
Figure 73: Two-way beam-column joint R2 rotations - CCCC, Lyttelton	83
Figure 74: Two-way beam-column joint R2 rotations - CCCC, Lyttelton (cumulative)	84
Figure 75: One-way beam-column joint R1 rotations - CHHC, Lyttelton	84
Figure 76: Two-way beam-column joint R1 rotations - CHHC, Lyttelton	85
Figure 77: Two-way beam-column joint R2 rotations - CHHC, Lyttelton	85
Figure 78: One-way beam-column joint R1 rotations - REHS, Lyttelton	86
Figure 79: Two-way beam-column joint R1 rotations - REHS, Lyttelton	86
Figure 80: Two-way beam-column joint R2 rotations - REHS, Lyttelton	87
Figure 81: Column C2 axial load variation - CBGS (left) & CCCC (right), Lyttelton	88
Figure 82: Column F2 axial load variation - CBGS (left) & CCCC (right), Lyttelton	88
Figure A.1: Proposed model (from Hindi and Hassan 2004)	96
Figure A.2: Example wall reinforcement	

Figure A.3: SAP2000 analysis model
Figure A.4: Reinforcing nonlinear steel stress-strain plot
Figure A.5: Concrete nonlinear stress-strain plot
Figure A.6: Nonlinear backbone curve
Figure A.7: Coupling beam hysteretic response
Figure A.8: Coupling beam hysteretic response (Takeda reinforcement)
Figure A.9: Reinforcing nonlinear stress-strain plot (modified for strain penetrations)
Figure C.1: Backbone curves from various sources (Alire 2002; ASCE 2006; Birely et al. 2012; S. Park 2010; Sharma et al. 2011; Walker 2001; Weng Yuen 2010)
Figure C.2: Joint shear stress vs strain until 3% drift for tests by Walker (2001) and Alire (2002) of interior unreinforced joints with axial load of ≈0.1Agfc
Figure C.3: Joint shear stress-deformation response of deficient beam-column joints (from Kurose 1987)
Figure C.4: Proposed backbone curve for joint deformation
Figure C.5: Comparison of PEER-4150 (Alire 2002; D. E. Lehman et al. 2004) against proposed backbone curve
Figure C.6: Column axial load ratio against joint shear strength coefficient for interior joints 111
Figure C.7: Column axial load ratio against joint shear strength coefficient for exterior joints 111
Figure C.8: Relationship of factor K to curvature ductility for different joint types (after NZSEE 2006)
Figure C.9: Example of beam-column joint finite element model relying on inputs from multiple nodes (from Mitra and Lowes 2007)
Figure C.10: Moment diagram assumed for development of joint spring
Figure C.11: Damage of exterior joint (left) observed during testing and (right) illustrated schematically (from Pampanin et al. 2002)
Figure C.12: Plan views of CTV Building exterior joints (Design Engineer 1986)
Figure C.13: Relationship between joint shear capacity and framing member curvature ductility (from NZSEE 2006)
Figure D.1: Expected Soil Stiffness (Sinclair 2011)
Figure E.1: Darfield 20100903_163541_CBGS N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots
Figure E.2: Darfield 20100903_163541_CCCC N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

Figure E.3: Lyttelton 20110221_235142_CBGS N00E (top), N90E (middle), and (bottom) acceleration time history record plots	
Figure E.4: Lyttelton 20110221_235142_CCCC N00E (top), N90E (middle), and (bottom) acceleration time history record plots	
Figure E.5: Lyttelton 20110221_235142_CHHC N00E (top), N90E (middle), and (bottom) acceleration time history record plots	
Figure E.6: Lyttelton 20110221_235142_REHS N00E (top), N90E (middle), and Vertical acceleration time history record plots	
Figure F.1: Level 6 Southeast corner displacements	127
Figure F.2: Level 6 Northwest corner displacements	127
Figure F.3: Frame A north/south inter-storey displacements	128
Figure F.4: Frame F north/south inter-storey displacements	129
Figure F.5: Frame 1 east/west inter-storey displacements	129
Figure F.6: Frame 4 east/west inter-storey displacements	130
Figure F.7: North core total diaphragm north/south actions	130
Figure F.8: North core total diaphragm east/west actions	131
Figure F.9: North core total diaphragm in-plane moments	131
Figure F.10: North core Wall C diaphragm north/south actions	
Figure F.11: North core Wall C/D diaphragm north/south actions	
Figure F.12: North core Wall D diaphragm north/south actions	133
Figure F.13: North core Wall D/E diaphragm north/south actions	133
Figure F.14: North core Slab 4/C to C/D diaphragm north/south actions	134
Figure F.15: North core Slab 4/C to C/D diaphragm east/west actions	
Figure F.16: North core Slab 4/C to C/D diaphragm in-plane moments	135
Figure F.17: North core Wall 5 diaphragm east/west	135
Figure F.18: South wall diaphragm east/west actions	136
Figure F.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	137
Figure F.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	138
Figure F.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	139
Figure F.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	140
Figure F.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	141
Figure G.1: Level 6 Southeast corner displacements, Darfield	142

Figure G.2: Level 6 Northwest corner displacements, Darfield	
Figure G.3: Frame A north/south inter-storey displacements, Darfield	144
Figure G.4: Frame F north/south inter-storey displacements, Darfield	144
Figure G.5: Frame 1 east/west inter-storey displacements, Darfield	
Figure G.6: Frame 4 east/west inter-storey displacements, Darfield	
Figure G.7: North core total diaphragm north/south actions	146
Figure G.8: North core total diaphragm east/west actions	146
Figure G.9: North core total diaphragm in-plane moments	147
Figure G.10: North core Wall C diaphragm north/south actions	147
Figure G.11: North core Wall C/D diaphragm north/south actions	148
Figure G.12: North core Wall D diaphragm north/south actions	
Figure G.13: North core Wall D/E diaphragm north/south actions	149
Figure G.14: North core Slab 4/C to C/D diaphragm north/south actions	149
Figure G.15: North core Slab 4/C to C/D diaphragm east/west actions	150
Figure G.16: North core Slab 4/C to C/D diaphragm in-plane moments	150
Figure G.17: North core Wall 5 diaphragm east/west actions	151
Figure G.18: South wall diaphragm east/west actions	151
Figure G.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	153
Figure G.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	
Figure G.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	155
Figure G.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	156
Figure G.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield	157
Figure H.1: Level 6 Southeast corner displacements, Undamaged	158
Figure H.2: Level 6 Southeast corner displacements, Damaged	159
Figure H.3: Level 6 Northwest corner displacements, Undamaged	159
Figure H.4: Level 6 Northwest corner displacements, Damaged	
Figure H.5: Frame A north/south inter-storey displacements, Undamaged	161
Figure H.6: Frame A north/south inter-storey displacements, Damaged	161
Figure H.7: Frame F north/south inter-storey displacements, Undamaged	
Figure H.8: Frame F north/south inter-storey displacements, Damaged	
Figure H.9: Frame 1 east/west inter-storey displacements, Undamaged	

Figure H.10: Frame 1 east/west inter-storey displacements, Damaged	
Figure H.11: Frame 4 east/west inter-storey displacements, Undamaged	
Figure H.12: Frame 4 east/west inter-storey displacements, Damaged	
Figure H.13: North core total diaphragm north/south actions	
Figure H.14: North core total diaphragm east/west actions	
Figure H.15: North core total diaphragm in-plane moments	
Figure H.16: North core Wall C diaphragm north/south actions	
Figure H.17: North core Wall C/D diaphragm north/south actions	
Figure H.18: North core Wall D diaphragm north/south actions	
Figure H.19: North core Wall D/E diaphragm north/south actions	
Figure H.20: North core Slab 4/C to C/D diaphragm north/south actions	
Figure H.21: North core Slab 4/C to C/D diaphragm east/west actions	
Figure H.22: North core Slab 4/C to C/D diaphragm in-plane moments	
Figure H.23: North core Wall 5 diaphragm east/west actions	
Figure H.24: South wall diaphragm east/west actions	
Figure H.25: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure H.26: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure H.27: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure H.28: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure H.29: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure I.1: Level 6 Southeast corner displacements, Undamaged	
Figure I.2: Level 6 Southeast corner displacements, Damaged	
Figure I.3: Level 6 Northwest corner displacements, Undamaged	
Figure I.4: Level 6 Northwest corner displacements, Damaged	
Figure I.5: Frame A north/south inter-storey displacements, Undamaged	
Figure I.6: Frame A north/south inter-storey displacements, Damaged	
Figure I.7: Frame F north/south inter-storey displacements, Undamaged	
Figure I.8: Frame F north/south inter-storey displacements, Damaged	
Figure I.9: Frame 1 east/west inter-storey displacements, Undamaged	
Figure I.10: Frame 1 east/west inter-storey displacements, Damaged	
Figure I.11: Frame 4 east/west inter-storey displacements, Undamaged	

Figure I.12: Frame 4 east/west inter-storey displacements, Damaged	
Figure I.13: North core total diaphragm north/south actions	
Figure I.14: North core total diaphragm east/west actions	
Figure I.15: North core total diaphragm in-plane moments	
Figure I.16: North core Wall C diaphragm north/south actions	
Figure I.17: North core Wall C/D diaphragm north/south actions	
Figure I.18: North core Wall D diaphragm north/south actions	
Figure I.19: North core Wall D/E diaphragm north/south actions	
Figure I.20: North core Slab 4/C to C/D diaphragm north/south actions	
Figure I.21: North core Slab 4/C to C/D diaphragm east/west actions	
Figure I.22: North core Slab 4/C to C/D diaphragm in-plane moments	
Figure I.23: North core Wall 5 diaphragm east/west actions	
Figure I.24: South wall diaphragm east/west actions	
Figure I.25: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure I.26: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure I.27: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure I.28: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure I.29: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	
Figure J.1: Level 6 Southeast corner displacements	
Figure J.2: Level 6 Northwest corner displacements	
Figure J.3: Frame A north/south inter-storey displacements	
Figure J.4: Frame F north/south inter-storey displacements	
Figure J.5: Frame 1 east/west inter-storey displacements	
Figure J.6: Frame 4 east/west inter-storey displacements	
Figure J.7: North core total diaphragm north/south actions	
Figure J.8: North core total diaphragm east/west actions	
Figure J.9: North core total diaphragm in-plane moments	
Figure J.10: North core Wall C diaphragm north/south actions	
Figure J.11: North core Wall C/D diaphragm north/south actions	
Figure J.12: North core Wall D diaphragm north/south actions	
Figure J.13: North core Wall D/E diaphragm north/south actions	

Figure J.14: North core Slab 4/C to C/D diaphragm north/south actions	203
Figure J.15: North core Slab 4/C to C/D diaphragm east/west actions	203
Figure J.16: North core Slab 4/C to C/D diaphragm in-plane moments	204
Figure J.17: North core Wall 5 diaphragm east/west actions	204
Figure J.18: South wall diaphragm east/west actions	205
Figure J.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	206
Figure J.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	207
Figure J.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	208
Figure J.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	209
Figure J.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	210
Figure K.1: Level 6 Southeast corner displacements	211
Figure K.2: Level 6 Northwest corner displacements	211
Figure K.3: Frame A north/south inter-storey displacements	212
Figure K.4: Frame F north/south inter-storey displacements	213
Figure K.5: Frame 1 east/west inter-storey displacements	213
Figure K.6: Frame 4 east/west inter-storey displacements	214
Figure K.7: North core total diaphragm north/south actions	214
Figure K.8: North core total diaphragm east/west actions	215
Figure K.9: North core total diaphragm in-plane moments	215
Figure K.10: North core Wall C diaphragm north/south actions	216
Figure K.11: North core Wall C/D diaphragm north/south actions	216
Figure K.12: North core Wall D diaphragm north/south actions	217
Figure K.13: North core Wall D/E diaphragm north/south actions	217
Figure K.14: North core Slab 4/C to C/D diaphragm north/south actions	218
Figure K.15: North core Slab 4/C to C/D diaphragm east/west actions	218
Figure K.16: North core Slab 4/C to C/D diaphragm in-plane moments	219
Figure K.17: North core Wall 5 diaphragm east/west actions	219
Figure K.18: South wall diaphragm east/west actions	220
Figure K.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	221
Figure K.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	222
Figure K.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	223

Figure K.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	. 224
Figure K.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton	. 225

# List of Tables

Table 1: Unconfined concrete stress-stain parameters	10
Table 2: Reinforcing steel stress-strain parameters.	11
Table 3: Expected soil stiffness	14
Table 4: Stiffness modifiers for elastically responding beam elements	15
Table 5: Column stiffnesses used in the analysis model	19
Table 6: Definition of beam-column joint response backbone curve	21
Table 7: Summary details of beam-column joints	22
Table 8: Modelled diaphragm (drag bar) connection capacities	
Table 9: Basic load pattern definitions	
Table 10: Global base reactions for basic load patterns (linear)	31
Table 11: Imposed loading allowances (for derivation of dynamic mass)	
Table 12: Modal participating mass ratios	33
Table 13: Seismic event information	35
Table 14: Adopted earthquake record information	35
Table 15: Adopted record start and finish times	39
Table 16: Rayleigh damping parameters - Darfield	40
Table 17: Rayleigh damping parameters - Lyttelton	41
Table 18: Wall C diaphragm connection forces - Darfield.	49
Table 19: Wall C/D diaphragm connection forces - Darfield	49
Table 20: Wall D diaphragm connection forces - Darfield	49
Table 21: Wall D/E diaphragm connection forces - Darfield.	50
Table 22: Wall 5 (C to C/D) diaphragm connection forces - Darfield.	50
Table 23: North core total diaphragm connection forces - Darfield.	51
Table 24: North core total diaphragm connection forces - Darfield.	51
Table 25: Slab 4 C to C/D diaphragm E/W actions - Darfield	52
Table 26: Slab 4 C to C/D diaphragm N/S actions - Darfield	52
Table 27: South wall diaphragm connection forces - Darfield	53

Table 28: Wall strains - Darfield	54
Table 29: South Wall Coupling Beam Strain	54
Table 30: CBGS peak column hinge compression strains - Darfield	55
Table 31: Wall C diaphragm connection forces - Lyttelton	68
Table 32: Wall C/D diaphragm connection forces - Lyttelton	68
Table 33: Wall D diaphragm connection forces - Lyttelton.	68
Table 34: Wall D/E diaphragm connection forces - Lyttelton.	69
Table 35: Wall 5 (C to C/D) diaphragm connection forces - Lyttelton.	69
Table 36: North core total diaphragm connection E/W forces - Lyttelton.	70
Table 37: North core total diaphragm connection N/S forces - Lyttelton.	70
Table 38: North core total diaphragm connection forces - Lyttelton	70
Table 39: Slab 4 C to C/D diaphragm E/W actions - Lyttelton.	71
Table 40: Slab 4 C to C/D diaphragm N/S actions - Lyttelton.	71
Table 41: Slab 4 C to C/D diaphragm connection forces - Lyttelton.	72
Table 42: South wall diaphragm connection forces - Lyttelton.	72
Table F.1: Wall D and D/E diaphragm disconnection times	. 128
Table G.1: Wall D and D/E diaphragm disconnection times	. 143
Table H.1: Wall D and D/E diaphragm disconnection times	160
Table I.1: Wall D and D/E diaphragm disconnection times	. 179
Table J.1: Wall D and D/E diaphragm disconnection times	. 197
Table K.1: Wall D and D/E diaphragm disconnection times	.212

Commune of Engineering Limited	
Compusoft Engineering Limited	

#### **Executive Summary**

This report describes the work performed by Compusoft Engineering Ltd to support the NLTA Expert Committee of the Royal Commission of Inquiry. The work undertaken has been the modification of a SAP2000 computer model of the CTV building developed for the DBH investigation into that building's collapse during the February 2011 earthquake and the rerunning of that model for a range of earthquake events.

The major changes to the model from that used in the DBH analyses are:

- The non-linear beam column joint behaviour has been modelled.
- Plastic hinges at the top and bottom of each column have been modelled to incorporate P-M-M interaction.
- The possibility of non-linear behaviour of the floor diaphragm adjacent to the north and south walls, and beam lines 2 and 3 has been modelled.
- The Rayleigh damping coefficients have been slightly adjusted so that an appropriate level of damping has been assigned to the vertical vibration of the floors.
- The ground motions recorded from the CBGS and CCCC sites have been run sequentially for both the September and February events to investigate whether possible damage from the first event influenced the results of analyses during the February earthquake.

The results of the analyses highlighted a number of effects. Firstly it supported the major findings of the previous analyses reported previously, that is:

1. During the September event it was most likely that one or more floor connections to the north wall failed.

Secondly, then inclusion of the additional modelling features listed above supported the assumptions made in the first (DBH) series of analyses:

1. The building would have collapsed in the February event whether or not there had been damage incurred in the previous earthquakes.

### 1. <u>Introduction</u>

Compusoft Engineering Limited was engaged by the Canterbury Earthquakes Royal Commission as part of the NLTHA Expert Panel to undertake further non-linear seismic analyses of the CTV Building. These analyses are additional to those undertaken for StructureSmith and the Department of Building and Housing that were detailed within the Compusoft report titled 'CTV Non-linear Seismic Analysis Report', reference 11033-00. It is the intent that the analyses outlined within this report further enhance the understanding of the CTV performance during the 4th September 2010 Darfield earthquake, and the February 2011 Lyttelton aftershock.

The non-linear analyses outlined in this report are intended to;

- Assist with the identification of the probable sequence of failure.
- Report displacement and storey drift demands, identifying the onset and progression of damage throughout the structure.
- Monitor and report seismic demands on critical structural elements.

The model used for all analyses have been based on building geometry, record structural drawings (Design Engineer 1986), material tests (Hyland 2011), along with published guidance on the hysteretic behaviour of detailing present within the CTV building.

# 2. <u>Building description</u>

The CTV building was a 6 storey structure of reinforced concrete construction with plan dimensions of approximately 31 m by 23 m. An overall impression of the complete structure is shown in Figure 1. Construction consisted of 200 mm thick in-situ composite concrete Hi-Bond floors supported by precast concrete half-beams, shell beams and in-situ concrete columns. A lightweight roof was supported from concrete columns that cantilever above the level 6 floor plate. At the north of the building a series of 300 mm thick reinforced concrete walls were used to support a stair and lift core that projects two storeys above the upper floor plate. A 400 mm thick reinforced concrete coupled shear wall system was situated on the south face of the building. These walls were considered to form the primary seismic resisting Frame action was engaged through stiffness compatibility with the walls and system. contributed to the overall lateral resistance of the structure, particularly the torsional resistance. Figure 2 below indicates the reinforced concrete framing and wall elements that were present (note that the model is presented with north oriented to the right). Foundations comprised pads supporting the internal columns, with a series of in-situ concrete inverted 'tee' beams supporting the perimeter columns and walls as shown in Figure 3. Inter-storey height was typically 3.24 m with 3.70 m for the bottom storey (3.825 m to top of foundations).

The lower 3 levels of the western perimeter frame were in-filled with reinforced concrete masonry panels. An additional feature was a series of precast concrete spandrel panels that were present on the north, east, and south perimeter frames.

Terminology used to describe floor levels within this report has been selected to match that used in the record structural drawings and ongoing investigation reports, with ground floor referred to as level 1, and the level 1 columns spanning between levels 1 and 2.

Figure 4 presents the building grid system used in both the original design and the analysis model.




Figure 1: Overall view of the CTV structural model (viewed from SW & SE respectively)




Figure 2: CTV structural model viewed from the east (slabs omitted for clarity)






Figure 3: CTV foundation arrangement viewed from the south-west.





# 3. <u>Analysis Procedure Overview</u>

A three dimensional model of the building was formed using the SAP2000 Advanced (v14.2.5, CSI Berkeley 2011) finite element program. This model was used to evaluate the seismic actions using non-linear pushover, and non-linear time history methods in accordance with accepted good practice, and recent advances in the understanding of the seismic performance of structures.

As requested by Royal Commission NTHA panel the analysis of the CTV building has been conducted based on the assumption that the only structural elements that resist seismic actions are the reinforced concrete frames and shear walls. Masonry infill panels and precast concrete spandrel elements are assumed to be effectively isolated such that they cannot influence the seismic response and performance of the building.

#### 3.1. <u>Alterations Made from Previous Analysis Model</u>

The analysis model has been developed from the original analysis model (denoted *Model A*) developed for use in the CTV Building non-linear analyses undertaken for the DBH, the results of which are documented in the Compusoft report titled 'CTV Building Non-Linear Seismic Analysis Report'. Changes/alterations made to the previous Model A include the following;

- Interacting M-M Hinges have been replaced with interacting P-M-M hinges.
- Axial release added to roof purlin.
- Non-linear floor elements included (adjacent to beam lines only).
- Damping parameters have been revised for the Lyttelton analysis runs.
- Non-linear strength and stiffness degradation of the beam column joints has been incorporated into the model.
- Slab stiffness has been revised.
- Minor floor mesh refinements.
- Changes to the concrete strength and corresponding stiffness parameters.
- Adjustment to non-linear link and elastic element stiffness to account for concrete material property changes.

- Analysis run times have been amended.
- Some Lyttelton analyses have been undertaken considering the damaged state present at the end of the Darfield earthquake.
- Inclusion of additional ground motion record (REHS) for the Lyttelton event.

#### 3.2. <u>Analysis Procedure</u>

The overall seismic analysis procedure for the CTV building consisted several different tasks as summarised below.

#### Non-linear static (Pushover) analyses

Non-linear static pushover analyses of the structure were undertaken for the two primary directions starting from the end state of a gravity analysis. The purpose of these analyses was to aid understanding of the non-linear performance of the structure, and to partially verify assumptions of the adopted analysis parameters.

#### Non-linear time history analyses for the Darfield event

Non-linear time history were undertaken using the CBGS and CCCC station records of the Darfield event.

#### Non-linear time history analyses for the Lyttelton event

Two separate sets of non-linear time history analyses were undertaken for the Lyttelton event.

Non-linear time history analyses assuming no pre-existing damage were conducted using four records of the Lyttelton event, namely CBGS, CCCC, CHHC, and REHS.

Two further time history analyses were undertaken to quantify and assess the effect of damage that occurred during the Darfield event on the response of the structure during the Lyttelton event. These analyses used the condition of the CTV building at the end of the Darfield event (CBGS and CCCC analyses) as the starting condition for the Lyttelton event as indicated in Figure 5. For these analyses the CBGS and CCCC records were examined.




Figure 5: Time history analysis sequence

# 4. <u>Material Properties</u>

#### 4.1. <u>Concrete</u>

The mean in-situ unconfined compressive strengths of the concrete elements have been evaluated via NZSEE guidelines (NZSEE 2006). In this the mean strength of in-situ concrete can be taken as 1.5 times the specified lower characteristic design strength. The elastic stiffness of the concrete has been derived following the provisions of the New Zealand Concrete Structures Standard (NZS 3101 2006, Clause 5.2.3) as below:

$$E_c = 3320\sqrt{f_c'} + 6900 \,(MPa)$$


Where  $f'_{c}$  is taken as the mean in-situ unconfined strength of concrete (in MPa).

Table 1 below presents the key input parameters used for the definition of concrete materials.

Material	f <sub>c</sub> ' (MPa) Specified	f <sub>c</sub> <sup>•</sup> (MPa) Adopted	E <sub>cu</sub>	E <sub>c</sub> (GPa)
PC Beams	25	37.5	0.00825	27.2
Ground beams	20	30	-NA-	25.1
Columns L1 - L2	35	52.5	0.0065	31.0
Columns L2- L3	30	45	0.0075	29.2
Columns L3- Roof	25	37.5	0.00825	27.2
Floor Slabs	loor Slabs 25		0.00825	27.2
Shear Walls	25	37.5	0.00825	27.2

Table 1: Unconfined concrete stress-stain parameters

Definition of the stress-strain curve for unconfined concrete has been based on the model proposed by Karthik and Mander (Karthik and Mander 2011). The strain at peak stress ( $\varepsilon_0$ ) was taken as 0.002 throughout. The nonlinear stress-strain behaviour of unconfined concrete materials is presented in Figure 6 below.



**Figure 6: Concrete stress-strain curve** 

## 4.2. <u>Reinforcement</u>

Reinforcing steel stress-strain properties have been determined from testing of materials extracted from the as-built structure (Hyland 2011). Where no test data is available, material properties have been adopted which are consistent with the period in which the structure was constructed (Andriono and R. Park 1986). Table 2 below presents the key input parameters used for the definition of reinforcing materials. The nonlinear stress-strain behaviour of the reinforcing materials is presented in Figure 7 below.

Grade	Es (GPa)	fy (MPa)	ε <sub>sh</sub>	ε <sub>su</sub>	fu (MPa)		
G275	205	321.3	0.0220	0.202	451.0		
G380	205	448 <sup>1</sup>	0.0097	0.168 <sup>1</sup>	603 <sup>1</sup>		
664 Mesh	205	615 <sup>1</sup>	0.01	0.0421	665 <sup>1</sup>		

 Table 2: Reinforcing steel stress-strain parameters.

Notes: 1. Mean values obtained via testing (Hyland 2011)




Figure 7: Reinforcing steel stress-strain curve



## 5. <u>Structural Elements</u>

#### 5.1. <u>Soil Structure Interaction</u>

In order to incorporate the potential lift-off of foundation elements in the model, non-linear link elements have been incorporated that represent the gapping behaviour of the foundations. Soil stiffness was considered to behave in a linear manner for compressive strains, with applied soil stiffness based on values provided by Tonkin and Taylor for the probable soil conditions at the site (Sinclair 2011).

It is expected that modelling the effects of any period shift due to foundation flexibility through gapping would outweigh the potential benefits of modelling the plastic behaviour of the soil (Carr 1994). No allowance was made for any suction that may be present between the soil and underside of the foundation beams. Table 3 and Figure 8 present the soil stiffness and foundation designation used in the analysis, with additional information presented in Appendix C. Based upon post earthquake inspections of the site it has been considered that the level of liquefaction observed would not have had a significantly adverse affect on the performance of the building (Sinclair 2011), and as such the effects of liquefaction have not been considered.

### 5.2. <u>Foundation Elements</u>

The foundation system consists of a series of large reinforced concrete pads and flanged ground beams. The pads are modelled using shell objects with suitable thickness. The ground beams are typically modelled as an assemblage of shell objects to form the overall section and provide the necessary bearing area. The Effect of backfill present on top of the foundations has been considered assuming that only the soil contained within vertical planes bounding the foundation width is able to be mobilised, and has a soil density of  $18 \text{ kN/m}^3$ .

July 2012

Foundation Element	Compressive Stiffness (MN/m <sup>3</sup> )
1	122.7
1a	130.89
1b	65.98
2	85.4
2a	53.14
3	117.22
3a	78.59
4	159.69
4a	73.94
5	104.35
6	185.42

# **Table 3: Expected soil stiffness**




Figure 8: CTV foundation element location plan (Design Engineer 1986)

# 5.3. <u>Reinforced Concrete Frames</u>

Reinforced concrete frames have been incorporated in the analysis model using elastically responding frame elements to represent the beam and column members, and discrete non-linear elements to account for non-linear behaviour of beams, columns, and beam-column joints. The implementation of these elements are all discussed in the following sections.

#### 5.3.1. <u>Beams and beam hinges</u>

To account for the effects of concrete cracking, the effective elastic stiffness of the reinforced concrete beam sections has been determined based upon the moment-curvature relationship (Priestley et al. 2007) as below:

$$EI_{eff} = \frac{M_Y}{\phi'_Y}$$

where ' $M_y$ ' is the first yield bending moment, and ' $\phi_y$ ' is the curvature at first yield using material strengths as per Section 4, member geometry and reinforcement as specified in the record drawings. Table 4 presents the stiffness modifiers used for a selection of beams.

Structural Component	Effective Cracked Section Property, I				
GL C Core Ground Beam (rect)	$0.64 I_g$				
GL C/D Core Ground Beam (rect)	$0.25 I_g$				
GL D/E Core Ground Beam (rect)	0.39 <i>I</i> <sub>g</sub>				
GL 1 2m Ground Beam (tee)	0.31-0.39 <i>I</i> g				
GL 3 Ground Beam (rect)	0.22-0.49 I <sub>g</sub>				
Typical 550x400 Beam (tee)	0.47 Ig				
Typical 550x960 Beam (L)	0.17 I <sub>g</sub>				

 Table 4: Stiffness modifiers for elastically responding beam elements

Beam hinges are incorporated in the analysis model as discrete non linear link elements located where inelastic demand is expected to occur. This is taken to be at beam ends.

The adopted beam plastic hinge length  $(L_p)$  considers strain penetration  $(L_{sp})$  into the beamcolumn joint zone and has been determined using the following relationship (Priestley et al. 2007):

$$L_p = kL_c + L_{sp} > 2L_{sp}$$

where,

$$k = 0.2 \left(\frac{f_u}{f_y} - 1\right) \le 0.08$$

$$L_{sp} = 0.022 f_{ye} d_b$$

and  $L_c$  is the length between the critical section and the point of contra-flexure in the member under consideration.

The nonlinear moment vs rotation behaviour of the beam hinges has been defined considering a multilinear backbone curve. The backbone curve for each hinge was determined via moment-curvature analysis of the section including the contribution of the slab where applicable. It should be noted that it has been assumed for analysis purposes that beam hinge formation is not limited by the capacity of bar anchorages. A Takeda hysteresis model (Takeda et al. 1970) was used to consider the degradation of hinge stiffness under cyclic loading. Figure 9 below presents the discretised moment curvature backbone relationship for an example beam hinge along with the actual hinge moment curvature relationship.

For all precast beams, anchorage of positive (bottom) reinforcement occurs via hooks into the beam-column joint zone which can be seen in Figure 10 and Figure 11 below. Top steel anchorage in exterior beam column joints is via hooked bars similar to the typical bottom steel anchorage (as seen in Figure 10). Physical evidence has indicated that the positive reinforcement of the beam along gridline 4 between grids B and C was not effectively anchored into the wall on grid C at levels 3 and 4 (Hyland 2011). To reflect this finding no positive moment capacity has been provided in the model at these locations <sup>1</sup>.

<sup>&</sup>lt;sup>1</sup> Note that post analyses it has been confirmed that in addition to levels 3 and 4, beam bottom steel (between grids B and C) was not effectively anchored at levels 1, 5, and 6 into the wall at grid C




Figure 9: Typical moment-curvature relationship for beam hinges




Figure 10: Reinforcement anchorage in Grid A beam column joint zone (Design Engineer 1986)




Figure 11: Typical bottom reinforcement anchorage in interior beam column joint zone (Design Engineer 1986)

# 5.3.2. <u>Columns and column hinges</u>

To account for the effect of concrete cracking on the flexural stiffness of the linearly responding frame elements stiffness modifier have been assigned. The stiffness modifiers have been determined in accordance with the New Zealand Concrete Structures Standard (NZS 3101 2006, Section 8.6.3) considering a weighted average of stiffness over the column height.

Figure 12 below presents the effective stiffness relationships used for the columns in the analysis model, with the effective stiffness properties presented in the New Zealand Concrete Structures Standard (NZS 3101 2006, Table C6.6) shown for comparison.




Figure 12: Effective column stiffness relationship.

July 2012

		L1			L2	r		L3			L4	1		L5	T
Grid Ref.	N* <sub>G+Qu</sub> (kN)	I <sub>cr</sub>	I <sub>eff</sub>	N* <sub>G+Qu</sub> (kN)	<b>I</b> cr	I <sub>eff</sub>	N* <sub>G+Qu</sub> (kN)	<b>I</b> cr	I <sub>eff</sub>	N* <sub>G+Qu</sub> (kN)	I <sub>cr</sub>	I <sub>eff</sub>	N* <sub>G+Qu</sub> (kN)	I <sub>cr</sub>	I <sub>eff</sub>
F1	1012	0.41	0.77	807	0.39	0.74	613	0.36	0.71	407	0.34	0.67	201	0.28	0.6
C1	1308	0.44	0.8	1035	0.42	0.78	805	0.38	0.74	544	0.35	0.69	281	0.31	0.64
A/B1	890	0.4	0.75	698	0.38	0.72	544	0.35	0.69	369	0.33	0.66	195	0.29	0.61
A1	241	0.25	0.73	174	0.24	0.71	130	0.24	0.69	88	0.22	0.67	49	0.21	0.66
F2	1194	0.43	0.79	947	0.41	0.77	723	0.37	0.72	482	0.34	0.68	240	0.29	0.62
E2	1429	0.45	0.81	1128	0.42	0.79	878	0.39	0.76	574	0.35	0.69	270	0.31	0.64
D2	1734	0.46	0.85	1372	0.43	0.81	1070	0.39	0.78	703	0.37	0.72	335	0.32	0.65
C2	1802	0.46	0.86	1430	0.43	0.82	1127	0.39	0.78	759	0.37	0.73	390	0.33	0.66
B2	1569	0.46	0.83	1244	0.43	0.8	984	0.39	0.77	655	0.36	0.71	344	0.32	0.65
A2	689	0.34	0.79	508	0.32	0.76	427	0.31	0.75	254	0.27	0.72	135	0.24	0.73
F3	1183	0.43	0.79	933	0.41	0.77	715	0.37	0.73	476	0.34	0.68	237	0.29	0.62
E3	1427	0.45	0.81	1118	0.42	0.78	873	0.39	0.76	570	0.35	0.69	268	0.31	0.64
D3	1734	0.46	0.85	1364	0.43	0.81	1064	0.39	0.78	698	0.37	0.72	332	0.32	0.65
C3	1752	0.46	0.85	1391	0.43	0.81	1096	0.39	0.78	737	0.37	0.73	377	0.33	0.65
B3	1564	0.46	0.83	1240	0.43	0.8	980	0.39	0.77	660	0.36	0.71	342	0.32	0.65
A3	689	0.34	0.79	508	0.32	0.76	427	0.31	0.75	254	0.27	0.72	135	0.24	0.73
F4	970	0.41	0.76	777	0.39	0.74	588	0.36	0.7	391	0.34	0.67	194	0.28	0.6
D/E4	1394	0.14	0.7	1062	0.42	0.78	833	0.38	0.75	560	0.35	0.69	275	0.31	0.64
B4	1095	0.43	0.78	860	0.4	0.75	668	0.36	0.71	450	0.34	0.68	236	0.3	0.62
A4	357	0.28	0.75	267	0.27	0.73	188	0.25	0.71	120	0.23	0.68	71	0.22	0.68

 Table 5: Column stiffnesses used in the analysis model

Flexural hinging is anticipated to occur in the columns immediately adjacent to the beam face. To account for this in the analysis model non-linear elements have been incorporated that includes consideration of axial-moment (commonly termed P-M-M) interaction and strength and stiffness degradation. The performance of these hinges is presented in Appendix B.

Figure 13 below indicates the typical reinforcement arrangement for the typical 400 mm diameter circular columns and the 400 mm x 300 mm columns located on grid A.




Figure 13: Typical column reinforcement. (Design Engineer 1986)

Examination of the eccentric column connection between the top of the column located at grid 4 D/E (referenced as C18 on the structural drawings) and the north core wall as seen in Figure 14, has indicated that the detailing present is not capable of transferring the significant axial

forces that would result from moderate seismic demands. As such, this connection has not been included in the analysis model, with column C18 assumed to behave as a cantilever above Level 6.





Figure 14: Column at GL 4 D/E (C18) to wall connection detailing at roof level (Design Engineer 1986)

#### 5.3.3. <u>Beam-Column Joints</u>

Non-linear behaviour of the beam-column joints in the CTV Building has been incorporated in the model by use of a non-linear moment-rotation spring located at the node at the intersection of the beam and column elements. This spring was calibrated to represent the expected shear stress-shear strain response of deficient concrete beam-column joints. The strength of beam column joints was determined based on procedures commonly used in New Zealand practice (NZSEE 2006), while the non-linear backbone curve defining response of the spring has been determined based on review of relevant literature. The definition of this backbone curve is summarised in Table 6, and an example joint response backbone curve can be seen in Figure 15. Table 7 provides summary details of data used to define the response of each beam-column joint in the CTV Building. Detailed discussion of the beam-column joint implementation can be found in Appendix C.



## Table 6: Definition of beam-column joint response backbone curve

Figure 15: Joint response backbone curve for joint at grid A2, level 3 (exterior E/W, interior N/S)

Location				North/South			
(grid, level)	axial stress (MPa)	Туре	$\mathbf{V}_{\mathbf{j}\mathbf{h}}$	$M_j/V_{jh}$	Туре	$\mathbf{V}_{\mathbf{j}\mathbf{h}}$	$M_{j}/V_{jh}$
F1, L2	-3.5	Ext	873	0.584	Ext	873	0.584
C1, L2	-4.5	Int	1842	0.584	-	-	-
B1, L2	-4.4	Int	1282	0.622	-	-	-
A1, L2	-1.5	Ext	371	0.628	Ext	310	0.584
F2, L2	-3.9	Ext	950	0.363	Int	1809	0.584
E2, L2	-7.1	Int	1437	0.599	-	-	-
D2, L2	-8.6	Int	1518	0.587	-	-	-
C2, L2	-8.9	Int	1537	0.587	-	-	-
B2, L2	-7.8	Int	1476	0.597	-	-	-
A2, L2	-4.2	Ext	486	0.352	Int	803	0.584
F2, L2	-3.9	Ext	950	0.363	Int	1809	0.584
E2, L2	-7.1	Int	1437	0.599		-	-
D2, L2	-8.6	Int	1518	0.587	-	-	-
C2, L2	-8.9	Int	1537	0.587	-	-	-
B2, L2	-7.8	Int	1476	0.597	-	-	-
A2, L2	-4.2	Ext	486	0.352	Int	803	0.584
F1, L2	-3.5	Ext	873	0.584	Ext	873	0.584
D/E4, L2	-6.6	Int	1414	0.586	-	-	-
B4, L2	-5.4	Int	1343	0.601	-	-	-
A4, L2	-2.2	Ext	406	0.600	Ext	344	0.584
F1, L3	-2.7	Ext	809	0.583	Ext	809	0.583
C1, L3	-3.5	Int	1753	0.583	-	-	-
B1, L3	-3.4	Int	1222	0.620	-	-	-
A1, L3	-1.1	Ext	353	0.626	Ext	293	0.583
F2, L3	-3.0	Ext	878	0.363	Int	1720	0.583

Table 7: Summary details of beam-column joints

Location	Column	East/West				North/South			
(grid, level)	axial stress (MPa)	Туре	$\mathbf{V_{jh}}$	${ m M_j/V_{jh}}$	Туре	$\mathbf{V_{jh}}$	$M_{j}/V_{jh}$		
E2, L3	-5.5	Int	1349	0.598	-	-	-		
D2, L3	-6.7	Int	1417	0.585	-	-	-		
C2, L3	-7.0	Int	1437	0.585	-	-	-		
B2, L3	-6.2	Int	1387	0.596	-	-	-		
A2, L3	-3.6	Ext	460	0.352	Int	772	0.583		
F2, L3	-3.0	Ext	878	0.363	Int	1720	0.583		
E2, L3	-5.5	Int	1349	0.598	-	-	-		
D2, L3	-6.7	Int	1417	0.585	-	-	-		
C2, L3	-7.0	Int	1437	0.585	-	-	-		
B2, L3	-6.2	Int	1387	0.596	-	-	-		
A2, L3	-3.6	Ext	460	0.352	Int	772	0.583		
F1, L3	-2.7	Ext	809	0.583	Ext	809	0.583		
D/E4, L3	-5.2	Int	1333	0.584	-	-	-		
B4, L3	-4.2	Int	1271	0.600	-	-	-		
A4, L3	-1.6	Ext	376	0.598	Ext	315	0.583		
F1, L4	-1.8	Ext	734	0.583	Ext	734	0.583		
C1, L4	-2.4	Int	1646	0.583	-	-	-		
B1, L4	-2.3	Int	1150	0.620	-	-	-		
A1, L4	-0.7	Ext	335	0.626	Ext	276	0.583		
F2, L4	-2.0	Ext	793	0.363	Int	1619	0.583		
E2, L4	-3.6	Int	1234	0.598	-	-	-		
D2, L4	-4.4	Int	1284	0.585	-	-	-		
C2, L4	-4.7	Int	1305	0.585	-	-	-		
B2, L4	-4.1	Int	1266	0.596	-	-	-		
A2, L4	-2.1	Ext	401	0.352	Int	704	0.583		

Table 7 (cont.): Summary	details of beam-column joints
Tuble / (conte). Summary	uctums of beam column joints

Location Column (grid, axial stress			East/West		North/South		
(grid, level)	axial stress (MPa)	Туре	$\mathbf{V_{jh}}$	${ m M_j/V_{jh}}$	Туре	$\mathbf{V}_{\mathbf{j}\mathbf{h}}$	$M_{j}/V_{jh}$
F2, L4	-2.0	Ext	793	0.363	Int	1619	0.583
E2, L4	-3.6	Int	1234	0.598	-	-	-
D2, L4	-4.4	Int	1284	0.585	-	-	-
C2, L4	-4.7	Int	1305	0.585	-	-	-
B2, L4	-4.1	Int	1266	0.596	-	-	-
A2, L4	-2.1	Ext	401	0.352	Int	704	0.583
F1, L4	-1.8	Ext	734	0.583	Ext	734	0.583
D/E4, L4	-3.5	Int	1228	0.584	-	-	-
B4, L4	-2.8	Int	1184	0.600	-	-	-
A4, L4	-1.0	Ext	349	0.598	Ext	289	0.583
F1, L5	-0.9	Ext	651	0.583	Ext	651	0.583
C1, L5	-1.2	Int	1530	0.583	-	-	-
B1, L5	-1.2	Int	1073	0.620	-	-	-
A1, L5	-0.4	Ext	317	0.626	Ext	258	0.583
F2, L5	-1.0	Ext	698	0.363	Int	1511	0.583
E2, L5	-1.7	Int	1107	0.598	-	-	-
D2, L5	-2.1	Int	1135	0.585	-	-	-
C2, L5	-2.4	Int	1158	0.585	-	-	-
B2, L5	-2.2	Int	1139	0.596	-	-	-
A2, L5	-1.1	Ext	355	0.352	Int	652	0.583
F2, L5	-1.0	Ext	698	0.363	Int	1511	0.583
E2, L5	-1.7	Int	1107	0.598	-	-	-
D2, L5	-2.1	Int	1135	0.585	-	-	-
C2, L5	-2.4	Int	1158	0.585	-	-	-
B2, L5	-2.2	Int	1139	0.596	-	-	-

Table 7 (cont.): Summary details of beam-column joints

Location	Column	East/West			North/South			
(grid, level)	axial stress (MPa)	Туре	$V_{jh}$	$M_{j}/V_{jh}$	Туре	$\mathbf{V}_{\mathbf{j}\mathbf{h}}$	$M_{j}/V_{jh}$	
A2, L5	-1.1	Ext	355	0.352	Int	652	0.583	
F1, L5	-0.9	Ext	651	0.583	Ext	651	0.583	
D/E4, L5	-1.7	Int	1109	0.584	-	-	-	
B4, L5	-1.5	Int	1091	0.600	-	-	-	
A4, L5	-0.6	Ext	328	0.598	Ext	268	0.583	
F1, L6	-0.1	Ext	566	0.583	Ext	566	0.583	
C1, L6	-0.1	Int	1406	0.583	-	-	-	
B1, L6	-0.1	Int	989	0.620	-	-	-	
A1, L6	-0.1	Ext	301	0.626	Ext	243	0.583	
F2, L6	-0.1	Ext	596	0.363	Int	1404	0.583	
E2, L6	-0.1	Int	990	0.598	-	-	-	
D2, L6	-0.1	Int	991	0.585	-	-	-	
C2, L6	-0.1	Int	991	0.585	-	-	-	
B2, L6	-0.1	Int	990	0.596	-	-	-	
A2, L6	-0.2	Ext	305	0.352	Int	599	0.583	
F2, L6	-0.1	Ext	596	0.363	Int	1404	0.583	
E2, L6	-0.1	Int	990	0.598	-	-	-	
D2, L6	-0.1	Int	991	0.585	-	-	-	
C2, L6	-0.1	Int	991	0.585	-	-	-	
B2, L6	-0.1	Int	990	0.596	-	-	-	
A2, L6	-0.2	Ext	305	0.352	Int	599	0.583	
F1, L6	-0.1	Ext	566	0.583	Ext	566	0.583	
D/E4, L6	-0.5	Int	1020	0.584	-	-	-	
B4, L6	-0.1	Int	990	0.600	-	-	-	
A4, L6	-0.1	Ext	302	0.598	Ext	244	0.583	

Table 7 (cont.): Summary details of beam-column joints

### 5.4. <u>Reinforced Concrete Shear Walls</u>

The CTV Building contains two reinforced concrete shear wall systems. Each of these systems was modelled using non-linear layered shell elements, which incorporate inelastic material effects at a fibre level. Where significant inelastic demands were not expected, the wall was modelled using linear elastic shell elements with stiffness modifiers determined from moment curvature analyses similar to those described in Section 5.3.2. The stiffness modifiers determined via these analyses along with those determined following the recommendations presented in the New Zealand Concrete Structures Standard (NZS 3101 2006, Table C6.6) are presented in Figure 16 below based on the gravity axial load.




Figure 16: Effective wall stiffness relationship

Confining reinforcement was detailed for the boundary regions of all reinforced concrete shear walls in the lower two storeys. It was considered appropriate to model the non-linear stress strain behaviour of the concrete fibres in these regions based on the Mander confined concrete model (Mander et al. 1988). The concrete material in the layered shell element was assumed to be unconfined between boundary regions and for wall elements above the level 3 floor plate.

Diagonally reinforced coupling beams connected the two portions of south shear wall as seen in Figure 17 below. The typical span to depth aspect ratio of the coupling beams was 0.76 but varied from 0.55 at the bottom to 1.2 at the top of the wall. Modelling of the diagonally reinforced coupling beams has been based upon the approach documented in Appendix A, with non linear links substituted for the fibre elements to reduce computation time.




Figure 17: South shear wall typical coupling beam reinforcement arrangement (Design Engineer 1986)

## 5.5. <u>Floors</u>

Review of the lateral load paths has indicated that diaphragm integrity at the interface with shear walls may have been an important consideration in the determination of the seismic performance of the structure. As such, the flexibility of each floor level has been modelled with in-plane stiffness based on the average thickness of the concrete slab (173 mm). For the purposes of the analysis the stiffness of the slab elements has been taken as  $0.32A_{gross}$  for inplane actions. In order to capture potential inelastic demand in the slabs at the support locations, non-linear layered shells have been used adjacent to beam lines. Shell properties have been based upon the reinforcement present at the beam face assuming no contribution from the metal decking. Linear elastic shells have been used to represent the remainder of the floor slabs. Diaphragm actions have been monitored at interfaces with shear walls.

The floor diaphragm connections to the north core lift shaft walls on grids D and D/E have been identified as an area of potential connection failure. As a consequence of a lack of specific tie reinforcement it was assumed that there is no tensile or gravity connection between the slab and these walls at levels 2 and 3. At levels 4 to 6 a retrofitted steel angle tie (or 'drag bar') provided limited tensile and gravity connection to the slab at the tips of walls D and D/E. Multi-linear links have been used to provide a 'fuse' that will transfer the expected upper bound tensile capacity of the retrofitted connection only with no limitation on the compressive load transfer capability. Nominal tensile connection capacities for the drag bar and its connections, and the corresponding ultimate displacements have been provided by Hyland Fatigue & Earthquake Engineering and StructureSmith. These are listed in Table 8 below.

Wall	Level	Tensile Capacity (kN)	Displacement at Disconnection (mm)	Compressive Capacity (kN)
D	2	0	0	Not limited
	3	0	0	Not limited
	4	320	2.3	Not limited
	5	420	2.4	Not limited
	6	603	2.6	Not limited
D/E	2	0	0	Not limited
	3	0	0	Not limited
	4	403	2.8	Not limited
	5	503	3.0	Not limited
	6	540	3.0	Not limited

 Table 8: Modelled diaphragm (drag bar) connection capacities

Floor diaphragm connections to the other north core walls on grids 5, C and C/D, and to the south wall on grid 1 were assumed to remain connected for the purposes of the seismic analysis. Maximum diaphragm actions at these locations are reported at these locations in Sections 9 and 10 for assessment by others.

For out-of-plane demands (i.e. plate action) the floors have been considered to have stiffness corresponding to  $EI_{Effective} = 1872 \text{ kNm}^2/\text{m}$  for the remaining slab (as recommended by Mander 2012, June 14) with the effective stiffness adjacent to beam lines and implicitly considered by the non-linear layered shell element. In the determination of the slab flexural stiffness at beam faces the contribution of the metal decking has been ignored as the decking would not have been effectively anchored at the beam support where the positive (sagging) flexural demands are greatest.



### 6. <u>Loadings</u>

#### 6.1. <u>Gravity Loadings</u>

For combination with seismic loads a gravity load combination has been developed following the requirements of the New Zealand Design Actions Standard (AS/NZS 1170.0 2002, section 4). This gravity load combination also formed the basis for consideration of P-delta effects in the seismic analyses. In this combination live load allowances have been combined with the initial staged dead load analysis as a separate loading step as follows,

$$E_d = G + \sum \Psi_{C,i} \Psi_{A,i} Q_i$$

Taking 'G' as the sum of all dead type loadings incorporating element self weights, plus any superimposed dead load (SDL) allowances that are required to be considered, and ' $\Sigma \Psi_{C,i} \Psi_{A,i} Q_i$ ' given as the sum product of all individual components of imposed loading as presented in Table 9 below<sup>1</sup>.

Gravity load component	Load allowance (kPa)	Ψc	ΨΑ
DL	Self weight	1.0	1.0
SDL	0.55	1.0	1.0
Plant LL	5.0	0.6	1.0
Toilet LL	2.0	0.4	1.0
Office LL	3.0	0.4	1.0
Roof LL	0.25	0	1.0

**Table 9: Basic load pattern definitions** 

Note that the use of  $\psi_A$  equal to 1.0 for office live load could slightly over-estimate column compression demand in lower levels of the structure by between 2 and 7 percent. For the purpose of determining gravity actions in the upper levels of the structure it is believed that a  $\psi_A$  equal to 1.0 suitably represents the gravity actions.

<sup>&</sup>lt;sup>1</sup> It is noted that the recent third amendment to NZS 1170.0 corrected the load combinations for earthquake loading so that the earthquake combination factor  $\psi_E$  is used to factor the live load component rather than the combination factor  $\psi_C$ . This change would have only a minor effect on the calculated gravity loads, resulting in the toilet and office live load factor listed in Table 9 reducing from 0.4 to 0.3.

It should be noted that level 3 and the east side of level 6 of the CTV structure are understood to have been untenanted at the time of the earthquake. No live load allowance has been included at these locations.

Table 10 below presents the global base reaction reported at the model origin (i.e.  $\{x,y,z\}=\{0,0,0\}c=$  Level 1 at grid reference F/1) for each load type arising from a linear analysis.

FZ (kN)	MX (kNm)	MY (kNm)
35458	492755	482464
4647	65608	59200
364	5014	8951
135	2220	3307
7437	119468	87223
0	0	0
	4647 364 135 7437	4647         65608           364         5014           135         2220           7437         119468

Table 10: Global base reactions for basic load patterns (linear)

## 6.2. <u>Dynamic Mass</u>

The dynamic mass used in the seismic analyses was determined following the provisions of the New Zealand Design Actions Standard (NZS 1170.5 2004, clause 4.2) where,

$$W_t = G + \sum \Psi_{E,i} \Psi_{A,i} Q_i$$

taking 'G' based on all dead loads (plus superimposed dead loads), ' $\Sigma \Psi_{c,i} \Psi_{A,i} Q_i$ ' as the sum product of the individual imposed loadings as per Table 11 below.

Gravity load component	Load allowance (kPa)	$\psi_{\rm E}$	ΨA
DL	Self weight	NA	NA
SDL	0.55	NA	NA
Plant LL	5.0	0.6	0.74
Toilet LL	2.0	0.3	0.5
Office LL	3.0	0.3	0.5
Roof LL	0.25	0.0	0.0

 Table 11: Imposed loading allowances (for derivation of dynamic mass)

Seismic mass associated with the load component 'DL' has been obtained through explicit modelling of the structural elements. All other tributary masses outlined in Table 11 have been incorporated via distributed loads applied to the floor/roof elements in order to accurately proportion mass for slabs and beams etc. Note that as for Section 6.1 no live load has been included in the development of the dynamic mass for the untenanted levels. The distribution of seismic mass in the analysis model is as presented in Figure 18 below.




Figure 18: Seismic mass distribution

# 7. <u>Seismic Analyses</u>

#### 7.1. <u>Modal Analysis</u>

Modal analysis has been carried out considering dynamic mass as outlined in Section 6.2. The results of this analysis are presented in Table 12 below (showing modes with more than 2% mass participating only), with X, Y, and Z representing the north, west, and vertical axes respectively. Note the modal analysis was performed using EI<sub>effective</sub> values for all members in the structure.

Mode	Period (sec)	UX	UY	UZ	∑UX	∑UY	∑UZ	RZ	∑RZ
1	1.33	0.63	0.01	0.00	0.63	0.00	0.00	0.21	0.21
2	1.00	0.00	0.41	0.00	0.63	0.41	0.00	0.01	0.23
3	0.51	0.00	0.25	0.00	0.63	0.66	0.00	0.42	0.65
7	0.28	0.02	0.03	0.00	0.68	0.71	0.00	0.01	0.68
8	0.27	0.06	0.02	0.00	0.74	0.73	0.00	0.00	0.69
13	0.21	0.00	0.02	0.00	0.77	0.78	0.00	0.05	0.76
14	0.19	0.00	0.00	0.28	0.77	0.78	0.28	0.00	0.76
16	0.19	0.00	0.00	0.08	0.77	0.78	0.38	0.00	0.76
78	0.1	0.00	0.00	0.03	0.81	0.81	0.69	0.00	0.78
81	0.1	0.00	0.00	0.04	0.81	0.81	0.73	0.00	0.78
102	0.05	0.04	0.00	0.00	0.87	0.88	0.85	0.02	0.83
104	0.04	0.01	0.04	0.00	0.88	0.92	0.87	0.07	0.90
105	0.04	0.03	0.00	0.00	0.91	0.93	0.87	0.00	0.91
110	0.03	0.00	0.00	0.03	0.96	0.95	0.93	0.00	0.93
112	0.02	0.00	0.00	0.04	0.96	0.95	0.96	0.00	0.93
115	0.02	0.00	0.00	0.03	0.97	0.97	1.00	0.00	0.94

Table 12: Modal participating mass ratios

### 7.2. <u>Non-Linear Static (Pushover) Analysis</u>

In order to gain an initial view of the anticipated seismic performance of the building a nonlinear static analysis (often referred to as a "Pushover") was undertaken for the analysis model. This pushover was used to verify that the finite elements employed for each of the structural mechanisms outlined in Section 0 were performing as expected.

Pushover analyses were undertaken in each of the two orthogonal directions i.e. north/south (N/S) & east/west (E/W) independently. The pushover cases consist of a displacement controlled, force based analysis with the load vector based upon a triangular load distribution, and inertia force applied to each mass degree of freedom in the model. Building centre of mass target displacements of 200 mm and 150 mm were taken for the N/S and E/W directions respectively. These values are approximately equivalent to the current Building Code (DBH 2011) elastic displacement demands based upon the fundamental periods of vibration obtained from section 7.1 and considering subsoil type D, Z=0.30, and  $S_p=1$  as can be seen in Figure 19 below. It was assumed that the level 6 displacement demand is approximately 1.5 times greater than the building centre of mass demand.




Figure 19: Site spectral displacements.

### 7.3. <u>Non-linear Dynamic (Time History) Analysis</u>

Non-linear time history analyses have been undertaken incorporating inelastic behaviour for the analysis model as outlined in Section 3. Two seismic event scenarios are considered in these analyses which are denoted as the '*Darfield*' event, and the '*Lyttelton*' event in this report. The details of these events as obtained from GNS Science (Geonet 2010a, 2011a) are presented in Table 13 below.

Event Name	Reference Number	Local Date & Time	Epicenter Location	Magnitude	Focal Depth
Darfield	3366146	04Sept2010, 0435hrs	43.55°S, 172.17°E	M <sub>L</sub> 7.1	11 km
Lyttelton	3468575	22Feb2011, 1251hrs	43.60°S, 172.71°E	M <sub>L</sub> 6.3	5 km

 Table 13: Seismic event information

## 7.3.1. Analysis Ground Motions

In an attempt to approximate the ground shaking that was experienced at the CTV site for each of the two events, a suite of four acceleration time history records were adopted following the recommendations of Tonkin and Taylor (Sinclair 2011). These were records recorded at other locations in the Christchurch CBD and are presented in Table 14 below. It is expected that the REHS time history record will produce an upper bound response in the performance of the CTV building (Sinclair 2012).

 Table 14: Adopted earthquake record information

Station Name	Station ID	Station Location
Christchurch Cathedral College	CCCC	43.54°S, 172.65°E
Christchurch Hospital	CHHC	43.54°S, 172.63°E
Christchurch Botanic Gardens		
Resthaven	REHS	43.52 S, 172.64 E

The acceleration time histories were obtained from GNS Science (Geonet 2010b, 2011b) and have been processed in order to align the axes of the recorded motions to purely north/south (denoted as component N00E) and east/west (denoted as component N90E) components to coincide with the principle axis of the CTV building. No processing has been undertaken on the vertical components of the records.

Figure 20 through Figure 25 below present the site 5% damped response spectra for the three (processed) components of the Darfield and Lyttelton events respectively. Also presented for reference is the mean of the recorded components and the elastic spectra used for design purposes at the site derived in accordance with New Zealand Standards (NZS 1170.5 2004) considering site subsoil class D, Z = 0.22 (i.e. that applicable for a new building design in Christchurch during February 2011), and  $S_p = 1.0$ .




Figure 20: Darfield N00E 5% damped response spectra (north/south)




Figure 21: Darfield N90E 5% damped response spectra (east/west)




Figure 22: Darfield Vertical 5% damped response spectra




Figure 23: Lyttelton N00E 5% damped response spectra (north/south)




Figure 24: Lyttelton N90E 5% damped response spectra (east/west)




Figure 25: Lyttelton Vertical 5% damped response spectra

The records as supplied by GNS have arbitrary stop and start times that encompass many seconds of very small ground vibration. Incorporation of the entire record into the analysis would add no benefit to the understanding of the structural response or performance, and would only add considerable analysis time. For the purposes of the non linear time history analysis runs, reduced length records have been used to reduce computation times. Record start and finish times have been selected to ensure that all significant shaking is captured by the analysis and are presented in Table 15. All results contained with this document have been presented relative to the adopted start time of each acceleration time history record. Appendix E contains the acceleration time history records used for these analyses.

Acceleration time history records for the Darfield event were much longer in duration than for the Lyttelton event. To reduce analysis time only the CBGS and CCCC record was analysed for Darfield.

Station Name	Event	Start Time (sec)	Finish Time (sec)
Christchurch Botanic Gardens (CBGS)	Darfield	15	55
Christchurch Cathedral College (CCCC)	Darfield	15	55
Christchurch Cathedral College (CCCC)	Lyttelton	15	25
Christchurch Hospital (CHHC)	Lyttelton	15	25
Christchurch Botanic Gardens (CBGS)	Lyttelton	15	25
Resthaven (REHS)	Lyttelton	9.5	19.5

Table 15: Adopted record start and finish times

## 7.3.2. Damping

### Elastic Structural Damping

Elastic damping for the structure has been incorporated in the time history analyses by way of mass ( $\alpha$ ) and stiffness ( $\beta$ ) proportional damping coefficients, commonly referred to as Rayleigh damping. A common criticism of the Rayleigh damping method is that it considers

only the initial stiffness in its determination of level of damping. In order to consider the reduced level of damping appropriate during inelastic cycling of structural elements a tangent stiffness damping model is often considered as being preferable (Priestley et al. 2007). To address this issue, a reduced damping coefficient,  $\zeta^*$ , for the fundamental period has been specified for use in determining the damping coefficients. This adopted method more closely approximates the tangent stiffness approach.

Observed damage of the CTV building after the Darfield event indicated that the ductility demand of the structure was nominal. On this basis, unmodified Rayleigh damping was adopted for Darfield analysis runs. Table 16 below presents the input parameters adopted in determining the Rayleigh damping coefficients for analyses of the Darfield event.

	Period, T (sec)	Damping, ξ*(%)
First	1.33	5
Second	0.05	5

Table 16: Rayleigh damping parameters - Darfield

Using the parameters presented in Table 16 the mass and stiffness proportional damping coefficients are determined as follows:

•	Mass Proportional Coefficient, α	0.4553
•	Stiffness Proportional Coefficient, β	$7.669 \times 10^{-4}$

For the Lyttelton event it was necessary to estimate the building displacement ductility capacity in order to select an appropriate level of damping. From the bi-linearised pushover plot in Figure 34 of Section 8 the approximate ductility capacity of the structure is between 1.4 and 2.1 depending on the direction of demand. For the purpose of the non-linear time history analyses a ductility of 2 was assumed for the structure. As vertical earthquake effects are assumed to influence the performance of the building it has been necessary to ensure that the damping in the vertical modes is realistically represented. For the purposes of this analysis the targeted damping in the vertical modes is 2%. Table 17 below presents the input parameters adopted in determining the Rayleigh damping coefficients for analyses of the Lyttelton event.


	Period, T (sec)	Damping, ξ*(%)
First	1.33	3.3
Second	0.20	2.0

### Table 17: Rayleigh damping parameters - Lyttelton

Using the parameters presented in Table 17 the mass and stiffness proportional damping coefficients are determined as follows:

•	Mass Proportional Coefficient, $\alpha$	0.2899
•	Stiffness Proportional Coefficient, $\beta$	9.795x10 <sup>-4</sup>

Figure 26 below presents a plot of equivalent viscous damping vs structure period obtained using the above coefficients.





### Radiation Damping

It has been considered that the adopted acceleration time histories inherently contain a component of radiation damping and given the uncertainties over the actual site accelerations, and material properties, the incorporation of additional radiation damping is expected to be insignificant and as such has not been incorporated.

## 8. Non-Linear Pushover Results

#### 8.1. <u>Force-Displacement Relationships</u>

Force-displacement plots for the push-over analyses are presented in Figure 27. Displacements have been recorded at a node located at approximately the centre of mass of level 6. Figure 28 and Figure 29 present the base shear components recorded at the top of the foundation beams for each of the primary structural elements.




Figure 27: Force-displacement relationship.

It can be seen from the pushover plots that the building responds to the imposed lateral loading in a non-linear manner. Plot profiles for both the east and west directions are almost identical indicating a similar building response in each of these directions. Initial response of the building in the northward direction is stiffer than in the southward direction, which can be attributed to the differences in the foundation behaviour under the north core for these directions.




Figure 28: Base shear components - east/west direction.




Figure 29: Base shear components - north/south direction.

Components of base shear are similar in each of the directions of loading with the exception of the north core in the north/south direction. As can be seen in Figure 29, more base shear is carried by the core for an applied northward load than for a loading direction toward the south. This is due to the mobilisation of additional gravity load from the beams and slab

along gridline 4 as the southern edge of the core wall webs move upwards with core rotation to the north. These shears provide a restoring force that restrains the wall rotation, requiring higher shears to generate the same centre of mass displacement at level 6.

Pushover analyses have indicated that the response of the building in the east/west direction to be significantly torsional. Figure 30 to Figure 33 present the variation in displacement profile between the approximate centre of mass (at Level 6) and the building perimeter gridlines for each direction under consideration. East/west displacement on gridline 1 is approximately three times greater than that on grid 4, and can be seen in Figure 30 and Figure 31. This is a consequence of the difference in relative stiffness between the north core and the coupled shear wall on grid 1. As the coupled shear wall on gridline 1 yields the torsional response of the building is further exacerbated.

Little torsional behaviour is exhibited through loading in the north/south direction. As can be seen in Figure 32 and Figure 33 there is almost no difference in displacement between grid A and grid F under north/south loading.




Figure 30: Level 6 western pushover displacement profile.




Figure 31: Level 6 eastern pushover displacement profile.




Figure 32: Level 6 northern pushover displacement profile.




Figure 33: Level 6 southern pushover displacement profile.

## 8.2. <u>Building Displacement Ductility Capacity.</u>

Figure 34 presents the pushover plots that have been bi-linearised in order to obtain an estimate on the building displacement ductility capacity. From Figure 34 the ductility capacity can be estimated as being approximately two.




Figure 34: Bi-linear pushover plots

# 9. <u>Non Linear Time History Darfield Results</u>

Results presented are a summary of the analyses only. Additional results can be found in Appendix F and Appendix G. All results are presented for the earthquake acceleration time history recorded at the Christchurch Botanic Gardens (CBGS), and the Christchurch Cathedral College (CCCC) using all three components of the record.

## 9.1.1. Drifts and Displacements

Figure 35 and Figure 36 indicates the north/south storey drifts for the perimeter frames located on grid A, and grid F for CBGS and CCCC.





Figure 35: Frame A north/south storey drifts - Darfield.






Figure 37 and Figure 38 indicates the east/west storey drifts for the perimeter frames located on grid 1, and grid 4 for CBGS and CCCC.




Figure 37: Frame 1 east/west storey drifts - Darfield.




Figure 38: Frame 4 east/west storey drifts - Darfield.

## 9.1.2. Diaphragm Connection Forces.

Table 18 to Table 22 present the diaphragm connection forces acting at each of the north core individual wall interfaces. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.

	North/South Actions					
Level	СВ	GS	CCCC			
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)		
Level 6	963	-807	1069	-790		
Level 5	4 5 624 -421		889	-404		
Level 4	vel 4 487 -529		795	-494		
Level 3	623 -495		941	-609		
Level 2	584	-694	742	-869		

## Table 18: Wall C diaphragm connection forces - Darfield.

## Table 19: Wall C/D diaphragm connection forces - Darfield.

	North/South Actions					
Level	СВ	GS	CCCC			
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)		
Level 6	593	-500	526	-397		
Level 5	548 -495 6		608	-412		
Level 4	vel 4 487 -461 568		568	-574		
Level 3	427	-479	354	-763		
Level 2	677	-577	755	-516		

### Table 20: Wall D diaphragm connection forces - Darfield.

	North/South Actions							
Level	СВ	GS	CCCC					
Level	Maximum Northward (kN)			Maximum Southward (kN)				
Level 6	460	-289	427	-322				
Level 5	evel 5 253 -216		267	-267				
Level 4	230	-237	263	$-320^{1}$				
Level 3	335	0	341	0				
Level 2	335	0	341 0					
	Notes: 1. Tensile limit of connection was exceeded.							

		North/South Actions						
Level	СВ	GS	CC	CC				
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)				
Level 6	463	463 -352		-442				
Level 5	141	-333	212	-485				
Level 4	222	-382	-382 277					
Level 3	476	0 443		0				
Level 2	577	0	452 0					

#### Table 21: Wall D/E diaphragm connection forces - Darfield.

Notes: 1. Tensile limit of connection was exceeded.

#### Table 22: Wall 5 (C to C/D) diaphragm connection forces - Darfield.

	East/West Actions					
Level	СВ	GS	CCCC			
	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)		
Level 6	783	-980	820	-745		
Level 5	576	-666	500	-672		
Level 4	el 4 495 -649		484	-693		
Level 3	413	-606	451	-798		
Level 2	369	-430	566	-508		

It can be seen from Table 20 and Table 21 that diaphragm drag bar disconnections is predicted for the CCCC record only at wall D and D/E for the upper bound connection forces analysed. Note that remaining tie forces are shown to be very close to the upper bound capacity at level 4 for the CBGS record, and level 5 and 6 for the CCCC record, indicating that connection failure may occur at these levels.

Once the diaphragms have disconnected at these wall lines any torsion on the north core must be resisted by a couple between walls C and C/D.

Table 23 and Table 24 present the diaphragm connection actions summarised for the entire north core at each floor level. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.


	East/West Actions						
	CBGS			СССС			
Level	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum In-Plane Moment (kNm)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum In-Plane Moment (kNm)	
Level 6	1075	-1168	7044	1111	-904	6952	
Level 5	962	-841	2566	806	-714	2816	
Level 4	831	-821	2050	851	-663	2176	
Level 3	740	-671	3739	749	-722	5974	
Level 2	451	-463	5351	611	-468	5050	

 Table 23: North core total diaphragm connection forces - Darfield.

 Table 24: North core total diaphragm connection forces - Darfield.

	North/South Actions					
	CBGS		СССС			
Level	Maximum Northward (kN)	Maximum Southward (kN)	Minimum In-Plane Moment (kNm)	Maximum Northward (kN)	Maximum Southward (kN)	Minimum In-Plane Moment (kNm)
Level 6	1424	-831	-8068	1434	-919	-7063
Level 5	1521	-1105	-4796	1699	-1316	-5548
Level 4	1180	-1061	-4286	1835	-1079	-2893
Level 3	1883	-796	-2107	2000	-1304	-2068
Level 2	1115	-1119	-2616	959	-1061	-2915

Table 25 and Table 26 present the actions acting along the slab interface along gridline 4 between grids C and C/D. Figure 39 indicates (in dark blue) the location of slab elements used to determine the actions presented. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.



### Figure 39: Slab 4 C-C/D section cut line.

Table 25: Slab	4 C to C/D	diaphragm	E/W actio	ons - Darfield

\_

	East/West Actions					
	CBGS			сссс		
Level	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum In-Plane Moment (kNm)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum In-Plane Moment (kNm)
Level 6	1008	-976	5102	766	-935	3509
Level 5	683	-828	3423	597	-672	2553
Level 4	691	-727	2976	553	-729	2721
Level 3	591	-641	2587	626	-639	2575
Level 2	423	-373	1631	430	-560	2223

	North/South Actions						
	CBGS			CCCC			
Level	Maximum Northward (kN)	Maximum Southward (kN)	Minimum In-Plane Moment (kNm)	Maximum Northward (kN)	Maximum Southward (kN)	Minimum In-Plane Moment (kNm)	
Level 6	1124	-1399	-3719	1149	-1466	-3654	
Level 5	759	-1081	-2728	600	-1388	-2618	
Level 4	828	-874	-2555	908	-1385	-2278	
Level 3	783	-987	-2137	1176	-1233	-1913	
Level 2	1097	-850	-2231	1198	-902	-1584	

Table 27 presents the diaphragm connection actions at each floor level of the South wall located on grid 1. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.

	East/West Actions					
Level	СВ	GS	CCCC			
Lever	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)		
Level 6	667	-557	633	-660		
Level 5	654	-824	726	-872		
Level 4	605	-669	720	-699		
Level 3	663	-541	843	-737		
Level 2	612	-480	724	-678		

Table 27: South wall diaphragm connection forces - Darfield

## 9.1.3. Inelastic Wall Demands.

Results have shown that inelastic demand for the cantilever bending of the north core and the south wall only occurs in the lower part of level 1. Table 28 below presents the peak strains that occur during the Darfield CBGS and CCCC events. Strains listed have been taken from the bottom shell elements at the extremities of each wall, and have presented as the average strain over the bottom 1 m of wall. Note that  $\varepsilon_y = 0.00219$  for the wall longitudinal reinforcement.

		СВ	GS	CCCC		
Location	Wall Element	Maximum Strain	Residual Displacement (m)	Maximum Strain	Residual Displacement (m)	
	Wall C gl 4	0.0070	0.0002	0.0235	0.0003	
	Wall C gl 5	0.0035	0.0006	0.0079	0.0020	
	Wall C/D gl 4	0.0093	0.0000	0.0207	-0.0001	
North Core	Wall C/D gl 5	0.0023	0.0001	0.0049	0.0014	
North Core	Wall D gl 4	0.0099	0.0003	0.0201	-0.0002	
	Wall D gl 5	0.0023	0.0001	0.0038	0.0012	
	Wall D/E gl 4	0.0094	0.0020	0.0155	0.0011	
	Wall D/E gl 5	0.0021	0.0000	0.0019	0.0000	
	Pier D gl D	0.0025	0.0001	0.0036	0.0008	
South Wall	Pier D gl E	0.0065	0.0005	0.0111	0.0008	
	Pier E gl D	0.0024	0.0001	0.0041	0.0009	
	Pier E gl E	0.0059	0.0000	0.0099	0.0004	

Table 28: Wall strains - Darfield

### **Table 29: South Wall Coupling Beam Strain**

Level	CBGS Maximum	CCCC Maximum	
Level 7	0.00024	0.00027	
Level 6	0.00069	0.00070	
Level 5	0.00103	0.00119	
Level 4	0.00128	0.00147	
Level 3	0.00150	0.00176	
Level 2	0.00189	0.00247	

The analysis results indicate that only the CCCC record produces inelastic demands on the coupling beams. Under CCCC the diagonal bars, located in the level 1 coupling beam are predicted to yield, with a maximum strain of 0.00247 (which corresponds to  $1.13\varepsilon_y$ ) reported.

### 9.1.4. Inelastic Column Actions.

Analysis results indicate that column hinging occurs for both the CBGS and CCCC records, with the number of hinges and plastic rotation demand being significantly greater for the CCCC record.

Hinges are predominantly located in the eastern perimeter frame (Frame F), although the CCCC record also predicts hinges in the base of numerous interior columns.


#### <u>CBGS</u>

The peak CBGS concrete hinge compressive strains generated at the outer face of the column are presented in Table 30 below for a selection of indicator columns.

	Column	Peak strain (mm/m)					
		Level 2 Level 3		Level 4	Level 5	Level 6	
	C1	1.89	1.83	2.48	2.85	3.21	
	F1	3.96	1.89	2.14	2.43	3.91	
	F2	3.50	3.14	3.27	3.67	3.79	
	F3	3.46	3.31	3.60	4.16	3.85	
	F4	2.44	1.73	1.70	1.83	3.17	

Table 30: CBGS peak column hinge compression strains - Darfield

Peak compressive strains are typically less than 0.002 for all levels of the remaining columns. From Table 30 it can be seen that hinging is predicted in gridlines F and 1 for the CBGS record. Maximum concrete strains are predicted for the upper hinge on column F3 at Level 4. Figure 40 to Figure 46 present a selection of plots showing the behaviour of this hinge. Information on further columns can be found in Appendix F.3








Figure 40: Column F3, Level 4 hinge rotation and elongation vs time, CBGS, Darfield.





Figure 41: Column F3 Level 4 hinge strain vs time, CBGS, Darfield.








Figure 42: Column F3 Level 4 hinge axial and moments vs time, CBGS, Darfield.




Figure 43: Column F3 Level 4 hinge moment axial relationship, CBGS, Darfield.




Figure 44: Column F3 Level 4 hinge hysteretic form, CBGS, Darfield.





Figure 45: Column F3 Level 4 moment rotation plot, CBGS, Darfield.



## Figure 46: Column F3 Level 4 hinge bi-axial moment plot, CBGS, Darfield.

## <u>CCCC</u>

The peak CCCC concrete hinge compressive strains generated at the outer face of the column are presented in Appendix G.3. Under Darfield CCCC record demands, several columns are predicted to exceed their ultimate concrete strain limits. Detailed processing of this data has not yet been completed.

# 9.1.5. Inelastic Beam-Column Joint Actions

This section presents the cumulative maximum joint deformation states for the Darfield event. Figure 47 defines the colour coding used in the plots to indicate the number of joints that have been subjected to different deformation states as the earthquake event progresses. Note that the blue colour represents elastic behaviour of the joints.

Plots are presented separately for the one-way (joints located on gridlines B to E) and twoway joints (joints located on gridline A and F). It should be noted that 'R1' corresponds to rotation about the north/south axis and 'R2' corresponds to rotation about the east/west axis. Report on Additional Non-Linear Seismic Analyses

July 2012




Figure 47: Colour coding used to represent different joint deformation states in Figure 48 to Figure 53

# <u>CBGS</u>

Figure 48 to Figure 70 present the behaviour of the beam column joints during the passage of the CBGS Darfield event. These plots present the maximum hinge rotation.





Figure 48: One-way beam-column joint R1 rotations - CBGS, Darfield

July 2012






Figure 49: Two-way beam-column joint R1 rotations - CBGS, Darfield




Figure 50: Two-way beam-column joint R2 rotations - CBGS, Darfield.

As can be seen in the Figure 48 the one-way beam column joints are predicted to remain elastic after the passage of the CBGS Darfield earthquake. Little non-linear response of the two-way beam-column joints is predicted for either axis of rotation during the Darfield event, as can be seen in Figure 49 and Figure 50.

#### <u>CCCC</u>

Figure 51 to Figure 53 present the behaviour of the beam column joints during the passage of the CCCC Darfield event. These plots present the maximum hinge rotation.





Figure 51: One-way beam-column joint R1 rotations - CCCC, Darfield.






Figure 52: Two-way beam-column joint R1 rotations - CCCC, Darfield.




Figure 53: Two-way beam-column joint R2 rotations - CCCC, Darfield.

July 2012

Report on Additional Non-Linear Seismic Analyses

As can be seen in the Figure 51 the one-way beam column joints are predicted to remain elastic after the passage of the CCCC Darfield earthquake. Figure 52 and Figure 53 show that up to 15 two-way joints are predicted to have undergone some minor cracking during the Darfield event, although their ultimate strength was not attained.

## 10. <u>Non Linear Time History: Lyttelton Results</u>

Results presented in this section are for the earthquake acceleration time history recorded at the Christchurch Botanical Gardens (CBGS), Christchurch Hospital (CHHC), Christchurch Cathedral College (CCCC), and Resthaven (REHS) stations and are a summary of the analyses only. Additional results for each record can be found in Appendix H to Appendix K. In all cases analyses results include all three components of the appropriate time history record.

Note that all records predict the loss of axial load carrying capacity of some columns during the course of the run record. Results have been presented for time-steps after axial column capacity has been exceeded so that trends can be seen and comparisons can be made between earthquake records. Assumptions in the solution process mean that results subsequent to the occurrence of column axial capacity degradation are not necessarily realistic and should be treated with caution.

## 10.1.1. Drifts and Displacements

Figure 54, and Figure 55, below present the maximum north/south percent storey drifts recorded for the perimeter frames located on grids A, and F respectively. Drifts are presented for the CCCC, CBGS, CHHC, and the REHS records.




Figure 54: Frame A north/south storey drifts - Lyttelton.

July 2012




Figure 55: Frame F north/south storey drifts - Lyttelton.

Figure 56, and Figure 57, below present the maximum east/west percentage storey drifts recorded for the perimeter frames located on grids 1, and 4 respectively. Drifts are presented for the CCCC, CBGS, CHHC, and the REHS records.




Figure 56: Frame 1 east/west storey drifts - Lyttelton.

Level

-3.50

-2.50

-1.50

-0.50

0.50

% Drift

1.50



Figure 57: Frame 4 east/west storey drifts - Lyttelton.

2.50

3.50

4.50

It can be seen from the storey drift plots above that the REHS record has larger displacement demands in the westerly direction, with the CCCC record producing the largest easterly drifts by some margin. Drift variations of up to 2.0% are predicted in the easterly direction with the CHHC record producing the smallest drifts. In the westerly direction drifts are similar for Frame 4, although variations of 0.6% are observed between the CCCC (highest drift) the CBGS (lowest drift) records.

Along frame line F all records produce a similar level of drift in the southerly direction with a maximum variation in drift of 0.7% occurring over all records and levels. More variation is seen in the northerly direction where up to 1.1% variation in drifts is seen between the REHS (smallest) and the CHHC records (largest). Frame A drifts exhibit more variation between records in the southward direction (up to 1.3% difference), with the CBGS and CHHC records producing the smallest southward drifts.

Frame A exhibits very high drifts in the northerly direction. Drifts of nearly 3.7% are predicted for the REHS record. In the southerly direction maximum drift predicted is 2.5% at level 6.

# 10.1.2. Diaphragm Connection Forces.

Table 31 to Table 35 present the diaphragm connection forces acting at each of the north core individual wall interfaces. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.

Compusoft Engineering Limited

Level	North/South Actions										
	CCCC		СННС		CBGS		REHS				
	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)			
Level 6	3041	-1924	2394	-1835	2882	-2277	3173	-1995			
Level 5	1052	-836	974	-726	1055	-829	986	-806			
Level 4	973	-1103	1156	-1028	843	-1387	837	-877			
Level 3	1035	-1185	1392	-1323	1232	-1449	963	-937			
Level 2	879	-2038	982	-1138	1274	-1087	1447	-1272			

# Table 31: Wall C diaphragm connection forces - Lyttelton.

 Table 32: Wall C/D diaphragm connection forces - Lyttelton.

	North/South Actions										
	CCCC		СННС		CBGS		REHS				
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)			
Level 6	804	-2619	1109	-2258	954	-2428	674	-2355			
Level 5	731	-1084	826	-1451	747	-1261	866	-1218			
Level 4	768	-937	795	-1461	656	-987	724	-870			
Level 3	813	-1482	1057	-1293	908	-980	831	-971			
Level 2	1308	-1059	1151	-1062	1099	-986	1269	-955			

Table 33: Wall D diaphragm connection forces - Lyttelton.

		North/South Actions										
	CCCC		СННС		CBGS		REHS					
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)				
Level 6	909	-603 <sup>1</sup>	720	-603 <sup>1</sup>	889	-603 <sup>1</sup>	718	-603 <sup>1</sup>				
Level 5	781	$-420^{1}$	703	$-420^{1}$	1129	$-420^{1}$	542	-420 <sup>1</sup>				
Level 4	593	-320 <sup>1</sup>	452	-320 <sup>1</sup>	629	-320 <sup>1</sup>	448	$-320^{1}$				
Level 3	456	0	483	0	501	0	521	0				
Level 2	456	0	565	0	534	0	613	0				

Notes: 1. Tensile limit of connection was exceeded.

	North/South Actions										
	CCCC		СННС		CBGS		REHS				
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)			
Level 6	1237	-603 <sup>1</sup>	743	-603 <sup>1</sup>	1477	-603 <sup>1</sup>	1075	-603 <sup>1</sup>			
Level 5	836	$-420^{1}$	743	$-420^{1}$	733	$-420^{1}$	615	-420 <sup>1</sup>			
Level 4	568	-320 <sup>1</sup>	564	-320 <sup>1</sup>	500	-320 <sup>1</sup>	600	-320 <sup>1</sup>			
Level 3	504	0	662	0	579	0	369	0			
Level 2	837	0	678	0	628	0	653	0			

## Table 34: Wall D/E diaphragm connection forces - Lyttelton.

Notes: 1. Tensile limit of connection was exceeded.

#### Table 35: Wall 5 (C to C/D) diaphragm connection forces - Lyttelton.

	East/West Actions										
	CCCC		СННС		CBGS		REHS				
Level	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)			
Level 6	1516	-1847	1533	-1960	2155	-1863	1380	-1707			
Level 5	1531	-2201	1102	-1542	1150	-1487	988	-1669			
Level 4	1307	-2180	1143	-1202	1400	-1840	1066	-1458			
Level 3	1169	-2001	1179	-1332	1241	-1313	906	-1438			
Level 2	893	-1389	771	-1041	1058	-1095	856	-1363			

Table 36, Table 37 and Table 38 present the diaphragm connection actions summarised for the entire north core at each floor level. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.

Level	East/West Actions										
	CCCC		СННС		CBGS		REHS				
	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)			
Level 6	2107	-2178	1920	-2546	2772	-2077	2068	-1717			
Level 5	2455	-2097	1719	-1852	1967	-1670	1664	-1575			
Level 4	2215	-2005	1838	-1392	2280	-1568	1745	-1493			
Level 3	1836	-2014	1848	-1338	1924	-1467	1437	-1667			
Level 2	1199	-1396	1129	-1214	1334	-1359	1139	-1714			

# Table 36: North core total diaphragm connection E/W forces - Lyttelton.

Table 37: North core total diaphragm connection N/S forces - Lyttelton.

	North/South Actions										
	CCCC		СННС		CBGS		REHS				
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)			
Level 6	2150	-1907	2034	-1700	2137	-1669	2772	-1689			
Level 5	1803	-1623	1974	-1982	2189	-1515	1875	-1628			
Level 4	1375	-2032	2143	-1793	1835	-2078	1514	-1795			
Level 3	1914	-2742	3111	-2339	2581	-2395	2236	-1906			
Level 2	2012	-1955	2320	-2005	2820	-1966	2352	-1844			

Table 38: North core total diaphragm connection forces - Lyttelton.

		In-Plane Moments										
	CCCC		СННС		CBGS		REHS					
Level	Maximum +Moment (kNm)	Maximum -Moment (kNm)	Maximum +Moment (kNm)	Maximum -Moment (kNm)	Maximum +Moment (kNm)	Maximum -Moment (kNm)	Maximum +Moment (kNm)	Maximum -Moment (kNm)				
Level 6	16127	-14027	16696	-11624	20809	-13254	15775	-15953				
Level 5	8232	-7792	5490	-7259	7223	-7125	6590	-6365				
Level 4	6149	-7138	5403	-5788	6779	-4918	6540	-4761				
Level 3	6779	-6128	5824	-5561	6227	-5315	6313	-5420				
Level 2	10378	-4811	8388	-4237	9543	-4857	7739	-6889				

Table 39, Table 40, and Table 41 present the actions acting along the slab interface along gridline 4 between grids C and C/D. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.

	East/West Actions										
	CCCC		СННС		CBGS		REHS				
Level	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)			
Level 6	2009	-1898	2311	-1697	1944	-2572	1523	-1892			
Level 5	1790	-2177	1620	-1591	1431	-1739	1325	-1395			
Level 4	1633	-1941	1161	-1599	1346	-2059	1276	-1499			
Level 3	1686	-1598	1147	-1603	1291	-1700	1427	-1403			
Level 2	1248	-1012	1103	-912	1174	-1216	1512	-935			

Table 39: Slab 4 C to C/D diaphragm E/W actions - Lyttelton.

Table 40: Slab 4 C to	C/D	diaphragm N	/S actio	ons - Lyttelton.
	0,2	windprin ugin i t	in actin	

	North/South Actions										
	CCCC		СННС		CBGS		REHS				
Level	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)	Maximum Northward (kN)	Maximum Southward (kN)			
Level 6	2300	-1724	2444	-1799	2297	-1956	2179	-3186			
Level 5	1464	-1532	1754	-1477	1538	-1749	1432	-1572			
Level 4	1948	-1328	1677	-1952	2012	-1448	1513	-1370			
Level 3	2551	-1443	2254	-2338	2255	-1690	1832	-1484			
Level 2	2118	-1882	1946	-1824	1745	-2157	1842	-2246			

Level	In-Plane Moments										
	CCCC		СННС		CBGS		REHS				
	Maximum +Moment (kNm)	Maximum -Moment (kNm)	Maximum +Moment (kNm)	Maximum -Moment (kNm)	Maximum +Moment (kNm)	Maximum -Moment (kNm)	Maximum +Moment (kNm)	Maximum -Moment (kNm)			
Level 6	15514	-8454	12502	-6496	13223	-7931	13830	-6194			
Level 5	9372	-7821	8336	-5425	7653	-7047	8119	-5526			
Level 4	9343	-7220	5557	-5754	6177	-7446	7470	-5168			
Level 3	7968	-4931	4928	-5329	5194	-5053	5714	-4450			
Level 2	5365	-4406	4739	-4615	5119	-3397	5366	-3073			

 Table 41: Slab 4 C to C/D diaphragm connection forces - Lyttelton.

Table 41 presents the diaphragm connection actions at each floor level of the south wall located on grid 1. Results presented are the enveloped maxima recorded over the duration of the time-history record analysed.

Level	East/West Actions							
	CCCC		СННС		CBGS		REHS	
	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)	Maximum Westward (kN)	Maximum Eastward (kN)
Level 6	1080	-979	1001	-1281	845	-1007	865	-1169
Level 5	1298	-1244	1124	-906	1321	-1010	1225	-1118
Level 4	1077	-1063	1265	-1126	1000	-1047	1120	-915
Level 3	1228	-1081	1134	-1364	1110	-1518	1299	-953
Level 2	1651	-1313	1492	-1151	1432	-1568	1460	-1203

## 10.1.3. Inelastic Column Actions.

Analyses predict failure of the columns to occur at various times throughout the passage of all earthquake records.

# <u>CBGS</u>

A number of column hinges in the base of the level 1 columns are predicted to exceed their ultimate stain limits 6.36 seconds into the run CBGS record. These hinges are located along

grid lines 1 and 2 e.g. column B1, B2, C1, C2, D2, and E2. Exceedence of the ultimate concrete strain corresponds to a large spike in the east-west displacements of the structure, which can be seen in Figure 58






Figure 58: Building level 6 displacements, CBGS, Lyttelton.

Column C2 has been presented in this section as it is predicted to be the first column to exceed capacity under the CBGS record demands, although only by a fraction of a second. A selection of column hinge actions for the hinge located at the base of the column at gridline C2 is presented in Figure 59 to Figure 65 for the CBGS earthquake record.

It can be seen in Figure 59 that the hinge at the bottom of the level 1 gridline C2 column is subject to a significant increase in rotation approximately 6.3 seconds into the run record. This causes a corresponding increase in concrete strains causing the ultimate concrete strain to be exceeded at 6.36 seconds. At this time concrete spalling is expected to occur. Shortly after spalling is predicted the column is seen to lose its axial load carrying capacity as can be seen in Figure 60 and Figure 61.



July 2012







Figure 59: Column C2, Level 1 hinge rotation and elongation vs time, CBGS, Lyttelton.

Figure 60: Column C2 Level 1 hinge strain vs time, CBGS, Lyttelton.








Figure 61: Column C2 Level 1 hinge axial and moments vs time, CBGS, Lyttelton.




Figure 62: Column C2 Level 1 hinge moment axial relationship, CBGS, Lyttelton.




Figure 63: Column C2 Level 1 hinge hysteretic form, CBGS, Lyttelton.





Figure 64: Column C2 Level 1 moment rotation, CBGS, Lyttelton.



# Figure 65: Column C2 Level 1 hinge bi-axial moment, CBGS, Lyttelton.

It should be noted that the strain plots indicate that the whilst a number of columns exceed the ultimate concrete compressive strain at similar times, the more heavily loaded columns such as columns C2 and D2 are seen to lose their vertical support more rapidly than the more lightly loaded columns. Appendix H.3 contains more information on the hinge strains for various hinges when subject to the CBGS Lyttelton demands.

# <u>CCCC</u>

Results for the CCCC Lyttelton analyses can be found in Appendix I.3.

# <u>CHHC</u>


Results for the CHHC Lyttelton analyses can be found in Appendix J.3.

## <u>REHS</u>

Results for the REHS Lyttelton analyses can be found in Appendix K.3.


#### 10.1.4. <u>Beam-Column Joints.</u>

This section presents the cumulative maximum joint deformation states for the Lyttelton event. Figure 47 (represented below) defines the colour coding used in the plots to indicate the number of joints that have been subjected to different deformation states as the earthquake event progresses. Note that the blue colour represents elastic behaviour of the joints.



# Figure 47: Colour coding used to represent different joint deformation states in Figure 66 to Figure 81

Plots are presented separately for the one-way (joints located on gridlines B to E) and twoway joints (joints located on gridline A and F). It should be noted that 'R1' corresponds to rotation about the north/south axis and 'R2' corresponds to rotation about the east/west axis.








Figure 66: One-way beam-column joint R1 rotations - CBGS, Lyttelton.





Figure 67: Two-way beam-column joint R1 rotations - CBGS, Lyttelton.






Figure 68: Two-way beam-column joint R1 rotations - CBGS, Lyttelton (cumulative).






Figure 69: Two-way beam-column joint R2 rotations - CBGS, Lyttelton.






#### Figure 70: Two-way beam-column joint R2 rotations - CBGS, Lyttelton (cumulative).


As can be seen in Figure 66 the interior beam column joints behave elastically when subject to the CBGS record demands. Figure 67 and Figure 69 indicate that the exterior joints are subject to inelastic demand, however joint ultimate capacity is only reached after column hinges located at the base of the column are predicted to have their ultimate concrete strain exceeded i.e. 6.36 seconds.

As can be seen in Figure 71 the interior beam column joints behave elastically when subject to the CCCC record demands. Figure 72 and Figure 74 indicate that the exterior joints are subject to inelastic demand, however joint ultimate capacity is only reached after column hinges are predicted to have their ultimate concrete strain exceeded.

As can be seen in Figure 76the interior beam column joints behave elastically when subject to the CHHC record demands. Figure 77 and Figure 78 indicate that the exterior joints are subject to inelastic demand, however joint ultimate capacity is only reached after column hinges are predicted to have their ultimate concrete strain exceeded.

July 2012









Figure 71: One-way beam-column joint R1 rotations - CCCC, Lyttelton.

Figure 72: Two-way beam-column joint R1 rotations - CCCC, Lyttelton.






Figure 73: Two-way beam-column joint R1 rotations - CCCC, Lyttelton (cumulative).





Figure 74: Two-way beam-column joint R2 rotations - CCCC, Lyttelton.








Figure 75: Two-way beam-column joint R2 rotations - CCCC, Lyttelton (cumulative).





Figure 76: One-way beam-column joint R1 rotations - CHHC, Lyttelton.








Figure 77: Two-way beam-column joint R1 rotations - CHHC, Lyttelton.





Figure 78: Two-way beam-column joint R2 rotations - CHHC, Lyttelton.



July 2012




Figure 79: One-way beam-column joint R1 rotations - REHS, Lyttelton.






Figure 80: Two-way beam-column joint R1 rotations - REHS, Lyttelton.



July 2012



#### Figure 81: Two-way beam-column joint R2 rotations - REHS, Lyttelton.

As can be seen in Figure 79 the interior beam column joints exhibit some minor in-elastic behaviour when subject to the REHS record demands, with up to five joints indicating rotations between 0.002 and 0.007 radians. Figure 80 and Figure 81 indicate that the exterior joints are subject to inelastic demand with strength degradation occurring in up to 11 joints after 6.7 seconds. It should be noted that degradation in the joint strength only occurs after column hinges are predicted to have their ultimate concrete strain exceeded.

Results show that the interior joints behaved elastically in the CBGS, CCCC, and CHHC records. The REHS record produced some minor inelastic behaviour in the joints towards the end of significant shaking. The results indicate that the interior beam-column joint strengths were not reached for all records.

Exterior beam-column joints were subject to inelastic demand for all records.

# 11. <u>Vertical Earthquake Effects</u>

#### 11.1. Axial Load Effects

Figure 82 and Figure 83 present the maximum variation in axial force obtained during the analysis for columns on grids C2 and F2 under the CBGS and CCCC record demands.




Figure 82: Column C2 axial load variation - CBGS (left) & CCCC (right), Lyttelton




Figure 83: Column F2 axial load variation - CBGS (left) & CCCC (right), Lyttelton

Columns with a larger tributary area of floor slab such as column C2 exhibit a larger variation in axial force than columns with a smaller axial load contribution from the slabs e.g. column F2. In addition to the slab component some of the axial load variation can be attributed to the stiffness of the beams spanning onto the column.

It can be seen that the CCCC record produces a much larger variation in axial load in the elements considered than the CBGS record. This can be attributed to the difference in frequency components between the two records and the magnitude of the vertical accelerations present in each. Figure E.3 and Figure E.4 contain the vertical acceleration time

Report on Additional Non-Linear Seismic Analyses

history records for the CBGS and the CCCC stations. From these it can be seen that the vertical accelerations were considerably higher at the CCCC station than for the CBGS station.

It should also be noted that the peak axial demands may not be concurrent with the peak bending actions that occur as a result of building drift. Consequently, when assessing vertical earthquake demands, consideration should be given to the concurrency of actions.

# 12. <u>Conclusions</u>

Conclusions will be published at the time of production of the first formal issue of this report.

# 13. <u>References</u>

- Alire, D. A. (2002). Seismic Evaluation of Existing Unconfined Reinforced Concrete Beam-Column Joints. University of Washington, Seattle, Washington, 306p.
- Andriono, T., and Park, R. (1986). "Seismic Design Considerations of the Properties of New Zealand Manufactured Steel Reinforcing Bars." *Bulletin of the New Zealand National Society for Earthquake Engineering*, 19(3), pp.213–246.
- AS/NZS 1170.0. (2002). *Structural design actions, Part 0: General Principles*. Standards New Zealand/Standards Australia, Wellington, New Zealand, 36p.
- ASCE. (2006). ASCE 41-06 Seismic Rehabilitation of Existing Buildings. American Society of Civil Engineers, Reston, Virginia, 411p.
- Birely, A., Lowes, L. N., and Lehman, D. E. (2012). "A Model for the Practical Nonlinear Analysis of Reinforced-Concrete Frames Including Joint Flexibility." *Engineering Structures*, 34, pp.455–465.
- Carr, A. J. (1994). "Dynamic Analysis of Structures." Bulletin of the New Zealand Society for *Earthquake Engineering*, 27(2).
- Clyde, C., Pantelides, C. P., and Reaveley, L. D. (2000). *Performance-Based Evaluation of Exterior Reinforced Concrete Building Joints for Seismic Excitation*. Pacific Earthquake Engineering Research Center, Berkeley, California, 50p.
- Concrete Design Committee P3101. (1994). *Revisions to the New Zealand Standard for the Design* of Concrete Structures NZS 3101. New Zealand Concrete Society, Wellington, New Zealand, 168p.
- CSI Berkeley. (2011). *Computer program SAP2000 v14.2.5*. Computers and Structures Inc., Berkeley, California.
- DBH. (2011). "Changes for Christchurch Seismicity: Changes to Verification Method B1/VM1 -Hazard Factor for Christchurch." Accessed at: http://www.dbh.govt.nz/UserFiles/File/Publications/Building/Guidance-information /pdf/information-sheet-on-seismicity-changes.pdf (Aug. 22, 2011).
- Design Engineer. (1986). Structural Drawings: Office Building 249 Madras Street. Set No. 7, Issued 30 September, 39p.
- Dowell, R. K., Seible, F., and Wilson, E. L. (1998). "Pivot Hysteresis Model for Reinforced Concrete Members." *ACI Structural Journal*, 95(5), pp.607–616.
- Geonet. (2010a). "M 7.1, Darfield (Canterbury), September 4 2010." Accessed at: www.geonet.org.nz/earthquake/historic-earthquakes/top-nz/quake-13.html (Aug. 5, 2011).
- Geonet. (2010b). "Darfield Mainshock Records." Accessed at: ftp.geonet.org.nz/strong/processed/Proc/2010/09\_Darfield\_ mainshock\_extended\_pass\_band/Vol2/data/ (Aug. 5, 2011).
- Geonet. (2011a). "M 6.3, Christchurch, February 22 2011." Accessed at: www.geonet.org.nz/earthquake/historic-earthquakes/top-nz/quake-14.html (Aug. 5, 2011).
- Geonet. (2011b). "Christchurch Mainshock Records." Accessed at: ftp.geonet.org.nz/strong/processed/Proc/2011/02\_Christchurch\_ mainshock\_extended\_pass\_band/Vol2/data/ (Aug. 5, 2011).

- Hakuto, S., Park, R., and Tanaka, H. (2000). "Seismic Load Tests on Interior and Exterior Beam-Column Joints with Substandard Reinforcing Details." *ACI Structural Journal*, 97(1), pp.11–25.
- Hindi, R. A., and Hassan, M. A. (2004). "Shear Capacity of Diagonally Reinforced Coupling Beams." *Engineering Structures*, 26(10), pp.1437–1446.
- Hyland, C. (2011). *CTV Building Site Examination and Materials Tests*. Hyland Fatigue and Earthquake Engineering, Auckland, New Zealand, 158p.
- Karthik, M. M., and Mander, J. B. (2011). "Stress-Block Parameters for Unconfined and Confined Concrete Based on a Unified Stress-Strain Model." *Journal of Structural Engineering*, 137(2), pp.270–273.
- Kurose, Y. (1987). Recent Studies on Reinforced Concrete Beam-Column Joints in Japan. Phil M. Ferguson Structural Engineering Laboratory, The University of Texas, Austin, Texas, 164p.
- LaFave, J. M., and Shin, M. (2005). "Discussion of 'Modelling Reinforced-Concrete Beam-Column Joints Subjected to Cyclic Loading' by Laura N. Lowes and Arash Altoontash." *Journal of Structural Engineering*, 131(6), pp.992–993.
- Lehman, D. E., Stanton, J. F., Anderson, M., Alire, D. A., and Walker, S. G. (2004). "Seismic Performance of Older Beam-Column Joints." *13th World Conference on Earthquake Engineering*, Vancouver, Canada.
- Mander, J. B. (2012). "RE: Compusoft Request for Information."
- Mander, J. B., Priestley, M. J. N., and Park, R. (1988). "Theoretical Stress-Strain Model for Confined Concrete." *ASCE Journal of Structural Engineering*, 114(8), pp.1804–1826.
- Mitra, N., and Lowes, L. N. (2007). "Evaluation, Calibration, and Verification of a Reinforced Concrete Beam-Column Joint Model." ASCE Journal of Structural Engineering, 133(1), pp.105–120.
- Moehle, J. P., Lehman, D., and Lowes, L. N. (2006). "Beam-Column Connections." PEER/EERI Seminar on Nonductile Concrete, Accessed at: peer.berkeley.edu/ research/ powerpoint/ non\_ductible\_concrete/Joints - Moehle c.ppt (Jun. 15, 2012).
- NZS 1170.5. (2004). Structural design actions, Part 5: Earthquake Actions New Zealand. Standards New Zealand, Wellington, New Zealand, 154p.
- NZS 3101. (2006). *Concrete Structures Standard*. Standards New Zealand, Wellington, New Zealand, 646p.
- NZSEE. (2006). Assessment and Improvement of the Structural Performance of Buildings in Earthquakes. New Zealand Society for Earthquake Engineering, Wellington, New Zealand, ~400p.
- Pampanin, S., Calvi, G. M., and Moratti, M. (2002). "Seismic Behaviour of RC Beam-Column Joints Designed for Gravity Loads." 12th European Conference on Earthquake Engineering, Elsevier Science Ltd., London, England.
- Pantelides, C. P., Hansen, J., and Nadauld, J. (2002). *Performance-Based Evaluation of Exterior Reinforced Concrete Building Joints for Seismic Excitation*. Pacific Earthquake Engineering Research Center, Berkeley, California, 103p.
- Park, S. (2010). *Experimental and Analytical Studies on Old Reinforced Concrete Buildings with Seismically Vulnerable Beam-Column Joints*. University of California, Berkeley, 260p.

- Paulay, T., and Priestley, M. J. N. (1992). Seismic Design of Reinforced Concrete and Masonry Buildings. John Wiley & Sons, New York, 744p.
- Priestley, M. J. N. (1997). "Displacement-Based Seismic Assessment of Reinforced Concrete Buildings." *Journal of Earthquake Engineering*, 1(1), pp.157–192.
- Priestley, M. J. N., Calvi, G. M., and Kowalsky, M. J. (2007). *Displacement-Based Seismic Design* of Structures. IUSS Press, Pavia, Italy, 721p.
- Sharma, A., Eligehausen, R., and Reddy, G. R. (2011). "A New Model to Simulate Joint Shear Behaviour of Poorly Detailed Beam-Column Connections in RC Structures Under Seismic Loads, Part 1: Exterior Joints." *Engineering Structures*, 33, pp.1034–1051.
- Sinclair, T. (2011). CTV Geotechnical Advice (11 July). Tonkin & Taylor, Auckland, New Zealand, 14p.
- Sinclair, T. (2012). *CTV Building Geotechnical Advice Addendum 2 (14 June)*. Tonkin & Taylor, Auckland, New Zealand, 9p.
- Takeda, T., Sozen, M. A., and Nielsen, N. N. (1970). "Reinforced Concrete Response to Simulated Earthquakes." *Journal of Structural Engineering*, 96(12), pp.2257–2273.
- Vecchio, F. J., and Collins, M. P. (1986). "The Modified Compression-Field Theory for Reinforced Concrete Elements Subjected to Shear." *Journal of the American Concrete Institute*, 83(2), pp.219–231.
- Walker, S. G. (2001). Seismic Performance of Existing Reinforced Concrete Beam-Column Joints. University of Washington, Seattle, Washington, 326p.
- Weng Yuen, K. (2010). Selective Weakening and Post-Tensioning for the Seismic Retrofit of Non-Ductile RC Frames. The University of Canterbury, Christchurch, New Zealand, 672p.

## List of appendices

Appendix A	A Nonlinear analysis of diagonally reinforced coupling beams	. 96
A.1 C	Considered model	96
A.2 E	Example structure	96
A.3 A	analysis model definition	. 97
A.4 A	analysis results	99
A.5 St	train penetrations	101
Appendix I	B :Nonlinear analysis of frames with consideration of axial-moment (P-M) interact 102	ion.
B.1 In	ntroduction	102
B.2 P1	roposed model	102
B.3 A	xial-moment (P-M) interaction relationship	102
B.4 M	Ioment-curvature relationship – monotonic loading	102
B.5 M	Ioment-curvature relationship – cyclic loading	102
Appendix C	C Development of a model for beam-column joints of the CTV building	103
C.1 In	ntroduction	103
C.1.1	CTV Building beam-column joints in relation to New Zealand Standards	103
C.1.2	Issues related to modelling of deficient beam-column joints	104
C.2 In	nplementation	105
C.3 D	Definition of relative stress vs deformation backbone curve	106
C.4 D	Definition of maximum joint shear strength	109
C.5 Is	ssues and limitations of the adopted joint degradation implementation	112
C.5.1	Limitations of the method used to implement the joint shear spring	112
C.5.2	Geometry of the exterior beam-column joints	114
C.5.3 impos	Relationship of joint strength and deformation characteristics to deformated on adjacent members	
	Calculations showing basis for relating joint moment to shear stress for model	-
	D Foundation Modelling Properties	
Appendix E	E Acceleration Time History Records	120

E.1	Darfield CBGS	120
E.2	Darfield CCCC	121
E.3	Lyttelton CBGS	122
E.4	Lyttelton CCCC	123
E.5	Lyttelton CHHC	124
E.6	Lyttelton REHS	125
Appendi	ix F Analysis Results - Darfield Event: CBGS Record	127
F.1	Building Displacements and Drifts.	127
F.2	Diaphragm Connection Forces	130
F.3	Column Hinge Actions	136
Appendi	ix G Analysis Results - Darfield Event: CCCC Record	142
G.1	Building Displacements and Drifts.	142
G.2	Diaphragm Connection Forces	145
G.3	Column Hinge Actions	151
Appendi	ix H Analysis Results - Lyttelton Aftershock: CBGS record	158
H.1	Building Displacements and Drifts.	
H.2	Diaphragm Connection Forces	
H.3	Column Hinge Actions	170
Appendi	ix I Analysis Results - Lyttelton Aftershock: CCCC record	177
I.1	Building Displacements and Drifts.	177
I.2	Diaphragm Connection Forces	183
I.3	Column Hinge Actions	189
Appendi	ix J Analysis Results - Lyttelton Aftershock: CHHC record	196
J.1	Building Displacements and Drifts.	196
J.2	Diaphragm Connection Forces	199
J.3	Column Hinge Actions	205
Appendi	ix K Analysis Results - Lyttelton Aftershock: REHS record	211
<b>K</b> .1	Building Displacements and Drifts.	211
K.2	Diaphragm Connection Forces	214
K.3	Column Hinge Actions	220

### Appendix A <u>Nonlinear analysis of diagonally reinforced coupling beams</u>

#### A.1 <u>Considered model</u>

A method for considering the nonlinear load-deformation behaviour of diagonally reinforced coupling beams is proposed by Hindi and Hassan (2004). In this method a simple truss mechanism is considered to provide all strength and stiffness to the system. When the system is subjected to sway actions the resulting shear force and bending moment is carried via two diagonal members with one in compression and one in tension. The compression member includes the confined concrete core and the diagonal reinforcing bars whereas the tension member includes only the diagonal reinforcing bars. It is considered that the concrete core provides sufficient stiffness to ensure that the member cannot buckle in compression. The proposed truss model is as presented in Figure A.1 below.




Figure A.1: Proposed model (from Hindi and Hassan 2004)

#### A.2 <u>Example structure</u>

The proposed model has been implemented for an example structure as presented in Figure A.2 below. In this structure two 2050 mm long reinforced concrete walls are joined by a coupling beam measuring 900 mm long by 1650 mm high. The wall thickness is 400 mm throughout.

#### Report on Additional Non-Linear Seismic Analyses




Figure A.2: Example wall reinforcement

#### A.3 <u>Analysis model definition</u>

The example structure has been analysed considering the proposed model using SAP2000 (v14). In this model axially "stiff" diagonal struts (oriented at 54° to the horizontal from Figure A.2) are included to consider the behaviour of the coupling beam following the model presented in Section A.1. The strut dimensions are taken as 150 mm square. Axial deformation in the struts is provided via fibre type hinge element which incorporates both concrete and reinforcement fibres. The walls are modelled using membrane elements that have sufficient stiffness to ensure that deformation is restricted to the coupling beam. As the conventional beam reinforcement also present in the coupling beam is not included, this modelling analogy will underestimate the stiffness of the coupling beam for elastic response, but will provide a reasonable representation of the wall response in the inelastic range. The analysis model is presented in Figure A.3 below.

July 2012

July 2012

Report on Additional Non-Linear Seismic Analyses




Figure A.3: SAP2000 analysis model

The reinforcement in the diagonal struts is included as a fibre type element with stress-strain behaviour as defined by Park and is presented in Figure A.4 below. The hysteretic form of the reinforcing is taken as kinematic type. The area of the reinforcing steel is taken as the sum of all longitudinal reinforcement present in the strut (i.e.  $A_s=4-D28=2463 \text{ mm}^2$ ). Strain penetration of the diagonal reinforcement into the walls has been excluded in this model.




Figure A.4: Reinforcing nonlinear steel stress-strain plot

The concrete core of the diagonal strut elements is included fibre type element with material behaviour based on a Mander confined concrete model (Mander et al. 1988) with an unconfined compressive strength,  $f_c$ '=33.5 MPa,  $\varepsilon_{c0}$ =0.002, ultimate unconfined strain capacity given as 0.004, and confining reinforcing as presented in Figure A.4 above (i.e. R6@75crs confining hoops). The hysteretic form of the concrete fibre is considered exhibit Takeda type behaviour. The area of the concrete is taken as the total concrete core area (i.e.

 $A_c=A_g-A_s=150^2-2,464=20,036 \text{ mm}^2$ ). The nonlinear stress-strain behaviour for the concrete is as presented in Figure A.5 below (note that the tensile capacity has been taken as zero).




Figure A.5: Concrete nonlinear stress-strain plot

#### A.4 <u>Analysis results</u>

A nonlinear analysis has been undertaken to derive the force-deformation behaviour of the system. The backbone curve for the coupling beam system plotted as wall rotation (=drift) vs coupling beam shear force is presented in Figure A.6 below.




Figure A.6: Nonlinear backbone curve

A qualitative comparison of the resulting backbone curve and those presented by Hindi and Hassan (2004) indicates that the model adequately predicts the force-displacement behaviour for monotonic loading.

In order to assess the hysteretic form, a non-linear displacement time history analysis has been undertaken. Figure A.7 below plots the wall rotation (=drift) vs coupling beam shear force for the cyclic analysis.

#### Report on Additional Non-Linear Seismic Analyses






Figure A.7: Coupling beam hysteretic response

It can be seen that for the level of drift considered the analysis model behaves essentially in an elastic-perfectly plastic manner due to the reinforcing with additional strength enhancement as a result of the concrete. A limitation of the analysis undertaken is that the hysteretic behaviour does not reflect the softening that would normally be expected under cyclic loading due to the Bauschinger effect, and other mechanisms such as concrete spalling etc.

In an attempt to approximate these effects an additional analysis model has been developed whereby the hysteresis type for the reinforcement has been changed from the default kinematic type to instead be a Takeda type. The resulting hysteretic response is presented in Figure A.8 below which plots the wall rotation (=drift) vs coupling beam shear force.





It can be seen that whilst the hysteretic behaviour is not perfect, the total amount of energy dissipated for the considered loading history is reduced by approximately 50%.

July 2012

#### A.5 <u>Strain penetrations</u>

The effects of strain penetration of the diagonal reinforcement into the wall have not been directly incorporated into the analysis models. In order to incorporate these effects, the non-linear stress-strain curve for the reinforcing steel element as presented in Figure A.4 has instead been scaled in the strain domain based on the following:

$$\varepsilon_s' = \varepsilon_s \left(\frac{L + 2L_{SP}}{L}\right)$$

Where  $\varepsilon_s$  is the scaled strain,  $\varepsilon_s$  is the material strain obtained from Figure A.4, L is the length of the element as considered in the model, and L<sub>SP</sub> is the strain penetration length, determined using the equation below taken from Paulay and Priestley (1992):

$$L_{SP} = 0.022 f_s d_b$$

where  $f_s$  and  $d_b$  are the stress and diameter of the longitudinal reinforcement respectively.

For the example structure the modelled length of the strut is given as 1531 mm and the diagonal bar is given as 28 mm diameter which then gives a modified non-linear stress-strain curve for the reinforcing fibre as presented in Figure A.9 below.




Figure A.9: Reinforcing nonlinear stress-strain plot (modified for strain penetrations)

# Appendix B:Nonlinear analysis of frames with consideration of axial-moment<br/>(P-M) interaction.

- B.1 <u>Introduction</u>
- B.2 <u>Proposed model</u>
- B.3 <u>Axial-moment (P-M) interaction relationship</u>
- B.4 <u>Moment-curvature relationship monotonic loading</u>
- B.5 <u>Moment-curvature relationship cyclic loading</u>

## Appendix C <u>Development of a model for beam-column joints of the CTV</u> <u>building</u>

#### C.1 <u>Introduction</u>

In typical modern reinforced concrete structures beam-column joints are designed so that they are stronger than the beam and column members framing into the joint. Such joints can reasonably be assumed to respond elastically during an earthquake, and thus it is not necessary to specifically model the beam-column joint beyond allowing some elastic deformation to occur in the joint core. In contrast, the beam-column joints of the CTV Building are significantly deficient in relation to modern design procedures, and cannot be assumed to respond elastically. Thus the potential for beam-column joint core failure to occur prior to or in conjunction with beam and/or column hinging must be considered when assessing the performance of the CTV Building. During the original time history analyses of the structure the possibility of joint failure was assessed by post-processing of output data. During discussions regarding alterations and enhancements to the CTV Building non-linear analysis model it was made clear that some members of the Royal Commission Expert Panel on Non-linear Time History Analysis (NLTHA) considered this post-processing approach to be inadequate and that implementation of non-linear beam-column joint behaviour in the analysis model would be preferred. This appendix discusses the beam-column joints of the CTV Building and the procedures developed to model them.

#### C.1.1 CTV Building beam-column joints in relation to New Zealand Standards

Beam-column joints require both horizontal and vertical reinforcement in order to develop the require mechanisms for reliable resistance of earthquake induced forces. Horizontal reinforcement is generally provided by stirrup or spiral reinforcement placed specifically for this purpose, while in New Zealand practice vertical joint shear reinforcement is typically assumed to be provided by the intermediate column longitudinal reinforcing bars, which are expected to behave elastically during earthquakes.

The CTV Building was designed during the mid 1980s, and as such would be assumed to have beam-column joints that met or exceeded (Concrete Design Committee P3101 1994) the detailing requirements of the current New Zealand Concrete Structures Standard (NZS 3101 2006). However, review of the structural drawings indicates that this is not the case. The beam-column joints are instead effectively unreinforced, and hence likely to perform in a

manner similar to joints typical of much older structures designed prior to the adoption of "modern" design standards. The reasons for considering the joints to be effectively unreinforced are twofold:

- The CTV Building drawings are unclear about whether the column transverse reinforcement continues through the joint core; however, the wide spacing of this transverse reinforcement means that even if it did continue through the joint core it would be equivalent to only a small fraction of the horizontal joint reinforcement required.
- The joints also lack effective vertical reinforcement, as the intermediate column longitudinal reinforcing bars of the CTV Building cannot generally be assumed to remain elastic during significant earthquakes. Instead the intermediate column longitudinal reinforcement would be expected to yield because many of the beam-column joints are expected to perform in a "strong beam-weak column" manner, i.e. with plastic hinge formation in the columns rather than the beams. Thus the intermediate column longitudinal bars would not possess reserve capacity with which to reinforce the joint.

#### C.1.2 Issues related to modelling of deficient beam-column joints

Realistic non-linear modelling of deficient concrete beam-column joints is unfortunately not a trivial exercise. Several factors make it difficult to accurately model the joints of the CTV building. These include:

- The response of deficient joints is still a highly active research topic;
- There are fundamental international disagreements regarding the mechanics and behaviour of concrete beam-column joints;
- Simple models of deficient beam-column joints available in the literature are typically intended for assessment of existing structures, and are thus considered to be unduly conservative for forensic engineering purposes;
- Rigorous joint models available in the literature are not suitable for implementation in commercial finite element software, particularly for a model containing multiple beam-column joints such as that of the CTV building.
- The joints of the CTV building contain many features that are not well covered by the available research literature. These features include circular columns,

"weak column-strong beam" behaviour, biaxial loading, and deficient hooked anchorages in interior joints.

The remainder of this document presents discussion related to the adopted analysis model for the CTV beam-column joints. This discussion is divided into a number of topics. Discussion of some of these topics includes non-comprehensive review of relevant literature where this has been used as the basis for defining the beam-column joint model.

#### C.2 Implementation

A number of methods can be used to incorporate beam-column joint response within a structural finite element model. The method adopted by Compusoft Engineering Limited for the CTV structural model is to develop a non-linear rotational spring representing the beam-column joint shear stress-shear strain response, with this spring located at the node representing the intersection of beams and columns at the beam-column joint. The moment applied to the joint can be related to the shear stress in the joint based on the geometry of the structure. Details of the calculations defining this relationship are presented in Appendix C.6.

The rotational spring used to model the joints has the following features:

- Independent, non-interacting properties for orthogonal axes of loading.
- No moment-axial load interaction.
- A moment-rotation backbone curve based on the joint shear stress-shear strain backbone curve described in the following sections and the calculations presented in Appendix C.6.
- Hysteretic response based on a "Pivot" hysteresis model (Dowell et al. 1998).

Review of relevant literature has shown that there is significant disagreement between sources with regards to both the peak strength of deficient beam-column joints, and also the force-deformation relationship that is appropriate for deficient joints. This document considers these two issues separately, first considering an appropriate backbone curve defining the relationship between joint deformation and relative or normalised strength, and then considering the peak strength expected from deficient beam-column joints.

#### C.3 Definition of relative stress vs deformation backbone curve

In this section various backbone curves relating joint deformation to joint stress presented in the literature are discussed, and from these curves an appropriate curve is defined for use in the CTV Building non-linear analyses. In order to clarify the discussion, the backbone curves are defined based on relative joint stress, with a relative joint stress of 1.0 being taken as equal to the maximum joint shear strength.

Figure C.1 shows a number of backbone curves for the relative stress-strain response of deficient beam-column joints. As indicated, these curves have been drawn from a wide variety of sources. It is evident from the plot that there is considerable variance between the postulated curves. Brief details of each curve are as follows:

- The FEMA 356/ASCE 41 curve is taken from a widely used U.S. document outlining procedures for assessment of existing buildings.
- The curve recommended by Park (2010) was based on testing of four exterior beam-column joints. The deformation at peak stress is determined based on joint geometry.
- The curve proposed by Weng Yuen (2010) is for exterior joints, and is a modification of similar curves published widely by other researchers.
- Sharma et al. (2011) specified in the paper that "the plot of principal tensile stress vs. joint shear deformation ... seems appropriate", but did not show supporting experimental data. Review of the referenced data (Clyde et al. 2000; Pantelides et al. 2002) suggests that the adopted curve was a "lower bound" appropriate for assessment but less so for prediction.
- Birely et al. (2012) provided no data regarding the descending branch of the backbone curve. They calibrated their curve against data from interior beam-column joint tests.
- The final curve plotted was developed by Compusoft Engineering Limited based on review of data presented by Walker (2001) and Alire (2002). It represents an approximate average of the stress-deformation response measured during 11 tests on interior beam-column joints. Data from these 11 tests is shown in Figure C.2.

July 2012




Figure C.1: Backbone curves from various sources (Alire 2002; ASCE 2006; Birely et al. 2012; S. Park 2010; Sharma et al. 2011; Walker 2001; Weng Yuen 2010)




Figure C.2: Joint shear stress vs strain until 3% drift for tests by Walker (2001) and Alire (2002) of interior unreinforced joints with axial load of ≈0.1Agfc

It is clear from consideration of the data presented in Figure C.1 that the backbone curve presented in FEMA 356/ASCE 41 is significantly conservative. Further evidence supporting this statement can be seen in Figure C.3, which shows the stress-deformation response of other deficient beam-column joints. Similarly, it seems that the curve proposed by Sharma et al. (2011) is unduly conservative for forensic purposes. A backbone curve based on

consideration of the remaining four backbone curves has been developed and is presented in Figure C.4. It can be seen that this curve is similar to the curve presented by Weng Yuen (2010).




Figure C.3: Joint shear stress-deformation response of deficient beam-column joints (from Kurose 1987)





Figure C.4: Proposed backbone curve for joint deformation

Members of the Royal Commission Expert Panel have stated to Compusoft Engineering Limited that the provision of any "plasticity" in the backbone curve for the beam-column joints is unrealistic, as any such plasticity is a result of yielding of beams and/or columns. Thus it is their opinion that strength decay should begin immediately following the development of peak joint strength, particularly if the joint is not strong enough to sustain yielding of the framing members. Compusoft Engineering Limited does not believe that this view is correct. Figure C.5 shows experimental behaviour of specimen PEER-4150 (Alire 2002; D. E. Lehman et al. 2004) with the proposed backbone curve overlaid. This joint was designed so that the joint shear strength should be exceeded prior to significant yielding of either beams or columns, with this being found to be the case during testing. Despite this it is evident that the stress resisted by the joint core remained essentially constant until quite large deformations were reached. In comparison, the proposed backbone curve appears to underestimate the ability of the joint core to resist stresses at large deformations.



## Figure C.5: Comparison of PEER-4150 (Alire 2002; D. E. Lehman et al. 2004) against proposed backbone curve

#### C.4 <u>Definition of maximum joint shear strength</u>

Two proposals for joint shear strength have been considered. These correspond broadly to the methods used in New Zealand and the U.S.A. for determination of deficient joint core strength.

The New Zealand method for determining joint core strength is based on checking that limiting values of joint principal tension and compression stresses are not exceeded (Hakuto et al. 2000; NZSEE 2006; Priestley 1997; Weng Yuen 2010). The limits on the principal stresses are dependent on joint detailing, and whether the joint is of the interior or exterior kind. The method inherently leads to joint shear strength being dependent on column axial load.

In U.S. practice, joint shear strength is typically assumed to be independent of column axial load. The limiting joint shear stress is assumed to be proportional to the square root of concrete compressive strength. The constant relating joint shear strength and square root compressive strength is typically referred to as " $\gamma$ ", and its value is dependent on the type of joint (interior/exterior) and the presence of members framing into the joint on the orthogonal axes. Refinements of this method have recently been proposed by Park (2010), who suggested that joint aspect ratio affected shear strength.

Figure C.6 shows a comparison of the joint shear strength coefficient for interior joints according to U.S. practice, New Zealand practice, and with modification to U.S. practice based on the work of Park (2010). Figure C.7 shows similar data for exterior joints. It is clear that there is a marked difference between these strengths for interior joints. It is notable that Lehman et al. (2004) and Moehle (2006) have noted that the strengths given by ASCE 41 can be conservative by a factor of two, with coefficients as high as 25 being observed for interior joints. These observations support the method used in NZ practice as being more realistic, and for this reason this approach has been adopted for the analyses discussed in the body of the report. The approach taken has been based on determining appropriate limits for joint core principal tension and principal compression stresses. The limit value for the principal tension stress was calculated as  $f_{tp,max} = k \sqrt{f'_c}$  (NZSEE 2006), with the value of k dependent on whether the joint was an interior or exterior joint and with the curvature ductility of the adjacent member being taken as zero (see Figure C.8). The limiting value for the principal compression stress in the joint core was taken as  $f_{cp,max} = 0.5 f'_c$  based on a recommendation made by Priestley (1997).

The principal tension and compression stresses existing in the joint core were calculated as  $0.5f_a \pm \sqrt{(0.5f_a)^2 + (v_{jh})^2}$ , where  $f_a$  is the column axial stress and  $v_{jh}$  is the horizontal joint shear stress. Consideration of the principal stresses shows that the joint shear stress required to cause tensile failure increases as the column axial compressive stress increases, while the

July 2012

joint shear stress required to cause compression failure in the joint decreases as the column axial compressive stress increases.





Figure C.6: Column axial load ratio against joint shear strength coefficient for interior joints



## Figure C.7: Column axial load ratio against joint shear strength coefficient for exterior joints




Figure C.8: Relationship of factor K to curvature ductility for different joint types (after NZSEE 2006)

A suggestion was made by members of the Royal Commission Expert Panel that a formulation for joint shear strength based on the Modified Compression Field Theory ("MCFT", Vecchio and Collins 1986) or related approaches could be appropriate. Such an approach was not pursued due to the wide range of such formulations available, and the observation that MCFT models typically underestimate the strength of deficient beam-column joints (LaFave and Shin 2005; Mitra and Lowes 2007).

#### C.5 Issues and limitations of the adopted joint degradation implementation

Aside from the issues related to uncertainty of the actual behaviour of joints evident from the scatter of data in the literature, there are a number of limitations to the joint degradation behaviour implemented in the CTV Building finite element model. It is important that these limitations be considered when the output of the finite element model is being used to assess the probable behaviour of the structure.

#### C.5.1 Limitations of the method used to implement the joint shear spring

As stated in section C.2, the non-linear behaviour of beam-column joints has been implemented in the CTV Building analysis model through use of a moment-rotation spring, with behaviour determined by the sum of moments occurring at the node representing the beam-column joint. In reality, the stress generated in a beam-column joint is not a function of the moment at the joint centroid; rather the stress that develops is determined from the beam

and column internal flexural forces and shears. Accurate representation of this behaviour in a finite element model is challenging to achieve, as it would require implementation of an element with behaviour influenced by multiple spatially separated nodes (for example see Figure C.9).




Figure C.9: Example of beam-column joint finite element model relying on inputs from multiple nodes (from Mitra and Lowes 2007)

Consideration was given to implementing a model of the type shown in Figure C.9, but the concept was ultimately not pursued for three reasons:

- 2. While implementation was considered possible, it was not felt that reliable calibration of the model could be achieved in the time available.
- 3. The addition of the required number of (non-linear) springs to the model would have prevented completion of the required analyses in the available timeframe.
- 4. Extension of the model shown to accommodate three-dimensional joints was not reported in literature reviewed by Compusoft Engineering Limited.

The implemented model avoids the difficulties outlined above by calibrating the momentrotation spring to represent the shear stress-deformation response using calculations outlined in Appendix C.6. However, this process introduces other limitations due to the number of assumptions inherent in the outlined calculations. Principle amongst these is the assumption of equal beam and column moments and shears on opposite sides of the joints (see Figure C.10). While appropriate for typical laboratory test specimens, this assumption are clearly not usually correct in a complete structure. The effect of the assumption made will generally be to overestimate the demands placed on the beam-column joint. The calculations shown in Appendix C.6 are also based on an assumption of equal member spans above and below and to either side of the joint; this limitation has been mitigated for the implementation used in the final analysis model by conducting the calibration of the spring using more complex calculations accounting for different member lengths at each side of the joint core.




Figure C.10: Moment diagram assumed for development of joint spring

#### C.5.2 Geometry of the exterior beam-column joints

The consequences of shear failure are generally considered to be more serious for exterior joints than for interior joints, and the strength of exterior joints is generally lower than the strength of interior joints. Both of these points are largely due to the propensity for a wedge of concrete to dislodge from the rear side of the joint after cracking of the joint has occurred and as shown in Figure C.11. The dislodgement of this wedge is liable to result in loss of column axial load capacity.

The strengths of the exterior joints of the CTV Building have been calculated on the basis that their geometry is superficially similar to that shown in Figure C.11, with an inherent assumption that the rear face of the joint (opposite the beam) is relatively poorly confined and prone to dislodgement. However, for many of the joints this assumption is not accurate. As shown in Figure C.12 many of the exterior joints of the CTV Building in fact have a significant volume of concrete located at the rear face of the joint core, with this concrete extending a significant distance beyond the column cross section. This concrete could be expected to provide additional confinement to the rear side of the joint core, and would hence

be likely to enhance the strength of the joint core. This effect has not been accounted for in the analyses undertaken.




Figure C.11: Damage of exterior joint (left) observed during testing and (right) illustrated schematically (from Pampanin et al. 2002)




Figure C.12: Plan views of CTV Building exterior joints (Design Engineer 1986)

C.5.3 Relationship of joint strength and deformation characteristics to deformation imposed on adjacent members

A further complexity is added to definition of the strength of deficient beam-column joints because it is acknowledged in the literature that the strength is not in fact a unique value dependent only on joint core properties (dimensions, concrete strength etc.). Rather, the strength is also dependent on the plastic deformation of the members framing into the beam-column joint (Hakuto et al. 2000; D. E. Lehman et al. 2004; Priestley 1997). The significance of this relationship can be seen in Figure C.13, which indicates that the joint shear capacity of

interior joints drops by 60% as the curvature ductility imposed on the adjacent members is increased from two or less to nine.





Figure C.13: Relationship between joint shear capacity and framing member curvature ductility (from NZSEE 2006)

The joint model implemented in the CTV Building model does not implement this relationship between member curvature and joint capacity. While technically achievable, the behaviour was not included based on concerns similar to those listed in section C.5.1 that guided the decision not to use a multi-node joint model.

## C.6 <u>Calculations showing basis for relating joint moment to shear stress for modelling purposes</u>



COMPUSOFT ENGINEERING	Project: CTV Joints	Date: 19/06 Page: 7
CALCULATIONS	Section:	By: NJB Checked:
Now,	2M = Vool Hs	
substituting	$V_{col} = \frac{2M}{H_s}$	
Vih	$= \frac{2M}{H_{s}} \left( \frac{H_{s}}{L_{B}} \right)^{(L_{B}-1)}$	$\frac{b_c}{c}$ -1)
2M	$= \frac{V_{jh}}{\frac{L_B - h_c}{L_B  jd}} - \frac{1}{H_S}$	
For CEL exam	ple plots, dimensions	taken were:
	s = 7000  mm	
	= 400  MM 2M = 0.553	

July 2012

## Appendix D Foundation Modelling Properties

Figure D.1 below shows the foundation stiffness information used as the basis of the CTV analysis model representation of the foundations.

	UNDATIONS	SPRING ST	TIFFNESS						
1/05/2011 16:02									
Nost likely values									
hear wave velocity:									
tiff area	300	m/s							
oft area	200	m/s							
hear modulus:									
tiff area	162.00	MPa							
oft area	70.00	MPa							
Density:									
itiff area	1900	) kg/m <sup>3</sup>							
		-							
oft area	1750	) kg/m <sup>4</sup>							
Detter									
oissons Ratio:									
oissons Ratio: Stiff area	0.3								
	0.3 0.4								
Stiff area			D (m)	L/B	D/B	Depth factor	Barcan: β <sub>z</sub>	Spring (MN/m <sup>3</sup> )	Comment
stiff area Soft area	0.4	Ļ	D (m)	L/B 1.00	<b>D/В</b> 0.25	Depth factor	Barcan: β <sub>z</sub> 2.12	122.71	Comment
tiff area Soft area Footing type	0.4 <b>B (m)</b>	L (m)		-		-			
itiff area ioft area Footing type 1	0.4 <b>B (m)</b> 4	L (m)	1	1.00	0.25	1	2.12	122.71	Comment Soft area
Stiff area Soft area Footing type 1 1a	0.4 <b>B (m)</b> 4 4.5	L (m) 4 4.5	1 1	1.00 1.00	0.25	1 1.2	2.12 2.12	122.71 130.89	Soft area
stiff area soft area Footing type 1 1a 1b	0.4 B (m) 4 4.5 4.5	L (m) 4 4.5 4.5	1 1 1	1.00 1.00 1.00	0.25 0.22 0.22	1 1.2 1.2	2.12 2.12 2.12 2.13 2.18	122.71 130.89 65.98 85.40 53.14	
Stiff area Soft area <b>Footing type</b> 1 1a 1b 2	0.4 <b>B (m)</b> 4 4.5 4.5 7.3	L (m) 4 4.5 4.5 7.7	1 1 1 1.8	1.00 1.00 1.00 1.05	0.25 0.22 0.22 0.25	1 1.2 1.2 1.3	2.12 2.12 2.12 2.12 2.13	122.71 130.89 65.98 85.40 53.14 117.22	Soft area Soft area
stiff area soft area <b>Footing type</b> 1 1a 1b 2 2 2a	0.4 B (m) 4 4.5 4.5 7.3 5.4	L (m) 4 4.5 4.5 7.7 7.7	1 1 1.8 1.8	1.00 1.00 1.00 1.05 1.43	0.25 0.22 0.22 0.25 0.33	1 1.2 1.2 1.3 1.35	2.12 2.12 2.12 2.13 2.18 2.22 2.22	122.71 130.89 65.98 85.40 53.14 117.22 78.59	Soft area
stiff area soft area 1 1a 1b 2 2 2a 3	0.4 <b>B (m)</b> 4 4.5 4.5 7.3 5.4 3.3	L (m) 4 4.5 4.5 7.7 7.7 5.8	1 1 1.8 1.8 1	1.00 1.00 1.00 1.05 1.43 1.76	0.25 0.22 0.22 0.25 0.33 0.30	1 1.2 1.2 1.3 1.35 1.33	2.12 2.12 2.13 2.18 2.22 2.22 2.22 2.44	122.71 130.89 65.98 85.40 53.14 117.22 78.59 159.69	Soft area Soft area Soft area
stiff area soft area 1 1a 1b 2 2a 3 3a	0.4 <b>B (m)</b> 4 4.5 7.3 5.4 3.3 3.3	L (m) 4 4.5 4.5 7.7 7.7 5.8 5.8	1 1 1.8 1.8 1 1	1.00 1.00 1.00 1.05 1.43 1.76 1.76	0.25 0.22 0.22 0.25 0.33 0.30 0.30	1 1.2 1.2 1.3 1.35 1.33 1.33	2.12 2.12 2.12 2.13 2.18 2.22 2.22	122.71 130.89 65.98 85.40 53.14 117.22 78.59 159.69 73.94	Soft area Soft area
stiff area soft area 1 1a 1b 2 2a 3 3 3a 4	0.4 <b>B (m)</b> 4 4.5 7.3 5.4 3.3 3.3 3.3 2.5	L (m) 4 4.5 4.5 7.7 7.7 5.8 5.8 9.8	1 1 1.8 1.8 1 1 1 1	1.00 1.00 1.00 1.05 1.43 1.76 1.76 3.92	0.25 0.22 0.22 0.25 0.33 0.30 0.30 0.30 0.40	1 1.2 1.3 1.35 1.33 1.33 1.4	2.12 2.12 2.13 2.18 2.22 2.22 2.22 2.44	122.71 130.89 65.98 85.40 53.14 117.22 78.59 159.69	Soft area Soft area Soft area

#### Figure D.1: Expected Soil Stiffness (Sinclair 2011)

### Appendix E <u>Acceleration Time History Records.</u>

#### E.1 Darfield CBGS

Christchurch Botanical Gardens (CBGS) time history records (Geonet 2010b) used to determine the structural response for the Darfield event are presented in Figure E.1 below.




Figure E.1: Darfield 20100903\_163541\_CBGS N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

#### E.2 Darfield CCCC

Christchurch Cathedral College (CCCC) time history records (Geonet 2010b) used to determine the structural response for the Darfield event are presented in Figure E.1 below.




Figure E.2: Darfield 20100903\_163541\_CCCC N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

## E.3 <u>Lyttelton CBGS</u>

Christchurch Botanical Gardens (CBGS) time history records (Geonet 2011b) used to determine the structural response for the Lyttelton aftershock are presented in Figure E.3 below.

July 2012




Figure E.3: Lyttelton 20110221\_235142\_CBGS N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

#### E.4 Lyttelton CCCC

Christchurch Cathedral College (CCCC) time history records (Geonet 2011b) used to determine the structural response for the Lyttelton aftershock are presented in Figure E.4 below.

#### Report on Additional Non-Linear Seismic Analyses

July 2012




Figure E.4: Lyttelton 20110221\_235142\_CCCC N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

#### E.5 <u>Lyttelton CHHC</u>

Christchurch Hospital (CHHC) time history records (Geonet 2011b) used to determine the structural response for the Lyttelton aftershock are presented in Figure E.5 below.

#### Report on Additional Non-Linear Seismic Analyses

July 2012




Figure E.5: Lyttelton 20110221\_235142\_CHHC N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

#### E.6 <u>Lyttelton REHS</u>

Resthaven (REHS) time history records (Geonet 2011b) used to determine the structural response for the Lyttelton aftershock are presented in Figure E.5 below.

July 2012

#### Report on Additional Non-Linear Seismic Analyses





Figure E.6: Lyttelton 20110221\_235142\_REHS N00E (top), N90E (middle), and Vertical (bottom) acceleration time history record plots

#### Appendix F Analysis Results - Darfield Event: CBGS Record


The following details the structural actions reported by the analysis as a function of time, for the Darfield event using the acceleration time history recorded at the CBGS station using all components of the record.

#### F.1 <u>Building Displacements and Drifts.</u>

Building Level 6 displacements are presented in Figure F.1 and Figure F.2 below for the Southeast and Northwest corners of the building respectively.







-0.1

-0.2

As can be seen in Figure F.1and Figure F.2 the predominant building displacements are in the north/south direction. No drags bars are predicted to fail under the CBGS demands (assuming an upper bound drag bar capacity). Table F.1 presents the sequence of failure of the north core wall ties throughout the record.

Level	Wall D Failure (sec)	Wall D/E Failure (sec)
6	No disconnection	No disconnection
5	No disconnection	No disconnection
4	No disconnection	No disconnection

Table F.1: Wall D and D/E diaphragm disconnection times

Inter-storey displacements for the perimeter frame lines A and F in the north/south direction are presented in Figure F.3, and Figure F.4 below.




Figure F.3: Frame A north/south inter-storey displacements








Figure F.4: Frame F north/south inter-storey displacements

Inter-storey displacements for the perimeter frame lines 1 and 4 in the east/west direction are presented in Figure F.5, and Figure F.6 below.






Figure F.5: Frame 1 east/west inter-storey displacements

#### BUI.MAD249.0535.146

#### Report on Additional Non-Linear Seismic Analyses





## F.2 Diaphragm Connection Forces

Diaphragm connection forces are presented in Figure F.7 to Figure F.18 below. Note that moments are reported about the geometric centroid of the element being considered.





Figure F.7: North core total diaphragm north/south actions






Figure F.8: North core total diaphragm east/west actions





Figure F.9: North core total diaphragm in-plane moments








Figure F.10: North core Wall C diaphragm north/south actions




Figure F.11: North core Wall C/D diaphragm north/south actions




Figure F.12: North core Wall D diaphragm north/south actions





Figure F.13: North core Wall D/E diaphragm north/south actions



July 2012




Figure F.14: North core Slab 4/C to C/D diaphragm north/south actions




Figure F.15: North core Slab 4/C to C/D diaphragm east/west actions

## Report on Additional Non-Linear Seismic Analyses




Figure F.16: North core Slab 4/C to C/D diaphragm in-plane moments




Figure F.17: North core Wall 5 diaphragm east/west






Figure F.18: South wall diaphragm east/west actions

## F.3 Column Hinge Actions

Figure F.19 to Figure F.23 present a selection of column hinge rotations, elongations, and concrete strains for a selected number of critical columns. Strains reported are the maximum that occur at the extreme concrete fibre. Plots are presented for individual columns and are orientated so that the top row of plots relate to the level 5 hinges with each row below corresponding to the hinges in the column below i.e. from the top level to the bottom level. Results presented are for the worst case hinge at each floor level, with hinge rotation and elongation shown in the left hand plot and hinge concrete strain shown in the right hand plot.




Figure F.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure F.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure F.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure F.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure F.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield

# Appendix G Analysis Results - Darfield Event: CCCC Record

The following details the structural actions reported by the analysis as a function of time, for the Darfield event using the acceleration time history recorded at the CCCC station using all components of the record.

## G.1 <u>Building Displacements and Drifts.</u>

Building Level 6 displacements are presented in Figure G.1 and Figure G.2 below for the Southeast and Northwest corners of the building respectively.




Figure G.1: Level 6 Southeast corner displacements, Darfield

July 2012




Figure G.2: Level 6 Northwest corner displacements, Darfield

As can be seen in Figure G.1 and Figure G.2 above a significant increase in the northward building displacement is observed in the northwest corner of the building between 14 and 20 seconds of the record. The peak displacement corresponds to a clockwise rotation in conjunction with a net northward building translation. Table G.1 presents the sequence of failure of the north core wall ties throughout the record.

Table G.1: Wall D and D/E diaphragm disconnection times

Level	Wall D Failure (sec)	Wall D/E Failure (sec)
6	No	No
	disconnection	disconnection
5	No	No
	disconnection	disconnection
4	14.44	14.40

Inter-storey displacements for the perimeter frame lines A and F in the north/south direction are presented in Figure G.3 and Figure G.4 below.

## Report on Additional Non-Linear Seismic Analyses







Figure G.3: Frame A north/south inter-storey displacements, Darfield






Inter-storey displacements for the perimeter frame lines 1 and 4 in the east/west direction are presented in Figure G.5, and Figure G.6 below.


#### Compusoft Engineering Limited



Report on Additional Non-Linear Seismic Analyses







## G.2 <u>Diaphragm Connection Forces</u>

Diaphragm connection forces are presented in Figure G.7 to Figure G.18 below. Note that moments are reported about the geometric centroid of the element being considered.




Figure G.7: North core total diaphragm north/south actions





Figure G.8: North core total diaphragm east/west actions






Figure G.9: North core total diaphragm in-plane moments




Figure G.10: North core Wall C diaphragm north/south actions




Figure G.11: North core Wall C/D diaphragm north/south actions




Figure G.12: North core Wall D diaphragm north/south actions




Figure G.13: North core Wall D/E diaphragm north/south actions




Figure G.14: North core Slab 4/C to C/D diaphragm north/south actions

## Report on Additional Non-Linear Seismic Analyses




Figure G.15: North core Slab 4/C to C/D diaphragm east/west actions




Figure G.16: North core Slab 4/C to C/D diaphragm in-plane moments







Figure G.17: North core Wall 5 diaphragm east/west actions





## G.3 <u>Column Hinge Actions</u>

Figure G.19 to Figure G.23 present a selection of column hinge rotations, elongations, and concrete strains for a selected number of critical columns. Strains reported are the maximum that occur at the extreme concrete fibre. Plots are presented for individual columns and are

orientated so that the top row of plots relate to the level 5 hinges with each row below corresponding to the hinges in the column below i.e. from the top level to the bottom level. Results presented are for the worst case hinge at each floor level, with hinge rotation and elongation shown in the left hand plot and hinge concrete strain shown in the right hand plot.

Compusoft Engineering Limited




Figure G.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure G.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure G.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure G.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Darfield




Figure G.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Darfield

# Appendix H Analysis Results - Lyttelton Aftershock: CBGS record

The following details the structural actions reported by the analysis as a function of time, for the Lyttelton aftershock using the acceleration time history recorded at the CBGS station using all components of the record. Results presented in this section include those assuming that the CTV Building was undamaged (denoted *'undamaged'*), and those for the analyses following on from the damaged building state at the end of the Darfield event (denoted *'damaged'*).

## H.1 <u>Building Displacements and Drifts.</u>

Building Level 6 displacements are presented in Figure H.1 to Figure H.4 below for the southeast and northwest corners of the building respectively.




Figure H.1: Level 6 Southeast corner displacements, Undamaged




Figure H.2: Level 6 Southeast corner displacements, Damaged




Figure H.3: Level 6 Northwest corner displacements, Undamaged






Figure H.4: Level 6 Northwest corner displacements, Damaged

As can be seen in Figure H.3 and Figure H.4 above a significant increase in the northward building displacement is observed in the northwest corner of the building approximately 6.5 seconds into the of the record. This occurs after the tension ties capacities on levels 4 to 6 of the core are exceeded allowing increased building rotation clockwise from west to north. The peak displacement corresponds to a clockwise rotation in conjunction with a net northward building translation. Table H.1 presents the sequence of failure of the north core wall ties throughout the record.

	Level	Undamaged		Damaged	
		Wall D Failure (sec)	Wall D/E Failure (sec)	Wall D Failure (sec)	Wall D/E Failure (sec)
	6	4.06	4.00	4.06	4.00
	5	4.04	4.00	4.04	4.00
Ī	4	4.02	3.98	4.02	3.98

Table H.1: Wall D and D/E diaphragm disconnection times.

It can be seen from Table H.1 that the damaged state from the end of the Darfield CBGS record has no impact on the performance of the diaphragm ties.

Inter-storey displacements for the perimeter frame lines A and F in the north/south direction are presented in Figure H.3 to Figure H.8 below. North core tie tensile failure is identified on the plots for reference.

#### Report on Additional Non-Linear Seismic Analyses




Figure H.5: Frame A north/south inter-storey displacements, Undamaged





Figure H.6: Frame A north/south inter-storey displacements, Damaged







Figure H.7: Frame F north/south inter-storey displacements, Undamaged





Inter-storey displacements for the perimeter frame lines 1 and 4 in the East/West direction are presented in Figure H.9, to Figure H.12 below.

#### Report on Additional Non-Linear Seismic Analyses




Figure H.9: Frame 1 east/west inter-storey displacements, Undamaged




Figure H.10: Frame 1 east/west inter-storey displacements, Damaged







Figure H.11: Frame 4 east/west inter-storey displacements, Undamaged





## H.2 Diaphragm Connection Forces

Diaphragm connection forces are presented in Figure H.13 to Figure H.24 below. Note that moments are reported about the geometric centroid of the element being considered.






Figure H.13: North core total diaphragm north/south actions




Figure H.14: North core total diaphragm east/west actions






Figure H.15: North core total diaphragm in-plane moments




Figure H.16: North core Wall C diaphragm north/south actions

July 2012




Figure H.17: North core Wall C/D diaphragm north/south actions




Figure H.18: North core Wall D diaphragm north/south actions






Figure H.19: North core Wall D/E diaphragm north/south actions




Figure H.20: North core Slab 4/C to C/D diaphragm north/south actions




Figure H.21: North core Slab 4/C to C/D diaphragm east/west actions




Figure H.22: North core Slab 4/C to C/D diaphragm in-plane moments








Figure H.23: North core Wall 5 diaphragm east/west actions





### H.3 <u>Column Hinge Actions</u>

Figure H.25 to Figure H.29 present a selection of column hinge rotations, elongations, and concrete strains for a selected number of critical columns. Strains reported are the maximum that occur at the extreme concrete fibre. Plots are presented for individual columns and are orientated so that the top row of plots relate to the level 5 hinges with each row below

corresponding to the hinges in the column below i.e. from the top level to the bottom level. Results presented are for the worst case hinge at each floor level, with hinge rotation and elongation shown in the left hand plot and hinge concrete strain shown in the right hand plot.




Figure H.25: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure H.26: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure H.27: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure H.28: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure H.29: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton

## Appendix I Analysis Results - Lyttelton Aftershock: CCCC record

The following details the structural actions reported by the analysis as a function of time, for the Lyttelton aftershock using the acceleration time history recorded at the CCCC station using all components of the record. Results presented in this section include those assuming that the CTV Building was undamaged (denoted *'undamaged'*), and those for the analyses following on from the damaged building state at the end of the Darfield event (denoted *'damaged'*).

## I.1 <u>Building Displacements and Drifts.</u>

Building Level 6 displacements are presented in Figure I.1 and Figure I.4 below for the southeast and northwest corners of the building for both the damaged and undamaged states.




Figure I.1: Level 6 Southeast corner displacements, Undamaged






Figure I.2: Level 6 Southeast corner displacements, Damaged




Figure I.3: Level 6 Northwest corner displacements, Undamaged






Figure I.4: Level 6 Northwest corner displacements, Damaged

As can be seen in Figure I.3 and Figure I.4 above a significant increase in the northward building displacement is observed in the northwest corner of the building approximately 5.5 seconds into the record. This occurs after the tension ties capacities on levels 4 to 6 of the core are exceeded allowing increased building rotation clockwise from west to north. The peak displacement corresponds to a clockwise rotation in conjunction with a net northward building translation. Table I.1 presents the sequence of failure of the north core wall ties throughout the record (note that time are presented relative to the start of the Lyttelton component of record).

Level	Undamaged		Damaged	
	Wall D Failure (sec)	Wall D/E Failure (sec)	Wall D Failure (sec)	Wall D/E Failure (sec)
6	1.52	1.46	3.18	1.48
5	2.58	1.46	4.18	1.50
4	1.62	1.48	disconnected	disconnected

Table I.1: Wall D and D/E diaphragm disconnection times

It can be seen from Table I.1 that the damaged state from the end of the Darfield CCCC influences the performance of the diaphragm ties on wall D, but has little influence on the wall D/E connections.

Inter-storey displacements for the perimeter frame lines A and F in the north/south direction are presented in Figure I.5 to Figure I.8 below. North core tie tensile failure is identified on the plots for reference.




Figure I.5: Frame A north/south inter-storey displacements, Undamaged




Figure I.6: Frame A north/south inter-storey displacements, Damaged








Figure I.7: Frame F north/south inter-storey displacements, Undamaged



## Figure I.8: Frame F north/south inter-storey displacements, Damaged

Inter-storey displacements for the perimeter frame lines 1 and 4 in the East/West direction are presented in Figure I.9 to Figure I.12 below.

### BUI.MAD249.0535.198








Figure I.9: Frame 1 east/west inter-storey displacements, Undamaged





Figure I.10: Frame 1 east/west inter-storey displacements, Damaged

#### BUI.MAD249.0535.199

#### 0.04 0.035 0.03 0.025 0.02 0.015 evel 6 E/W drift 0.01 Level 5 E/W drift Level 4 E/W drift 3E-17 Disblace Disbla 4 9 Level 3 E/W drift evel 2 E/W drift -0.01 First Core Connection Failure -0.015 - Last Core Connection Failure -0.02 -0.025 -0.03 -0.035 Time (s)

#### Report on Additional Non-Linear Seismic Analyses







## I.2 <u>Diaphragm Connection Forces</u>

Diaphragm connection forces are presented in Figure I.13 to Figure I.24 below. Note that moments are reported about the geometric centroid of the element being considered.




Figure I.13: North core total diaphragm north/south actions




Figure I.14: North core total diaphragm east/west actions






Figure I.15: North core total diaphragm in-plane moments




Figure I.16: North core Wall C diaphragm north/south actions






Figure I.17: North core Wall C/D diaphragm north/south actions




Figure I.18: North core Wall D diaphragm north/south actions






Figure I.19: North core Wall D/E diaphragm north/south actions




Figure I.20: North core Slab 4/C to C/D diaphragm north/south actions






Figure I.21: North core Slab 4/C to C/D diaphragm east/west actions




Figure I.22: North core Slab 4/C to C/D diaphragm in-plane moments






Figure I.23: North core Wall 5 diaphragm east/west actions




Figure I.24: South wall diaphragm east/west actions

## I.3 <u>Column Hinge Actions</u>

Figure I.25 to Figure I.29 present a selection of column hinge rotations, elongations, and concrete strains for a selected number of critical columns. Strains reported are the maximum that occur at the extreme concrete fibre. Plots are presented for individual columns and are orientated so that the top row of plots relate to the level 5 hinges with each row below corresponding to the hinges in the column below i.e. from the top level to the bottom level.

Results presented are for the worst case hinge at each floor level, with hinge rotation and elongation shown in the left hand plot and hinge concrete strain shown in the right hand plot.

Compusoft Engineering Limited




Figure I.25: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure I.26: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure I.27: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure I.28: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton





Figure I.29: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton


# Appendix J Analysis Results - Lyttelton Aftershock: CHHC record

The following details the structural actions reported by the analysis as a function of time, for the Lyttelton aftershock using the acceleration time history recorded at the CHHC station using all components of the record.

## J.1 <u>Building Displacements and Drifts.</u>

Building Level 6 displacements are presented in Figure J.1 and Figure J.2 below for the southeast and northwest corners of the building respectively.





As can be seen in Figure J.2 above a significant increase in the northward building displacement is observed in the northwest corner of the building between 6.2 and 7.2 seconds of the record. This occurs after the tension ties capacities on levels 4 to 6 of the core are exceeded allowing increased building rotation clockwise from west to north. The peak displacement corresponds to a clockwise rotation in conjunction with a net northward building translation Table J.1 presents the sequence of failure of the north core wall ties throughout the record.

Level	Wall D Failure (sec)	Wall D/E Failure (sec)
6	2.96	2.50
5	3.90	2.50
4	3.86	2.50

Table J.1: Wall D and D/E diaphragm disconnection times.

Inter-storey displacements for the perimeter frame lines A and F in the north/south direction are presented in Figure J.3 and Figure J.4 below. North core tie tensile failure is identified on the plots for reference.





Figure J.3: Frame A north/south inter-storey displacements

#### BUI.MAD249.0535.214


#### Report on Additional Non-Linear Seismic Analyses





## Figure J.4: Frame F north/south inter-storey displacements

Inter-storey displacements for the perimeter frame lines 1 and 4 in the East/West direction are presented in Figure J.5 and Figure J.6 below.




**Figure J.5: Frame 1 east/west inter-storey displacements** 

#### BUI.MAD249.0535.215

#### Report on Additional Non-Linear Seismic Analyses





## Figure J.6: Frame 4 east/west inter-storey displacements

## J.2 <u>Diaphragm Connection Forces</u>

Diaphragm connection forces are presented in Figure J.7 to Figure J.18 below. Note that moments are reported about the geometric centroid of the element being considered.





Figure J.7: North core total diaphragm north/south actions



July 2012




Figure J.8: North core total diaphragm east/west actions





Figure J.9: North core total diaphragm in-plane moments








Figure J.10: North core Wall C diaphragm north/south actions




Figure J.11: North core Wall C/D diaphragm north/south actions

July 2012




Figure J.12: North core Wall D diaphragm north/south actions




Figure J.13: North core Wall D/E diaphragm north/south actions




Figure J.14: North core Slab 4/C to C/D diaphragm north/south actions




Figure J.15: North core Slab 4/C to C/D diaphragm east/west actions

July 2012




Figure J.16: North core Slab 4/C to C/D diaphragm in-plane moments




Figure J.17: North core Wall 5 diaphragm east/west actions






Figure J.18: South wall diaphragm east/west actions

# J.3 <u>Column Hinge Actions</u>

Figure J.19 to Figure J.23 present a selection of column hinge rotations, elongations, and concrete strains for a selected number of critical columns. Strains reported are the maximum that occur at the extreme concrete fibre. Plots are presented for individual columns and are orientated so that the top row of plots relate to the level 5 hinges with each row below corresponding to the hinges in the column below i.e. from the top level to the bottom level. Results presented are for the worst case hinge at each floor level, with hinge rotation and elongation shown in the left hand plot and hinge concrete strain shown in the right hand plot.




Figure J.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure J.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure J.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure J.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure J.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton

# Appendix K Analysis Results - Lyttelton Aftershock: REHS record

The following details the structural actions reported by the analysis as a function of time, for the Lyttelton aftershock using the acceleration time history recorded at the REHS station using all components of the record.

# K.1 <u>Building Displacements and Drifts.</u>

Building Level 6 displacements are presented in Figure K.1 and Figure K.2 below for the southeast and northwest corners of the building respectively.




Figure K.1: Level 6 Southeast corner displacements




Figure K.2: Level 6 Northwest corner displacements

As can be seen in Figure K.2 above a significant increase in the northward building displacement is observed in the northwest corner of the building between 6.5 and 7.5 seconds of the record. Similarly, a significant increase in the westward building displacement is observed in the southeast corner of the building over the same time period. This occurs after the tension ties capacities on levels 4 to 6 of the core are exceeded allowing increased building rotation clockwise from west to north. The peak displacement corresponds to a clockwise rotation in conjunction with a net northward building translation Table K.1 presents the sequence of failure of the north core wall ties throughout the record.

Table K.1: Wall D and	d D/E diaphra	gm disconnection	times
-----------------------	---------------	------------------	-------

Level	Wall D Failure (sec)	Wall D/E Failure (sec)
6	5.18	4.68
5	5.20	3.80
4	3.76	3.70

Inter-storey displacements for the perimeter frame lines A and F in the north/south direction are presented in Figure K.3 and Figure K.4 below. North core tie tensile failure is identified on the plots for reference.





Figure K.3: Frame A north/south inter-storey displacements

July 2012



# **Figure K.4: Frame F north/south inter-storey displacements**

Inter-storey displacements for the perimeter frame lines 1 and 4 in the East/West direction are presented in Figure K.5 and Figure K.6 below.




Figure K.5: Frame 1 east/west inter-storey displacements

July 2012

# Report on Additional Non-Linear Seismic Analyses




Figure K.6: Frame 4 east/west inter-storey displacements

# K.2 Diaphragm Connection Forces

Diaphragm connection forces are presented in Figure K.7 to Figure K.18 below. Note that moments are reported about the geometric centroid of the element being considered.




Figure K.7: North core total diaphragm north/south actions






Figure K.8: North core total diaphragm east/west actions




Figure K.9: North core total diaphragm in-plane moments






Figure K.10: North core Wall C diaphragm north/south actions





Figure K.11: North core Wall C/D diaphragm north/south actions






Figure K.12: North core Wall D diaphragm north/south actions




Figure K.13: North core Wall D/E diaphragm north/south actions

July 2012




Figure K.14: North core Slab 4/C to C/D diaphragm north/south actions




Figure K.15: North core Slab 4/C to C/D diaphragm east/west actions






Figure K.16: North core Slab 4/C to C/D diaphragm in-plane moments




Figure K.17: North core Wall 5 diaphragm east/west actions






Figure K.18: South wall diaphragm east/west actions

# K.3 Column Hinge Actions

Figure K.19 to Figure K.23 present a selection of column hinge rotations, elongations, and concrete strains for a selected number of critical columns. Strains reported are the maximum that occur at the extreme concrete fibre. Plots are presented for individual columns and are orientated so that the top row of plots relate to the level 5 hinges with each row below corresponding to the hinges in the column below i.e. from the top level to the bottom level. Results presented are for the worst case hinge at each floor level, with hinge rotation and elongation shown in the left hand plot and hinge concrete strain shown in the right hand plot.




Figure K.19: Column F1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure K.20: Column F2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure K.21: Column F3 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure K.22: Column C1 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton




Figure K.23: Column C2 Levels 1 (bottom) to 5 (top) hinge actions, Lyttelton