









004 cnr & E Wall Nth tower



005 NE cnr spandrels



006 E Wall spandrels

007 Grd storey GIB cracking

150/B



CONTROL ROOM




**Control Room.
Please Do Not Enter!**

HTV

**NO-ONE IS TO ENTER THE
CONTROL ROOM WHEN THE**



008 Grd floor GIB cracking



009 Grd floor GIB cracking



011 Grd Fl Gib cracking



012 Grd Fl Gib cracking



013 Grd FI GIB cracking



014 Grd Fl ceiling/column crack



015 Grd Fl column





017 Grd FI block wall



018 Grd Fl E wall window seal



019 Grd Fl E wall window

