SMS Incident Report

6/08/2012 9:30:55 a.m.

_	Summary			
	CAD Number	F0914237	Status	Closed
	Station	Amberley Volunteer Fire Brig	gade	
	Incident Started	22/02/2011 3:30:05 p.m.	Incident Ended	22/02/2011 8:46:21 p.m.
	Incident Type	8101: Earthquake		
	Common Name	CTV		
	Address	249 MADRAS STREET CHRISTCHURCH CENTRAL		
	Alarm Method	111 Telephone	Alarm Level	1
	PFA Number			
	Zone	342101	Risk Classification	Ν
	Map Grid E	1571112	Map Grid N	5179963
	First Caller	KOMOTO/KIYU	First Caller Contact	10274017000
	Incident Closed	22/02/2011 8:46:21 p.m.		
	Report Completed	19:52, Mon 04 Apr 2011 by	Bertha Dodds	

Responses

Callsign	Туре	Station Alert	Enroute Time	Arrival Time	Departed
AMBE48/ PR		15:49:03 22 Feb 2011	15:50:00 22 Feb 2011	15:51:00 22 Feb 2011	16:21:46 22 Feb 2011
Start->Alert 7 min 10 m		nin 10 min			
			T.		
0 min Alert->1st Arrival			15 min		30 ו

Elapsed Times

Callsign	Start To Alert	Alert To Arrival	Start To Arrival	Start To Depart
AMBE487	00:18:58	00:01:57	00:20:55	00:51:41

Notifications

Date	Time	Party Notified
22 Feb 2011	15:55:23	TOO MUCH LEFT ON BATTERY

The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.

Some message timestamps may differ to actual times in multi-agency incidents. Communication centres can supply correct times if essential.

75.2

6/08/2012 9:30:55 a.m.

BUI.MAD249.057

SMS Incident Report F	0914237
-----------------------	---------

l n	010	lent
	1.10	еп
	0.0	

CAD Number	F0914237
Incident Reporter	Bertha Dodds
Incident Controller	D.C.F.O. Parish.
Distance Travelled (km)	5
Delay In Receiving Call	5

Property Details

Occupant	
Building Owner	
General Property Use	Office, Bank, Embassy, Fire/Ambulance/Police station
Special Property Use	Office: General business
Purpose Group	

Actions

Persons Reported Trapped	Yes
Evacuation Status	
Action Prior 1	
Action Prior 2	
Action Taken	Extinguishment only: Includes isolating fuel/power supply

Civilians

Civilians Rescued	0
Civilians Extricated	0
Civilians Assisted	0
Civilians Evacuated	

Origin

Location	
Level	

Equipment Used

Quantity	Equipment
1	Low pressure delivery

Equipment Involved

Equipment Involved
Year
Make
Model

The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.

The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.

SMS Incident Report F0914237

7/8

6/08/2012 9:30:55 a.m.

BUI.MAD249.0575.4

Reporter Comments

Comments

Earthquake. Assisted Woolston Appliance, feeder for fire. on scene for approximately 30 mins.

Bertha Dodds

The information contained in this report is subject to the provisions of the Official Information Act 1982 and the Privacy Act 1993. Neither the information nor the report should be released to any person outside the NZ Fire Service or the National Rural Fire Authority without prior approval.