


Christchurch CBD Damaged Buildings 31 March 2011


● I - Demolished ● I - Severe Damage ● I - Moderate Damage ● I - Minor Damage
 ▲ II - Demolished ▲ II - Severe Damage ▲ II - Moderate Damage ▲ II - Minor Damage

Index Map




Christchurch CBD Damaged Buildings 31 March 2011 - Category I & II

● I - Demolished ● I - Severe Damage ● I - Moderate Damage ● I - Minor Damage
 ▲ II - Demolished ▲ II - Severe Damage ▲ II - Moderate Damage ▲ II - Minor Damage




Christchurch CBD Damaged Buildings 31 March 2011 - Category I & II

- I - Demolished
- I - Severe Damage
- I - Moderate Damage
- I - Minor Damage
- ▲ II - Demolished
- ▲ II - Severe Damage
- ▲ II - Moderate Damage
- ▲ II - Minor Damage



Christchurch CBD Damaged Buildings 31 March 2011 - Category I & II

● I - Demolished ● I - Severe Damage ● I - Moderate Damage ● I - Minor Damage
▲ II - Demolished ▲ II - Severe Damage ▲ II - Moderate Damage ▲ II - Minor Damage



Christchurch CBD Damaged Buildings 31 March 2011 - Category I & II

- I - Demolished
- ▲ II - Demolished
- I - Severe Damage
- ▲ II - Severe Damage
- I - Moderate Damage
- ▲ II - Moderate Damage
- I - Minor Damage
- ▲ II - Minor Damage