



081 W wall 4th Fl?



082 Conc column 4th Fl?



083 5th Fl Stair well crack







086 5th Fl Stair well crack



087 5th Fl lift lobby column



088 5th Fl lift lobby column cracking





089 Top FI NE corner column



090 top FI Nth wall spandrel



091 5th Fl Sth column cracks



092 5th Sth column cracks



093 Plant Rm walls



094 Plant Rm wall crack



095 Plan Rm water leaks



096 Plan Rm wall crack





097 E wall Nth shear tower



098 E wall Nth sgear tower



099 W wall Nth shear tower



100 W wall Nth shear tower